

Route	Local Name	BMP	EMP	Length	Activity
CO1	Old Scherr Rd	0.00	4.52	4.52	Ditching
CO1	Old Greenland Rd	0.00	4.52	4.52	Mowing
CO1	Old Greenland Rd	0.00	4.52	4.52	Patching
CO2	Belle Babb	0.00	3.63	3.63	Mowing
CO2	Belle Babb Lane	0.00	3.63	3.63	Patching
CO2	Belle Babb	0.00	3.63	3.63	Ditching
CO220/1	Welton Orchard Rd	0.00	3.13	3.13	Ditching
CO220/1	Welton Orchard Rd	0.00	3.13	3.13	Mowing
CO220/1	Welton Orchard	0.00	3.13	3.13	Patching
CO220/10	Middle Mt.	0.00	0.80	0.80	Ditching
CO220/10	Middle Mt. Rd	0.00	0.80	0.80	Stabilization
CO220/11	Dolan Lane	0.00	0.27	0.27	Ditching
CO220/11	Dolan Lane (Allied Egr)	0.00	0.27	0.27	Mowing
CO220/11	Dolan Lane (Allied Egr)	0.00	0.27	0.27	Mowing
CO220/11	Access Rd to Allied Egr	0.00	0.27	0.27	Patching
CO220/12	Water St	0.00	0.13	0.13	Ditching
CO220/12	Water & Park Street	0.00	0.13	0.13	Mowing
CO220/12	Water & Park Street	0.00	0.13	0.13	Mowing
CO220/12	Water St & Park St Extension	0.00	0.13	0.13	Patching
CO220/14	Pierpoint St	0.00	0.90	0.90	Ditching
CO220/14	Pierpont Street & South Branch VoTech	0.00	0.90	0.90	Mowing
CO220/14	Pierpont Street & South Branch VoTech	0.00	0.90	0.90	Mowing
CO220/14	Pierpont St. & South Branch	0.00	0.90	0.90	Patching
CO220/18	RMX Dr	0.00	0.12	0.12	Ditching
CO220/18	RMX	0.00	0.12	0.12	Mowing
CO220/18	RMX	0.00	0.12	0.12	Mowing
CO220/19	Business Park Dr	0.00	0.71	0.71	Ditching
CO220/19	Grant Co Industrial Park Rd	0.00	0.71	0.71	Mowing
CO220/19	Grant Co Industrial Park Rd	0.00	0.71	0.71	Mowing
CO220/19	Business Park Dr	0.00	0.71	0.71	Patching
CO220/2	Johnson Run Rd	0.00	3.67	3.67	Ditching
CO220/2	Fish Hatchery	0.00	3.67	3.67	Mowing
CO220/2	Fish Hatchery	0.00	3.67	3.67	Patching
CO220/20	Providence Lane	0.00	0.23	0.23	Ditching
CO220/20	Providence Lane	0.00	0.23	0.23	Mowing
CO220/20	Providence Lane	0.00	0.23	0.23	Mowing
CO220/20	Providence Lane	0.00	0.23	0.23	Patching
CO220/21	Technology Lane	0.00	0.29	0.29	Ditching
CO220/21	Technology Lane	0.00	0.29	0.29	Mowing
CO220/21	Technology Lane	0.00	0.29	0.29	Mowing
CO220/21	Technology Lane	0.00	0.29	0.29	Patching
CO220/3	Kellers Ridge Rd	0.00	2.33	2.33	Ditching
CO220/3	Kellers Ridge Rd	0.00	2.33	2.33	Mowing
CO220/3	Keller's Ridge	0.00	2.33	2.33	Patching
CO220/3	Kellers Ridge Rd	0.39	1.15	0.76	Stabilization
CO220/4	North Mill Creek	0.00	3.28	3.28	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO220/4	North Mill Creek Rd	0.00	3.28	3.28	Mowing
CO220/4	North Mill Creek Rd	0.00	3.28	3.28	Patching
CO220/5	Shooks Gap Rd	0.00	4.46	4.46	Ditching
CO220/5	Shooks Gap Rd	0.00	2.10	2.10	Stabilization
CO220/6	Pink Alt Rd	0.00	2.13	2.13	Ditching
CO220/6	Pink Alt Rd	0.00	2.13	2.13	Stabilization
CO220/7	Kellers Ridge Ext.	0.00	0.23	0.23	Ditching
CO220/7	Kellers Ridge Extension	0.00	0.23	0.23	Mowing
CO220/7	Keller's Ridge Extension	0.00	0.23	0.23	Patching
CO220/8	Airport Rd	0.00	0.46	0.46	Ditching
CO220/8	Airport Rd	0.00	0.46	0.46	Mowing
CO220/8	Airport Rd	0.00	0.46	0.46	Patching
CO220/9	Bob Ours Rd (911 Tower)	0.00	1.60	1.60	Ditching
CO220/9	Bob Ours Rd (911 Tower)	0.00	1.60	1.60	Mowing
CO220/9	Bob Ours (911 Tower)	0.00	1.60	1.60	Stabilization
CO28/1	River Rd	0.00	2.05	2.05	Ditching
CO28/1	River Rd	0.00	2.05	2.05	Patching
CO28/1	River Rd	0.75	2.05	1.30	Stabilization
CO28/1	River Rd	0.00	2.05	2.05	Mowing
CO28/10	Cutoff Lane (Redman)	0.00	0.32	0.32	Ditching
CO28/10	Redman Rd	0.00	0.32	0.32	Mowing
CO28/10	Redman Run	0.00	0.32	0.32	Patching
CO28/11	Smoke Hole Rd	0.00	8.07	8.07	Ditching
CO28/11	Smoke Hole Rd	0.00	8.07	8.07	Mowing
CO28/11	Smoke Hole Rd	0.00	8.07	8.07	Patching
CO28/12	Sky Valley Sub.	0.00	0.83	0.83	Ditching
CO28/12	Sky Valley	0.00	0.83	0.83	Mowing
CO28/12	Sky Valley	0.00	0.83	0.83	Mowing
CO28/12	Sky Valley Subdivision	0.00	0.83	0.83	Patching
CO28/13	Sky Valley Sub. II	0.00	0.21	0.21	Ditching
CO28/13	Sky Valley II	0.00	0.21	0.21	Mowing
CO28/13	Sky Valley II	0.00	0.21	0.21	Mowing
CO28/13	Sky Valley Subdivision II	0.00	0.21	0.21	Patching
CO28/15	Oak Cove Drive	0.00	0.55	0.55	Ditching
CO28/15	Oak Cove Drive	0.00	0.55	0.55	Mowing
CO28/15	Oak Cove Drive	0.00	0.55	0.55	Mowing
CO28/15	Oak Cove Drive	0.00	0.55	0.55	Patching
CO28/16	Cardinal Drive (Oak Cove)	0.00	0.63	0.63	Ditching
CO28/16	Cardinal Circle	0.00	0.63	0.63	Mowing
CO28/16	Cardinal Circle	0.00	0.63	0.63	Mowing
CO28/16	Cardinal Circle	0.00	0.63	0.63	Patching
CO28/17	Bob White Dr. (Oak Cove)	0.00	0.50	0.50	Ditching
CO28/17	Bob White Drive (Oak Cove)	0.00	0.50	0.50	Mowing
CO28/17	Bob White Drive (Oak Cove)	0.00	0.50	0.50	Mowing
CO28/17	Bob White Drive	0.00	0.50	0.50	Patching
CO28/18	Robin Lane (Oak Cove)	0.00	0.05	0.05	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO28/18	Robin Lane (Oak Cove)	0.00	0.05	0.05	Mowing
CO28/18	Robin Lane (Oak Cove)	0.00	0.05	0.05	Mowing
CO28/18	Robin Lane	0.00	0.06	0.06	Patching
CO28/19	Sunrise Drive	0.00	0.80	0.80	Ditching
CO28/19	Sunrise Drive	0.00	0.80	0.80	Mowing
CO28/19	Sunrise Drive	0.00	0.80	0.80	Mowing
CO28/19	Sunrise Drive	0.00	0.80	0.80	Patching
CO28/2	Hoguland Lane	0.00	2.85	2.85	Ditching
CO28/2	Houghlin Lane	0.00	2.85	2.85	Mowing
CO28/2	Houghlin Lane	0.00	2.85	2.85	Patching
CO28/20	Sky Valley Sub. III (clipper)	0.00	0.34	0.34	Ditching
CO28/20	Sky Valley III (Clipper)	0.00	0.34	0.34	Mowing
CO28/20	Sky Valley III (Clipper)	0.00	0.34	0.34	Mowing
CO28/20	Sky Valley Drive	0.00	0.34	0.34	Patching
CO28/21	Sky Valley Sub. IV (Gale)	0.00	0.23	0.23	Ditching
CO28/21	Sky Valley IV (East)	0.00	0.23	0.23	Mowing
CO28/21	Sky Valley IV (East)	0.00	0.23	0.23	Mowing
CO28/21	East Court	0.00	0.23	0.23	Patching
CO28/22	Sky Valley Sub. V (Humidity)	0.00	0.18	0.18	Ditching
CO28/22	Sky Valley V (Humidity)	0.00	0.18	0.18	Mowing
CO28/22	Sky Valley V (Humidity)	0.00	0.18	0.18	Mowing
CO28/22	North Street	0.00	0.18	0.18	Patching
CO28/23	Vandevander Dr	0.00	0.57	0.57	Ditching
CO28/23	Vandevander Drive	0.00	0.57	0.57	Mowing
CO28/23	Vandevander Drive	0.00	0.57	0.57	Mowing
CO28/23	Vandevander Drive	0.00	0.57	0.57	Patching
CO28/24	Meadows Lane (Vand. Dr)	0.00	0.55	0.55	Ditching
CO28/24	Meadow Drive (Vand.)	0.00	0.55	0.55	Mowing
CO28/24	Meadow Drive (Vand.)	0.00	0.55	0.55	Mowing
CO28/24	Meadow Drive	0.00	0.55	0.55	Patching
CO28/25	Boardwalk Dr (Vand. Dr)	0.00	0.40	0.40	Ditching
CO28/25	Hillcrest Drive (Vand.)	0.00	0.40	0.40	Mowing
CO28/25	Hillcrest Drive (Vand.)	0.00	0.40	0.40	Mowing
CO28/25	HillCrest Drive	0.00	0.40	0.40	Patching
CO28/26	Circle Dr. (Buffalo Dr)	0.00	0.70	0.70	Ditching
CO28/26	Circle Drive (Buffalo)	0.00	0.70	0.70	Mowing
CO28/26	Circle Drive (Buffalo)	0.00	0.70	0.70	Mowing
CO28/26	Circle Drive	0.00	0.70	0.70	Patching
CO28/27	Liberty Ct. (Buffalo Dr)	0.00	0.07	0.07	Ditching
CO28/27	Liberty Court (Buffalo)	0.00	0.07	0.07	Mowing
CO28/27	Liberty Court (Buffalo)	0.00	0.07	0.07	Mowing
CO28/27	Liberty Court	0.00	0.07	0.07	Patching
CO28/28	Hospital Dr	0.00	0.34	0.34	Ditching
CO28/28	Grant Memorial Drive	0.00	0.34	0.34	Mowing
CO28/28	Grant Memorial Drive	0.00	0.34	0.34	Mowing
CO28/28	Grant Memorial Drive	0.00	0.34	0.34	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO28/29	Fort Mulligan	0.00	0.06	0.06	Ditching
CO28/29	Fort Mulligan	0.00	0.06	0.06	Mowing
CO28/29	Fort Mulligan	0.00	0.06	0.06	Mowing
CO28/29	Fort Mulligan Access Rd	0.00	0.06	0.06	Patching
CO28/3	Corners Rd	0.00	4.86	4.86	Ditching
CO28/3	Corners Rd	0.00	4.86	4.86	Mowing
CO28/3	Corners Rd	0.00	4.86	4.86	Patching
CO28/30	Buffalo Dr (HA914)	0.00	0.65	0.65	Ditching
CO28/30	Buffalo Drive	0.00	0.65	0.65	Mowing
CO28/30	Buffalo Drive	0.00	0.65	0.65	Mowing
CO28/30	Buffalo Drive	0.00	0.65	0.65	Patching
CO28/30	Buffalo Drive	0.00	0.65	0.65	Patching
CO28/4	Powers Hollow	0.00	2.17	2.17	Ditching
CO28/4	Powers Hollow Rd	0.00	2.17	2.17	Mowing
CO28/4	Powers Hollow	0.00	2.17	2.17	Patching
CO28/4	Powers Hollow Rd	0.68	2.17	1.49	Stabilization
CO28/7	Jordan Run Rd	0.00	13.05	13.05	Ditching
CO28/7	Jordan Run Rd	0.00	13.05	13.05	Mowing
CO28/7	Jordan Run Rd	0.00	13.05	13.05	Patching
CO28/8	Wildcat Rd	0.00	1.58	1.58	Ditching
CO28/8	WildCat Rd	0.00	1.58	1.58	Mowing
CO28/8	WildCat Rd	0.00	1.58	1.58	Patching
CO28/9	Corners "Y"	0.00	0.12	0.12	Ditching
CO28/9	Corners Y	0.00	0.12	0.12	Mowing
CO28/9	Corners Y	0.00	0.12	0.12	Patching
CO3	Knobley Rd	0.00	13.63	13.63	Ditching
CO3	Knobley Rd	0.00	13.63	13.63	Mowing
CO3	Knobley	0.00	13.63	13.63	Patching
CO3/1	Harness Run Rd	0.00	4.24	4.24	Ditching
CO3/1	Harness Run Rd	0.00	4.24	4.24	Mowing
CO3/1	Harness Run Rd	0.00	4.24	4.24	Patching
CO3/1	Harness Run	1.45	4.24	2.79	Stabilization
CO3/2	Martin Rd	0.00	4.04	4.04	Ditching
CO3/2	Martin Rd	0.00	4.04	4.04	Mowing
CO3/2	Martin Rd	0.00	4.04	4.04	Mowing
CO3/2	Martin-Thorne Rd	0.00	4.04	4.04	Patching
CO3/3	Greenland Gap Rd	0.00	5.89	5.89	Ditching
CO3/3	Greenland Oscar Halterman Rd	0.00	5.89	5.89	Mowing
CO3/3	Greenland Oscar Halterman Rd	0.00	5.89	5.89	Mowing
CO3/3	Greenland Gap	0.00	5.89	5.89	Patching
CO3/4	Morgantown West	0.00	4.13	4.13	Ditching
CO3/4	Morgantown West	0.00	4.13	4.13	Mowing
CO3/4	Morgantown West	0.00	4.13	4.13	Patching
CO3/5	Eston Carr Rd	0.00	2.15	2.15	Ditching
CO3/5	Eston Carr Rd	0.00	2.15	2.15	Mowing
CO3/5	Eston Carr Rd	0.00	2.15	2.15	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO3/6	Tucker Ridge Rd	0.00	1.18	1.18	Ditching
CO3/6	Tucker Ridge	0.00	1.18	1.18	Mowing
CO3/6	Tucker Ridge Rd	0.00	1.18	1.18	Stabilization
CO4/2	Stoney Rive Rd	0.00	2.94	2.94	Ditching
CO4/2	Stoney River Dam Rd	0.00	2.94	2.94	Mowing
CO4/2	Stoney River Dam Rd	0.00	2.94	2.94	Patching
CO4/2	Stoney River Rd	0.38	2.94	2.56	Stabilization
CO4/3	Germany Hollow Rd	0.00	1.73	1.73	Ditching
CO4/3	Germany Hollow	0.00	1.73	1.73	Mowing
CO4/3	Germany Hollow	0.00	1.73	1.73	Patching
CO4/3	Germany Hollow Rd	0.44	1.73	1.29	Stabilization
CO42/1	Grassy Ridge Rd	0.00	3.11	3.11	Ditching
CO42/1	Grassy Ridge Rd	0.00	3.11	3.11	Mowing
CO42/1	Grassy Ridge Rd	0.00	3.11	3.11	Patching
CO42/1	Grassy Ridge Rd	2.00	3.11	1.11	Stabilization
CO42/10	Maysville Cemetary Rd	0.00	0.19	0.19	Ditching
CO42/10	Maysville Cemetary Rd	0.00	0.19	0.19	Mowing
CO42/10	Maysville Cemetary Rd	0.00	0.19	0.19	Patching
CO42/11	Maysville Main St	0.00	0.08	0.08	Ditching
CO42/11	Maysville Street	0.00	0.08	0.08	Mowing
CO42/11	Main St	0.00	0.08	0.08	Patching
CO42/12	Maysville Water St	0.00	0.35	0.35	Ditching
CO42/12	Maysville Street	0.00	0.35	0.35	Mowing
CO42/12	Water St	0.00	0.35	0.35	Patching
CO42/13	Roby Rd	0.00	1.94	1.94	Ditching
CO42/13	Roby Rd	0.00	1.94	1.94	Mowing
CO42/13	Roby Rd	0.00	1.94	1.94	Patching
CO42/14	Old Rt. 42 (Scherr)	0.00	0.32	0.32	Ditching
CO42/14	Old WV42 (Scherr)	0.00	0.32	0.32	Mowing
CO42/14	Old WV42 Scherr	0.00	0.32	0.32	Patching
CO42/15	Old Rt. 42 (VFW-Blacks Turn)	0.00	0.56	0.56	Ditching
CO42/15	Old 42 (VFW)	0.00	0.56	0.56	Mowing
CO42/15	Old WV42 VFW	0.00	0.56	0.56	Patching
CO42/16	Maysville Elementary School	0.00	0.09	0.09	Ditching
CO42/16	Maysville School Access	0.00	0.09	0.09	Mowing
CO42/16	Maysville Elementary School	0.00	0.09	0.09	Patching
CO42/2	Oakdale rd	0.00	3.52	3.52	Ditching
CO42/2	OakDale Rd	0.00	3.52	3.52	Mowing
CO42/2	Oakdale Rd	0.00	3.52	3.52	Patching
CO42/3	Buckbee Hollow Rd	0.00	5.06	5.06	Ditching
CO42/3	Cal Lyons Buckbee Hollow Rd	0.00	5.06	5.06	Mowing
CO42/3	Buckbee Hollow Rd	0.00	5.06	5.06	Patching
CO42/4	Keplinger Rd	0.00	4.17	4.17	Ditching
CO42/4	Keplinger Rd	0.00	4.17	4.17	Mowing
CO42/4	Keplinger Rd	0.00	4.17	4.17	Patching
CO42/5	Country Rd	0.00	3.76	3.76	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO42/5	Maysville Rd	0.00	3.76	3.76	Mowing
CO42/5	Maysville Rd	0.00	3.76	3.76	Patching
CO42/6	Possum Hollow Rd	0.00	5.40	5.40	Ditching
CO42/6	Possum Hollow	0.00	5.40	5.40	Mowing
CO42/6	Possum Hollow Rd	0.00	5.40	5.40	Patching
CO42/6	Galazy Rd	1.70	2.20	0.50	Stabilization
CO42/7	Haslacker/Hott Hill	0.00	6.55	6.55	Ditching
CO42/7	Haslacker/Hott Hill	0.00	6.55	6.55	Mowing
CO42/7	Haslacker/Hott Hill Rd	0.00	6.55	6.55	Patching
CO42/8	Bible Rd	0.00	0.72	0.72	Ditching
CO42/8	Seymoressville Rd Bible Rd	0.00	0.72	0.72	Mowing
CO42/8	Seymourville Rd	0.00	0.72	0.72	Stabilization
CO42/9	Smith Rd	0.00	0.39	0.39	Ditching
CO42/9	Smith Rd	0.00	0.27	0.27	Ditching
CO42/9	Smith Rd	0.00	0.27	0.27	Mowing
CO42/9	Smith Rd	0.00	0.39	0.39	Mowing
CO42/9	Smith Rd	0.00	0.39	0.39	Patching
CO42/9	Smith Rd	0.00	0.27	0.27	Patching
CO5	Patterson Creek Rd	0.00	16.20	16.20	Ditching
CO5	Patterson Creek Rd	0.00	16.20	16.20	Patching
CO5	Patterson Creek Rd	0.00	16.20	16.20	Mowing
CO5/1	Popular School Rd	0.00	3.91	3.91	Ditching
CO5/1	Poplar School Rd (T & C)	0.00	3.91	3.91	Mowing
CO5/1	Poplar School Rd	0.00	3.91	3.91	Mowing
CO5/1	Poplar School Rd	0.00	3.91	3.91	Patching
CO5/1	Popular School Rd	0.00	2.23	2.23	Stabilization
CO5/2	Williamsport Rd	0.00	5.81	5.81	Ditching
CO5/2	Williamsport Twin Mt. (T & C)	0.00	1.91	1.91	Mowing
CO5/2	Williamsport Twin Mt.	0.00	5.81	5.81	Mowing
CO5/2	Williamsport-Twin Mt.	0.00	5.81	5.81	Patching
CO5/2	Williamsport Rd	1.91	5.81	3.90	Stabilization
CO5/3	Max Baer Rd	0.00	3.90	3.90	Ditching
CO5/3	Max Baer Rd	0.00	3.90	3.90	Mowing
CO5/3	Max Baer Rd	0.00	3.90	3.90	Mowing
CO5/3	Max Baer Rd	0.00	3.90	3.90	Patching
CO5/4	Thorn Run Rd	0.00	3.54	3.54	Ditching
CO5/4	Thorne Run Rd	0.00	3.54	3.54	Mowing
CO5/4	Thorne Run Rd	0.00	3.54	3.54	Mowing
CO5/4	Thorne Run Rd	0.00	3.54	3.54	Patching
CO5/5	Foreman Rd	0.00	2.59	2.59	Ditching
CO5/5	Foreman Rd	0.00	2.59	2.59	Mowing
CO5/5	Foreman Road	0.00	2.59	2.59	Patching
CO5/5	Foreman Rd	0.81	2.59	1.78	Stabilization
CO5/6	Pumpkin Center Rd	0.00	2.45	2.45	Ditching
CO5/6	Pumpkin Center	0.00	2.45	2.45	Mowing
CO5/6	Pumpkin Center Rd	0.00	2.45	2.45	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO5/7	Morgantown East	0.00	3.10	3.10	Ditching
CO5/7	Morgantown East	0.00	3.10	3.10	Mowing
CO5/7	Morgantown East	0.00	3.10	3.10	Patching
CO5/8	Egypt Hollow Rd	0.00	1.36	1.36	Ditching
CO5/8	Egypt Rd	0.00	1.36	1.36	Mowing
CO5/8	Egypt Rd	0.00	1.36	1.36	Mowing
CO5/8	Egypt Rd	0.00	1.36	1.36	Patching
CO5/8	Egypt Hollow Rd	1.10	1.36	0.26	Stabilization
CO5/9	Tearcoat Rd	0.00	1.75	1.75	Ditching
CO5/9	Tearcoat Td	0.00	1.75	1.75	Mowing
CO5/9	Tearcoat Rd	0.00	1.75	1.75	Patching
CO50/1	Bayard Cemetary Rd	0.00	2.50	2.50	Ditching
CO50/1	Bayard Cemetary Rd	0.00	2.50	2.50	Mowing
CO50/1	Bayard Cemetary	0.00	2.50	2.50	Patching
CO50/10	Moomau Mine	0.00	0.70	0.70	Ditching
CO50/10	Moomau Mine Rd	0.00	0.70	0.70	Mowing
CO50/10	Moomau Mine	0.00	0.70	0.70	Patching
CO50/11	Snowfall Dr	0.00	0.25	0.25	Ditching
CO50/11	Old US50 (Snowfall)	0.00	0.25	0.25	Mowing
CO50/11	Vepco Dam Rd Old US50	0.00	0.25	0.25	Patching
CO50/12	Energy Way	0.00	0.80	0.80	Ditching
CO50/12	Energy Way Rd	0.00	0.80	0.80	Mowing
CO50/12	Energy Way	0.00	0.80	0.80	Patching
CO50/13	Old Rt. 50 (VFW)	0.00	0.20	0.20	Ditching
CO50/13	Old US50 (VFW)	0.00	0.20	0.20	Mowing
CO50/14	Old Rt. 50 (Stoney River)	0.00	0.42	0.42	Ditching
CO50/14	Old US50 (Stoney River)	0.00	0.42	0.42	Mowing
CO50/2	Cherry Ridge Rd	0.00	2.37	2.37	Ditching
CO50/2	Cherry Ridge Rd	0.00	2.37	2.37	Mowing
CO50/2	Cherry Ridge	0.00	2.37	2.37	Patching
CO50/3	Bismark Rd	0.00	4.86	4.86	Ditching
CO50/3	Bismark Rd	0.00	4.86	4.86	Mowing
CO50/3	Bismark	0.00	4.86	4.86	Patching
CO50/4	Schell Rd	0.00	1.78	1.78	Ditching
CO50/4	Schell Rd	0.00	1.78	1.78	Mowing
CO50/4	Schell Rd	0.00	1.78	1.78	Patching
CO50/5	Arnold Mine Rd	0.00	5.97	5.97	Ditching
CO50/5	Arnold Mine / Butterfly	0.00	4.77	4.77	Mowing
CO50/5	Arnold Mine Rd	0.00	5.97	5.97	Patching
CO50/5	Arnold Mine Rd	2.67	3.97	1.30	Stabilization
CO50/6	Pisagh Rd	0.00	2.18	2.18	Ditching
CO50/6	Pisagah Rd	0.00	2.18	2.18	Mowing
CO50/6	Pisagah	0.00	2.18	2.18	Patching
CO50/7	Lee Davis	0.00	1.07	1.07	Ditching
CO50/7	Lee Davis Rd	0.00	1.07	1.07	Mowing
CO50/7	Lee Davis Rd	0.00	1.07	1.07	Stabilization

Route	Local Name	BMP	EMP	Length	Activity
CO50/8	Kuhn Mine Rd	0.00	1.70	1.70	Ditching
CO50/8	Kuhn Mine Rd	0.00	1.20	1.20	Mowing
CO50/8	Kuhn Mine	0.00	1.70	1.70	Patching
CO50/9	Jones Hollow Rd	0.00	1.77	1.77	Ditching
CO50/9	Jones Hollow (Kitzmiller)	0.00	1.77	1.77	Mowing
CO50/9	Jones Hollow Rd	0.00	1.77	1.77	Patching
CO6	Reuben Martin Rd	0.00	0.65	0.65	Ditching
CO6	Ruben Martin Rd	1.04	2.04	1.00	Ditching
CO6	Klines Gap	0.00	1.54	1.54	Mowing
CO6	Klines Gap Rd	0.00	1.54	1.54	Mowing
CO6	Reuben Martin Rd	0.00	0.65	0.65	Stabilization
CO6	Reuben Martin Rd	1.04	1.65	0.61	Stabilization
CO7	Ridge Rd	0.00	5.90	5.90	Ditching
CO7	Ridge Rd	0.00	5.90	5.90	Mowing
CO7	Ridge Rd	0.00	5.90	5.90	Patching
CO7/1	Brick School Rd	0.00	2.00	2.00	Ditching
CO7/1	Brick School Rd	0.00	2.00	2.00	Mowing
CO7/1	Brick School Rd	0.00	2.00	2.00	Patching
CO8	Durgon rd	0.00	2.89	2.89	Ditching
CO8	Durgon Rd	0.00	2.89	2.89	Mowing
CO8	Durgon Rd	0.00	2.89	2.89	Patching
CO8/1	Creitz Rd	0.00	1.31	1.31	Ditching
CO8/1	Crites Rd	0.00	1.31	1.31	Mowing
CO8/1	Creitz Rd	0.00	1.31	1.31	Patching
CO9	South Mill Creek Rd	0.00	12.81	12.81	Ditching
CO9	South Mill Creek Rd	0.00	12.81	12.81	Mowing
CO9	South Mill Creek Rd	0.00	12.81	12.81	Patching
CO9/1	Elkhorn/Getz	0.00	5.32	5.32	Ditching
CO9/1	Elkhorn Rd	0.00	5.32	5.32	Mowing
CO9/1	Elkhorn Getz Rd	0.00	5.32	5.32	Patching
CO9/1	Elkhorn/Getz Rd	0.00	1.81	1.81	Stabilization
CO9/10	Tom Cox Rd	0.00	1.17	1.17	Ditching
CO9/10	Tom Cox Rd	0.00	1.17	1.17	Mowing
CO9/10	Tom Cox Rd	0.00	1.17	1.17	Patching
CO9/11	Old Rt. 9	0.00	0.11	0.11	Ditching
CO9/11	Old Rt. 9 (Alt's Groc)	0.00	0.11	0.11	Mowing
CO9/11	Old Rt. 9 (Alt's Groc)	0.00	0.11	0.11	Mowing
CO9/11	Old Co 9	0.00	0.11	0.11	Patching
CO9/12	Yucky Run Rd	0.00	0.34	0.34	Ditching
CO9/12	Yucky Run Rd	0.00	0.34	0.34	Mowing
CO9/12	Yucky Run Rd	0.00	0.34	0.34	Mowing
CO9/12	Yucky Run Rd	0.00	0.34	0.34	Patching
CO9/13	Arnold Rd	0.00	2.55	2.55	Ditching
CO9/13	Arnold Rd	0.00	2.55	2.55	Mowing
CO9/13	Arnold Rd	0.00	2.55	2.55	Mowing
CO9/13	Arnold Rd	0.00	2.55	2.55	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO9/2	Spring Run Rd	0.00	4.39	4.39	Ditching
CO9/2	Spring Run	0.00	4.39	4.39	Mowing
CO9/2	Spring Run	0.00	4.39	4.39	Patching
CO9/2	Spring Run Rd	2.22	4.39	2.17	Stabilization
CO9/3	Deep Springs Rd	0.00	7.02	7.02	Ditching
CO9/3	Deep Spring Rd	0.00	7.02	7.02	Mowing
CO9/3	Deep Spring Rd (T & C)	4.47	7.02	2.55	Mowing
CO9/3	Deep Spring	0.00	7.02	7.02	Patching
CO9/3	Deep Spring Rd	0.00	4.47	4.47	Stabilization
CO9/4	Kites Rd	0.00	1.06	1.06	Ditching
CO9/4	Kites Rd	0.00	1.06	1.06	Mowing
CO9/4	Kite Rd	0.00	1.06	1.06	Stabilization
CO9/5	Hinkle Hollow	0.00	1.35	1.35	Ditching
CO9/5	Hinkle Hollow Rd	0.00	1.35	1.35	Mowing
CO9/5	Hinkle Hollow Rd	0.00	1.35	1.35	Mowing
CO9/5	Hinkle Hollow Rd	0.00	1.35	1.35	Patching
CO9/6	Happy Hollow	0.00	2.66	2.66	Ditching
CO9/6	Happy Hollow	0.00	2.66	2.66	Mowing
CO9/6	Sites Hollow	0.00	2.66	2.66	Patching
CO9/6	Happy Hollow Rd	0.00	0.56	0.56	Stabilization
CO9/7	Knob Rd	0.00	0.52	0.52	Ditching
CO9/7	Knob Rd	0.00	0.52	0.52	Mowing
CO9/7	Knob Road	0.00	0.52	0.52	Patching
CO9/8	Bergdoll Rd	0.00	0.17	0.17	Ditching
CO9/8	Bergdell Rd	0.00	0.17	0.17	Mowing
CO9/8	Bergdell Rd	0.00	0.17	0.17	Mowing
CO9/8	Bergdell	0.00	0.17	0.17	Patching
CO9/9	Deep Springs Rd	0.00	0.15	0.15	Ditching
CO9/9	Deep Spring Rd	0.00	0.15	0.15	Mowing
CO9/9	Deep Spring	0.00	0.15	0.15	Stabilization
CO90/1	Al Brown Rd	0.00	5.90	5.90	Ditching
CO90/1	Al Brown Rd	0.00	5.90	5.90	Mowing
CO90/1	Al Brown	0.00	5.90	5.90	Patching
CO90/1	Al Brown Rd	1.75	5.90	4.15	Stabilization
CO90/2	Bayard Bridge App.	0.00	0.03	0.03	Ditching
CO90/2	Bayard Bridge Approach	0.00	0.03	0.03	Mowing
CO90/2	Bayard Bridge Approach	0.00	0.03	0.03	Patching
CO90/3	Wilson Bridge App.	0.00	0.14	0.14	Ditching
CO90/3	Wilson Bridge Approach	0.00	0.14	0.14	Mowing
CO90/3	Wilson Bridge Approach	0.00	0.14	0.14	Patching
CO90/4	Dobbin Bridge App.	0.00	0.07	0.07	Ditching
CO90/4	Dobbin Bridge Approach	0.00	0.07	0.07	Mowing
CO90/4	Dobbin Bridge Approach	0.00	0.07	0.07	Patching
CO93/1	Industrial Park Rd	0.00	0.44	0.44	Ditching
CO93/1	Mountain Top Industrial Park Access	0.00	0.44	0.44	Mowing
CO93/1	Mountain Top Industrial Park	0.00	0.44	0.44	Patching

Route	Local Name	BMP	EMP	Length	Activity
FS19	Dolly Sods Rd	0.00	4.70	4.70	Ditching
FS19	FS19	0.00	4.70	4.70	Mowing
FS19	FS19	0.00	4.72	4.72	Patching
FS19	Dolly Sods Rd	0.19	4.70	4.51	Stabilization
FS75	Brush Ridge Rd	0.00	1.65	1.65	Ditching
FS75	FS75	0.00	1.65	1.65	Mowing
FS75	FS75	0.00	1.22	1.22	Patching
FS75	Brushy Ridge Rd	0.60	1.65	1.05	Stabilization
HA901	Rohrbaugh Lane	0.00	0.90	0.90	Ditching
HA901	Rohrbaugh Lane	0.00	0.90	0.90	Mowing
HA901	Rohrbaugh Lane	0.00	0.90	0.90	Stabilization
HA902	Bland Rd	0.00	0.15	0.15	Ditching
HA902	Bland Rd	0.00	0.15	0.15	Stabilization
HA903	Echo Hollow Dr	0.00	0.33	0.33	Ditching
HA903	Echo Hollow Rd	0.00	0.33	0.33	Stabilization
HA904	Sears Gap Rd	0.00	1.00	1.00	Ditching
HA904	Sears Gap Phares Hollow	0.00	1.00	1.00	Mowing
HA904	Sears Gap Rd	0.00	1.00	1.00	Stabilization
HA908	Hedrick Dr	0.00	0.30	0.30	Ditching
HA908	Hedrick Drive	0.00	0.30	0.30	Mowing
HA908	Hedrick Drive	0.00	0.30	0.30	Stabilization
HA909	Kimble Rd (220/15)	0.00	0.25	0.25	Ditching
HA909	Kimble Rd	0.00	0.25	0.25	Patching
HA910	Judy Rd (220/16)	0.00	0.24	0.24	Ditching
HA910	Judy Rd	0.00	0.24	0.24	Patching
HA911	Kyle Rd (220/17)	0.00	0.12	0.12	Ditching
HA911	Kyle Rd	0.00	0.12	0.12	Patching
HA912	Deer Ridge	0.00	0.40	0.40	Ditching
HA912	Mountain View (Deer Ridge)	0.00	0.40	0.40	Mowing
HA912	Mountain View Rd	0.00	0.40	0.40	Patching
HA913	Bishop Pine Rd	0.00	0.25	0.25	Ditching
HA913	Oak Lane Rd (Deer Ridge)	0.00	0.25	0.25	Mowing
HA913	Oak Lane Rd	0.00	0.25	0.25	Patching
HA913	Oak Lane (Deer Ridge)	0.00	0.25	0.25	Stabilization
HA919	Mourning Dove Lane (Buffalo Dr)	0.00	0.11	0.11	Ditching
HA919	Mourning Dove Lane (Oak Cove)	0.00	0.11	0.11	Mowing
HA919	Mourning Dove Lane	0.00	0.11	0.11	Patching
HA920	Mockingbird Lane (Buffalo Dr)	0.00	0.06	0.06	Ditching
HA920	Mocking Bird Lane (Oak Cove)	0.00	0.06	0.06	Mowing
HA920	Mockingbird Lane	0.00	0.06	0.06	Patching
HA921	Bluebird Lane (Buffalo Dr)	0.00	0.05	0.05	Ditching
HA921	BlueBird Lane (Oak Cove)	0.00	0.05	0.05	Mowing
HA921	Bluebird Lane	0.00	0.05	0.05	Patching
HA923	Wheeler Rd	0.00	0.58	0.58	Ditching
HA923	Wheeler Hill	0.00	0.58	0.58	Mowing
HA923	Wheeler Hill Rd	0.00	0.58	0.58	Stabilization

Route	Local Name	BMP	EMP	Length	Activity
HA924	Sherman Lane	0.00	0.22	0.22	Ditching
HA924	Sherman Lane	0.00	0.22	0.22	Mowing
HA924	Sherman Lane	0.00	0.22	0.22	Stabilization
HA927	Woodland Drive	0.00	0.21	0.21	Ditching
HA927	Woodlanw Drive (Monarch)	0.00	0.21	0.21	Mowing
HA927	Woodlawn Drive	0.00	0.21	0.21	Patching
HA928	Sunset Drive	0.00	0.14	0.14	Ditching
HA928	Sunset Drive (Monarch)	0.00	0.14	0.14	Mowing
HA928	Sunset Drive	0.00	0.14	0.14	Patching
HA929	Hillcrest Drive	0.00	0.03	0.03	Ditching
HA929	Hillcrest Court (Monarch)	0.00	0.03	0.03	Mowing
HA929	Hillcrest Court	0.00	0.03	0.03	Patching
HA930	Clearview Drive	0.00	0.03	0.03	Ditching
HA930	Clearview Court (Monarch)	0.00	0.03	0.03	Mowing
HA930	Clearview Court	0.00	0.03	0.03	Patching
HA931	Evans Dr (off 50/5)	0.00	0.38	0.38	Ditching
HA931	Evans Drive	0.00	0.38	0.38	Mowing
HA931	Evans Drive	0.00	0.38	0.38	Stabilization
HA932	Wycroff Run Rd (off50E)	0.00	0.42	0.42	Ditching
HA932	Wycroff Run Rd	0.00	0.42	0.42	Mowing
HA932	Wycroff Run Rd	0.00	0.42	0.42	Stabilization
HA933	Boot Hill Dr	0.00	0.50	0.50	Ditching
HA933	Boot Hill Drive	0.00	0.50	0.50	Mowing
HA933	Boot Hill Rd	0.00	0.50	0.50	Patching
HA933	Boot Hill Rd	0.30	0.50	0.20	Stabilization
HA934	Calico Dr	0.00	0.20	0.20	Ditching
HA934	Chams Lane	0.00	0.20	0.20	Mowing
HA934	Calico Lane	0.00	0.20	0.20	Patching
HA934	Silverado Drive	0.00	0.07	0.07	Stabilization
HA935	Silverado Dr	0.00	0.07	0.07	Ditching
HA935	Hobbits Glen Lane	0.00	0.07	0.07	Mowing
HA936	H.L. Lane	0.00	0.09	0.09	Ditching
HA936	HL Lane	0.00	0.09	0.09	Mowing
HA936	H.L. Lane	0.00	0.09	0.09	Patching
US220	Franklin Pike	0.00	10.64	10.64	Ditching
US220	Petersburg Gap (220N)	11.34	13.03	1.69	Ditching
US220	US220	0.00	13.03	13.03	Mowing
US220	Pendleton Co Line to WV28	0.00	10.64	10.64	Patching
US220	WV28 Stplgt. To Hardy CO LN	0.00	2.39	2.39	Patching
US48	Corridor H	75.62	77.00	1.38	Ditching
US48	Corridor H	77.00	79.00	2.00	Ditching
US48	Corridor H	79.00	81.00	2.00	Ditching
US48	Corridor H	81.00	83.00	2.00	Ditching
US48	Corridor H	83.00	85.00	2.00	Ditching
US48	Corridor H	85.00	87.00	2.00	Ditching
US48	Corridor H	87.00	89.00	2.00	Ditching

Route	Local Name	BMP	EMP	Length	Activity
US48	Corridor H	89.00	91.00	2.00	Ditching
US48	Corridor H	91.00	93.00	2.00	Ditching
US48	Corridor H	93.00	95.00	2.00	Ditching
US48	Corridor H	95.00	97.00	2.00	Ditching
US48	Corridor H	97.00	99.00	2.00	Ditching
US48	Corridor H	99.00	101.00	2.00	Ditching
US48	Corridor H	101.00	103.00	2.00	Ditching
US48	Corridor H	103.00	105.00	2.00	Ditching
US48	Corridor H	105.00	106.36	1.36	Ditching
US48	Corridor H	75.62	77.00	1.38	Mowing
US48	Corridor H	77.00	79.00	2.00	Mowing
US48	Corridor H	79.00	81.00	2.00	Mowing
US48	Corridor H	81.00	83.00	2.00	Mowing
US48	Corridor H	83.00	85.00	2.00	Mowing
US48	Corridor H	85.00	87.00	2.00	Mowing
US48	Corridor H	87.00	89.00	2.00	Mowing
US48	Corridor H	89.00	91.00	2.00	Mowing
US48	Corridor H	91.00	93.00	2.00	Mowing
US48	Corridor H	93.00	95.00	2.00	Mowing
US48	Corridor H	95.00	97.00	2.00	Mowing
US48	Corridor H	97.00	99.00	2.00	Mowing
US48	Corridor H	99.00	101.00	2.00	Mowing
US48	Corridor H	101.00	103.00	2.00	Mowing
US48	Corridor H	103.00	105.00	2.00	Mowing
US48	Corridor H	105.00	106.36	1.36	Mowing
US48	Corridor H	75.62	77.00	1.38	Patching
US48	Corridor H	77.00	79.00	2.00	Patching
US48	Corridor H	79.00	81.00	2.00	Patching
US48	Corridor H	81.00	83.00	2.00	Patching
US48	Corridor H	83.00	85.00	2.00	Patching
US48	Corridor H	85.00	87.00	2.00	Patching
US48	Corridor H	87.00	89.00	2.00	Patching
US48	Corridor H	89.00	91.00	2.00	Patching
US48	Corridor H	91.00	93.00	2.00	Patching
US48	Corridor H	93.00	95.00	2.00	Patching
US48	Corridor H	95.00	97.00	2.00	Patching
US48	Corridor H	97.00	99.00	2.00	Patching
US48	Corridor H	99.00	101.00	2.00	Patching
US48	Corridor H	101.00	103.00	2.00	Patching
US48	Corridor H	103.00	105.00	2.00	Patching
US48	Corridor H	105.00	106.36	1.36	Patching
US50	George Washington Hwy (50W)	0.00	7.45	7.45	Ditching
US50	George Washington Hwy (50E)	7.45	12.06	4.61	Ditching
US50	Maryland Line to Mt. Storm (West)	0.00	7.45	7.45	Mowing
US50	Mt. Storm to Mineral Co. Line(East)	7.45	12.06	4.61	Mowing
US50	MD Line to Mineral Co Line	0.00	12.06	12.06	Patching

Route	Local Name	BMP	EMP	Length	Activity
WV28	North Fork Hwy	0.00	13.38	13.38	Ditching
WV28	WV28	0.00	12.66	12.66	Mowing
WV28	Pendleton Co Line to US220	0.00	13.38	13.38	Patching
WV42	Lunice Creek Hwy	0.00	16.97	16.97	Ditching
WV42	Union Highway (Mt.)	16.97	25.62	8.65	Ditching
WV42	WV42	0.00	16.97	16.97	Mowing
WV42	Scherr to Bismark (42 Mt)	16.97	21.26	4.29	Mowing
WV42	Bismark to Mt. Storm(42 Mt. Top)	21.26	25.62	4.36	Mowing
WV42	WV28 to Scherr	0.00	16.97	16.97	Patching
WV42	Scherr to US50	16.97	25.62	8.65	Patching
WV90	Dobbin Hwy	0.00	10.51	10.51	Ditching
WV90	WV90	0.00	10.51	10.51	Mowing
WV90	Tucker Co Line to US50	0.00	10.51	10.51	Patching
WV93	Union Hwy (Lower 93)	9.60	18.22	8.62	Ditching
WV93	Tucker Co. Line to Bismark (Upper 93)	0.00	5.32	5.32	Mowing
WV93	Scherr to Mineral Co. (Lower 93)	9.60	18.22	8.62	Mowing
WV93	Tucker Co Line to WV42	0.00	5.32	5.32	Patching
WV93	Scherr to Mineral Co Line	9.60	18.22	8.62	Patching
WV93	Power Station Hwy (upper93)	0.00	5.32	5.32	Ditching

448.28 Mowing
415.12 Ditching
396.16 Patching