

Route	Local Name	BMP	EMP	Length	Activity
CO1/2	Badger Run Road	0.00	1.86	1.86	Ditching
CO1/2	Badger Run Road	0.00	1.86	1.86	Stabilization
CO10/2	Stewarts Run	0.00	1.98	1.98	Patching
CO11	Elk Ford Rd	0.47	10.24	9.77	Mowing
CO11	Elk Fork RD	0.00	10.24	10.24	Patching
CO11/6	Elk Ford Rd	0.00	0.42	0.42	Mowing
CO13	Dale Rd	12.09	14.20	2.11	Ditching
CO13	Indian Creek Rd	0.00	12.09	12.09	Patching
CO13	Dale Rd	12.09	14.20	2.11	Stabilization
CO13/1	Walnut Fork	0.00	2.00	2.00	Mowing
CO13/5	Sunfish	0.00	1.36	1.36	Ditching
CO13/5	Sunfish	0.00	1.36	1.36	Stabilization
CO13/8	Left Hand Fork	0.00	1.39	1.39	Mowing
CO14/4	Shiloh-Slicker Road	0.00	3.51	3.51	Ditching
CO18/2	Badger Run Road	1.67	3.96	2.29	Ditching
CO18/2	Badger Run Road	1.67	3.96	2.29	Stabilization
CO18/7	Lemasters Road	0.00	2.00	2.00	Ditching
CO18/7	Lemasters Road	0.00	2.00	2.00	Stabilization
CO18/8	Purgatory Run Road	0.00	1.36	1.36	Ditching
CO18/8	Purgatory Run Road	0.00	1.36	1.36	Stabilization
CO18/9	Spring Hill Lane	0.00	0.18	0.18	Ditching
CO18/9	Spring Hill Lane	0.00	0.18	0.18	Stabilization
CO24	Sellers Rd	0.00	3.60	3.60	Patching
CO28/1	Wetzel Tyler Ridge Road	7.60	0.00	7.60	Ditching
CO28/1	Wetzel Tyler Ridge Road	10.40	4.60	5.80	Ditching
CO28/1	Wetzel Tyler Ridge Rd	0.00	10.40	10.40	Mowing
CO28/1	Wetzel Tyler Ridge Road	7.60	0.00	7.60	Stabilization
CO30/3	Stull Hill Road	0.00	2.54	2.54	Ditching
CO30/3	Stull Hill Road	0.00	2.54	2.54	Stabilization
CO30/5	Cabin Run Road	0.00	0.71	0.71	Ditching
CO30/5	Cabin Run Road	0.00	0.71	0.71	Stabilization
CO36	Roberts Hill Road	0.00	1.77	1.77	Ditching
CO36	Roberts Hill Road	0.00	1.77	1.77	Stabilization
CO38	Muddy Creek Road	0.00	4.16	4.16	Ditching
CO38	Muddy Creek Road	0.00	4.16	4.16	Stabilization
CO40	Big Run Rd	0.00	4.86	4.86	Mowing
CO40/1	Meeker Rd	0.00	0.48	0.48	Mowing
CO42/2	Fallen Timber Road	1.20	0.00	1.20	Ditching
CO42/2	Fallen Timber Road	1.20	0.00	1.20	Stabilization
CO44	Wetzel Tyler Ridge Rd	0.00	5.69	5.69	Mowing
CO44/1	Big Run Rd	0.00	1.30	1.30	Mowing
CO44/2	Bonelick Run Rd	0.00	1.40	1.40	Mowing
CO46	Klondike Road	0.00	6.10	6.10	Ditching
CO46	Klondike Road	0.00	6.10	6.10	Stabilization
CO46/1	Jug Run Road	0.00	0.67	0.67	Ditching
CO46/1	Jug Run Road	0.00	0.67	0.67	Stabilization

Route	Local Name	BMP	EMP	Length	Activity
CO5	Arvilla Road	0.00	0.98	0.98	Ditching
CO5	Arvilla Rd	0.00	0.98	0.98	Mowing
CO55/1	Davis Run Rd	0.00	2.51	2.51	Mowing
CO55/3	Camp Run Rd	0.00	0.53	0.53	Mowing
CO58	Jefferson Run Road	0.00	7.07	7.07	Ditching
CO58	Singer Hill	3.73	4.83	1.10	Ditching
CO58	Jefferson Run	0.00	7.07	7.07	Mowing
CO58	Singer Hill	3.73	4.83	1.10	Stabilization
CO58/2	Duckworth Ridge	0.00	3.15	3.15	Mowing
CO6	Friendly-Rush Fork Road	2.29	5.29	3.00	Ditching
CO6	Friendly-Rush Fork Road	8.41	9.82	1.41	Ditching
CO6	Rush Fork - Friendly Rd	15.78	2.29	13.49	Patching
CO6/3	Sancho Rd	0.00	4.77	4.77	Patching
CO64	Braden Hill Rd	0.00	3.38	3.38	Mowing
CO66	Flint Run Rd	0.00	0.44	0.44	Mowing
CO7/2	Jamison Hill Road	0.00	1.01	1.01	Ditching
CO7/2	Jamison Hill Road	0.00	1.01	1.01	Stabilization
CO7/3	Rock Run Road	0.00	2.81	2.81	Ditching
CO7/6	Wheelers Run Road	3.29	2.10	1.19	Ditching
CO7/6	Wheelers Run Road	3.79	3.29	0.50	Ditching
CO7/6	Wheelers Run Road	3.29	2.10	1.19	Stabilization
WV18	WV 18	0.00	30.95	30.95	Mowing
WV18	WV 18	0.00	30.08	30.08	Patching
WV180	WV 180	0.00	4.06	4.06	Mowing
WV180	WV 180	0.00	4.06	4.06	Patching
WV2	WV 2	0.00	13.93	13.93	Mowing
WV2	WV 2	0.00	13.93	13.93	Patching
WV23	WV 23	0.00	8.75	8.75	Mowing
WV23	WV 23	0.00	8.75	8.75	Patching
WV74	WV 74	0.00	1.96	1.96	Mowing
WV74	WV 74	0.00	1.96	1.96	Patching

115.42 Mowing
64.29 Ditching
104.95 Patching
39.21 Stabilization