

Polymer Guardrail Blockouts

Material Code: 607.002.002 (AWP)

Effective: 4/29/2024

Contact: Gary.W.Mullins@wv.gov

Plastic Block on Steel Posts w/W-beam G.R. MASH Systems			
Manufacturer	Location	Material	Lab Number
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - GB14SH2	2100783
Valtir LLC. (Formerly Trinity Industries)	Lima, OH	King Block MASH16	2201674
Valtir LLC. (Formerly Trinity Industries)	Orangeburg, SC	King Block MASH16	2201675
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - GB14SH1	2400248

For Repair of 28 1/2" Splice on Post Guardrail Systems			
Manufacturer	Location	Material	Lab Number
Valtir LLC. (Formerly Trinity Industries)	Lima, OH	King Block 350	2201676
Valtir LLC. (Formerly Trinity Industries)	Orangeburg, SC	King Block 350	2201677
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - GB14SH	1438598

Plastic Block on Steel Posts w/Thrie-beam G.R.			
Manufacturer	Location	Material	Lab Number
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - TB21SH	1438599

Plastic Block on Notched or Rectangular Wood Posts w/W-beam G.R.			
Manufacturer	Location	Material	Lab Number
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - GB14U	1438601

**Plastic Block on Round Wood Posts w/W-beam G.R.			
Manufacturer	Location	Material	Lab Number
Mondo Polymer Technologies, Inc.	Reno, OH	Mondo Block - GB14R	1438600

**The WVDOH no longer uses round wooden posts for new construction. This item to only be used for repair of round wood post systems.