

Route	Local Name	BMP	EMP	Length	Activity
CO1	Beryl Road	0.00	0.09	0.09	Mowing
CO1	Beryl Rd	0.00	0.09	0.09	Patching
CO10	Georges Run	0.00	5.55	5.55	Ditching
CO10	Georges Run Road	0.00	5.55	5.55	Mowing
CO10	Georges Run Rd	0.00	5.55	5.55	Patching
CO11	Patterson Creek	0.00	5.40	5.40	Ditching
CO11	Patterson Creek	0.00	5.40	5.40	Ditching
CO11	Patterson Creek	5.40	7.98	2.58	Ditching
CO11	Patterson Creek	5.40	7.98	2.58	Ditching
CO11	Patterson Creek	8.08	13.50	5.42	Ditching
CO11	Patterson Creek [behind district	8.08	13.50	5.42	Ditching
CO11	Patterson Creek	13.61	18.35	4.74	Ditching
CO11	Patterson Creek	13.61	18.35	4.74	Ditching
CO11	Pattersons Creek Road	0.00	18.25	18.25	Mowing
CO11	Pattersons Creek Rd	0.00	18.25	18.25	Patching
CO11/2	Ed Welsh	0.00	4.21	4.21	Ditching
CO11/2	Ed Welsh	0.00	4.21	4.21	Ditching
CO11/2	Ed Welsh Road	0.00	4.21	4.21	Mowing
CO11/2	Ed Welsh Rd	0.00	4.21	4.21	Patching
CO11/3	Harness Run	0.00	0.65	0.65	Ditching
CO11/3	Harness Run	0.00	0.65	0.65	Ditching
CO11/3	Harness Run Road	0.00	0.65	0.65	Mowing
CO11/3	Harness Run	0.00	0.65	0.65	Stabilization
CO11/4	Fairview Drive	0.00	0.57	0.57	Ditching
CO11/4	Fairview Drive	0.00	0.57	0.57	Ditching
CO11/4	Fairview Drive	0.00	0.57	0.57	Mowing
CO11/4	Fairview Drive	0.00	0.57	0.57	Patching
CO11/5	Hilltop Drive	0.00	0.86	0.86	Ditching
CO11/5	Hilltop Drive	0.00	0.86	0.86	Ditching
CO11/5	Hill Top drive	0.00	0.86	0.86	Mowing
CO11/5	Hill Top	0.00	0.86	0.86	Patching
CO11/6	Lena's Lane	0.00	0.35	0.35	Ditching
CO11/6	Lena's Lane	0.00	0.35	0.35	Ditching
CO11/6	Kerns Lane	0.00	0.35	0.35	Mowing
CO11/6	Lena Lane	0.00	0.35	0.35	Stabilization
CO11/7	Red Oak Drive	0.00	0.07	0.07	Ditching
CO11/7	Red Oak Drive	0.00	0.07	0.07	Ditching
CO11/7	Red Oak Drive	0.00	0.07	0.07	Mowing
CO12	Seymour	0.00	1.00	1.00	Ditching
CO12	Seymour	1.00	2.40	1.40	Ditching
CO12	Seymous Road	0.00	2.40	2.40	Mowing
CO12	Seymous Rd	0.00	0.93	0.93	Patching
CO13	Russell Dale Road	0.00	6.62	6.62	Mowing
CO13	Russell Dale Rd	1.12	6.62	5.50	Patching
CO14	Limestone	0.00	4.72	4.72	Ditching
CO14	Limestone	0.00	4.72	4.72	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO14	Lime Stone Road	0.00	4.72	4.72	Mowing
CO14	Limestone Rd	0.00	4.72	4.72	Patching
CO14/1	Hollywood Road	0.00	0.68	0.68	Mowing
CO14/1	Hollywood Rd	0.00	0.68	0.68	Patching
CO15	Dans Run	0.00	8.97	8.97	Ditching
CO15	Dans Run Road	0.00	8.97	8.97	Mowing
CO15	Dans Run Rd	0.00	8.97	8.97	Patching
CO15/1	Broad Hollow Road	0.00	2.66	2.66	Mowing
CO15/2	Wagoner Road	0.00	2.74	2.74	Mowing
CO15/4	Seeders Road	0.00	1.25	1.25	Mowing
CO15/4	Miller Rd	0.00	1.25	1.25	Stabilization
CO15/5	FT.Ashby School	0.00	0.30	0.30	Ditching
CO15/5	Fort Ashby School	0.00	0.30	0.30	Mowing
CO15/5	Ft Ashby School	0.00	0.30	0.30	Patching
CO15/6	FT.Ashby School	0.00	0.9	0.90	Ditching
CO15/6	Fort Ashby School Road	0.00	0.09	0.09	Mowing
CO15/6	Fort Ashby School Rd	0.00	0.09	0.09	Patching
CO16	Beaver Run	0.00	5.52	5.52	Ditching
CO16	Beaver Run	0.00	5.52	5.52	Ditching
CO16	Fountain Headsville Beaver Run	5.52	8.13	2.61	Ditching
CO16	Fountain Headsville Beaver Run	5.52	8.13	2.61	Ditching
CO16	Fountain Headsville Beaver Run	8.13	9.48	1.35	Ditching
CO16	Fountain Headsville Beaver Run	8.13	9.48	1.35	Ditching
CO16	Fountain Headsville Beaver Run	9.48	9.93	0.45	Ditching
CO16	Fountain Headsville Beaver Run	9.48	9.93	0.45	Ditching
CO16	Fountain Headsville Beaver Run	9.93	10.55	0.62	Ditching
CO16	Fountain Headsville Beaver Run	9.93	10.55	0.62	Ditching
CO16	Fountain Headsville Beaver Run	10.55	10.98	0.43	Ditching
CO16	Fountain Headsville Beaver Run	10.55	10.98	0.43	Ditching
CO16	Headsville Road	0.00	10.86	10.86	Mowing
CO16	Headsville Rd	0.00	10.86	10.86	Patching
CO16/1	Fried Meat	0.00	4.18	4.18	Ditching
CO16/1	Fried Meat	0.00	4.18	4.18	Ditching
CO16/1	Fried Meat Ridge Rd	0.00	4.18	4.18	Patching
CO16/1	Fried Meat Ridge Road	0.00	4.18	4.18	Mowing
CO16/2	Push Root	0.00	4.74	4.74	Ditching
CO16/2	Push Root	0.00	4.74	4.74	Ditching
CO16/2	Push Root Road	0.00	4.74	4.74	Mowing
CO16/2	Push Root Rd	0.00	4.74	4.74	Patching
CO16/3	Tony Cook	0.00	2.23	2.23	Ditching
CO16/3	Tony Cook	0.00	2.23	2.23	Ditching
CO16/3	Tony Cook Road	0.00	2.23	2.23	Mowing
CO16/3	Tony Cook Rd	0.00	0.27	0.27	Patching
CO16/4	Old State Road	0.00	1.80	1.80	Ditching
CO16/4	Old State Road	0.00	1.80	1.80	Ditching
CO16/4	Old State Road	0.00	1.80	1.80	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO16/4	Old State Rd	0.00	1.80	1.80	Patching
CO17	Dennison Hollow	0.00	4.84	4.84	Ditching
CO17	Dennison Hollow Road	0.00	4.84	4.84	Mowing
CO17	Dennison Hollow Road	0.00	4.84	4.84	Patching
CO18	Dry Run Road	0.00	3.62	3.62	Mowing
CO18	Dry Run Rd	0.00	3.62	3.62	Patching
CO19	Donaldson Loop	0.00	2.91	2.91	Ditching
CO19	From RT 17 to RT 17	0.00	2.91	2.91	Mowing
CO19	From RT 17 to RT 17	0.00	2.91	2.91	Patching
CO2	Hartmansville	2.56	0.00	2.56	Ditching
CO2	Hartmansville	4.21	2.56	1.65	Ditching
CO2	Hartmansville	6.06	4.21	1.85	Ditching
CO2	Hartmansville Road	0.00	6.06	6.06	Mowing
CO2	Hartmansville Rd	0.00	6.06	6.06	Patching
CO2/1	Schell Road	0.00	7.33	7.33	Mowing
CO2/2	Oakmont	0.00	1.62	1.62	Ditching
CO2/2	Oakmont Road	0.00	1.82	1.82	Mowing
CO2/2	Oakmont Rd	0.00	1.30	1.30	Patching
CO2/3	Emoryville	0.00	0.23	0.23	Ditching
CO2/3	Emroyville Road	0.00	0.23	0.23	Mowing
CO2/3	Emoryvill Rd	0.00	0.23	0.23	Patching
CO21	Maple Avenue	0.00	2.22	2.22	Ditching
CO21	Airport Road	0.00	2.22	2.22	Mowing
CO21	Airport Rd	0.00	2.22	2.22	Patching
CO21/1	Swan Pond	0.00	0.39	0.39	Ditching
CO21/1	Swan Pond Road	0.00	0.39	0.39	Mowing
CO21/1	Swan Pond Road	0.00	0.39	0.39	Patching
CO22	Potomac Manner	0.00	0.04	0.04	Mowing
CO220/1	Stony Run	0.00	2.17	2.17	Ditching
CO220/1	Stoney Run Road	0.00	2.17	2.17	Mowing
CO220/1	Stoney Run Rd	0.00	2.17	2.17	Patching
CO220/2	Pine Swamp	0.00	0.34	0.34	Ditching
CO220/2	Piney Swamp	0.34	1.46	1.12	Ditching
CO220/2	Pine Swamp Road	0.00	1.46	1.46	Mowing
CO220/2	Pine Swamp Rd	0.00	1.46	1.46	Patching
CO220/3	New Creek "Y"	0.00	0.10	0.10	Mowing
CO220/3	New Creek "Y"	0.00	0.10	0.10	Patching
CO220/5	Harley O Staggers Drive	0.00	1.34	1.34	Ditching
CO220/5	New Creek Drive	0.00	1.34	1.34	Mowing
CO220/5	New Creek Drive	0.00	1.34	1.34	Patching
CO220/6	New Creek School Road	0.00	0.12	0.12	Mowing
CO220/6	New Creek School Rd	0.00	0.12	0.12	Patching
CO220/7	Southern Drive	0.00	0.21	0.21	Ditching
CO220/7	Southern Drive	0.00	0.21	0.21	Mowing
CO220/7	Southern Drive	0.00	0.21	0.21	Patching
CO220/8	New Keyser High School	0.00	0.44	0.44	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO220/8	Keyser High School Access Road	0.00	0.44	0.44	Mowing
CO220/8	Keyser High School Rd	0.00	0.44	0.44	Patching
CO28/1	Carpendale	0.00	2.20	2.20	Ditching
CO28/1	Carpenters Road	0.00	2.20	2.20	Mowing
CO28/1	Carpenters Rd	0.00	2.20	2.20	Patching
CO28/10	Plum Run Road	0.00	3.36	3.36	Mowing
CO28/10	Plum Run Rd	0.00	3.36	3.36	Patching
CO28/10	Plum Run Rd	0.00	1.11	1.11	Stabilization
CO28/11	Steckley Road	0.00	0.71	0.71	Ditching
CO28/11	Old Airport Road	0.00	0.71	0.71	Mowing
CO28/11	Old Airport Rd	0.00	0.71	0.71	Patching
CO28/12	Wiley Ford PO	0.00	0.32	0.32	Mowing
CO28/12	Wiley Ford PO	0.00	0.32	0.32	Patching
CO28/13	Detrick	0.00	0.32	0.32	Ditching
CO28/13	Detric Road	0.00	0.32	0.32	Mowing
CO28/13	Detrick Rd	0.00	0.32	0.32	Patching
CO28/14	Old Rt 28	0.00	0.31	0.31	Ditching
CO28/14	Fort Ashby Bridge to VFW Road	0.00	0.31	0.31	Mowing
CO28/14	Forst Ashby Br. to VFW Rd	0.00	0.23	0.23	Patching
CO28/15	Wiley Ford School	0.00	0.08	0.08	Ditching
CO28/15	Old Delta Wiley Ford School Road	0.00	0.08	0.08	Mowing
CO28/15	Old Delta Wiley Ford School	0.00	0.08	0.08	Patching
CO28/16	Green Alley	0.00	0.08	0.08	Mowing
CO28/16	Green Alley	0.00	0.08	0.08	Patching
CO28/17	Old WV 28 ALT	0.00	0.08	0.08	Mowing
CO28/17	Old WV 28 Alt.	0.00	0.08	0.08	Patching
CO28/18	Old WV 28 the Loop	0.00	0.07	0.07	Mowing
CO28/18	Old WV 28 The Loop	0.00	0.07	0.07	Patching
CO28/19	Old WV 28 at the Boonies	0.00	0.17	0.17	Mowing
CO28/19	Old WV 28 at Boonies	0.00	0.17	0.17	Patching
CO28/2	Furnace Road	0.00	3.92	3.92	Mowing
CO28/2	Furnace Rd	0.00	3.92	3.92	Patching
CO28/20	Old WV 28 Boonies	0.00	0.05	0.05	Mowing
CO28/20	Old WV 28 at Boonies	0.00	0.05	0.05	Patching
CO28/21	Millerdale/Davis/Powell	0.00	0.44	0.44	Ditching
CO28/21	Millerdale / Davis / Powenell Drive	0.00	0.44	0.44	Mowing
CO28/21	Millerdale-Davis-Pownell Dr	0.00	0.44	0.44	Patching
CO28/22	Old WV 28 (Wiley Ford)	0.00	0.18	0.18	Mowing
CO28/22	Old WV Rt 28 (Wiley Ford)	0.00	0.18	0.18	Patching
CO28/23	Old Rt 28/Miltenberger Strait	0.00	0.33	0.33	Ditching
CO28/23	Wiley Ford Road	0.00	0.33	0.33	Mowing
CO28/23	Wiley Ford	0.00	0.33	0.33	Patching
CO28/24	Frontage Road	0.00	0.07	0.07	Mowing
CO28/24	Frontage Rd	0.00	0.07	0.07	Patching
CO28/25	Frankfort Middle School	0.00	0.39	0.39	Ditching
CO28/25	Frankfort Middle School Entrance	0.00	0.39	0.39	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO28/25	Frankfort Middle School Ent	0.00	0.39	0.39	Patching
CO28/26	Cedar Avenue	0.00	0.16	0.16	Mowing
CO28/26	Cedar Avenue	0.00	0.16	0.16	Patching
CO28/27	Old WV 28	0.00	0.13	0.13	Mowing
CO28/27	Old WV Route 28	0.00	0.13	0.13	Patching
CO28/3	Patterson Creek	0.00	4.21	4.21	Ditching
CO28/3	Pattersons Creek Village Road	0.00	4.21	4.21	Mowing
CO28/3	Pattersons Creek Village Rd	0.00	4.21	4.21	Patching
CO28/4	Baker Road	0.00	3.19	3.19	Ditching
CO28/4	Baker Road	0.00	3.19	3.19	Mowing
CO28/4	Baker Rd	0.00	3.19	3.19	Patching
CO28/5	Painter Hollow	0.00	3.66	3.66	Ditching
CO28/5	Painter Hollow Road	0.00	3.32	3.32	Mowing
CO28/5	Painter Holow Rd	0.00	3.10	3.10	Patching
CO28/6	John Chaney	0.00	0.81	0.81	Ditching
CO28/6	John Chaney Road	0.00	0.81	0.81	Mowing
CO28/6	John Chaney Rd	0.00	0.81	0.81	Patching
CO28/7	Turnaround/Scenic	0.00	1.69	1.69	Ditching
CO28/7	Turnaround Road	0.00	1.69	1.69	Mowing
CO28/7	Turnaround Rd	0.00	1.69	1.69	Patching
CO28/8	Cement Hill	0.00	0.53	0.53	Ditching
CO28/8	Cement Mill Road	0.00	0.53	0.53	Mowing
CO28/8	Cement Mill Rd	0.00	0.53	0.53	Patching
CO28/9	Grace Cabin Road	0.00	1.38	1.38	Mowing
CO28/9	Grace Cabin Rd	0.00	1.14	1.14	Patching
CO3	Tasker / Canter Cutoff	0.00	2.10	2.10	Ditching
CO3	Tasker Road	0.00	2.10	2.10	Mowing
CO3	Tasker Rd	0.00	2.10	2.10	Patching
CO4	Pinnacle	0.00	8.23	8.23	Ditching
CO4	Pinnacle	8.23	9.49	1.26	Ditching
CO4	Pinnacle Road	0.00	9.49	9.49	Mowing
CO4	Pinnacle Rd	0.00	9.19	9.19	Patching
CO4/1	Bosley Road	0.00	3.67	3.67	Mowing
CO4/1	Bosley Rd	0.00	3.67	3.67	Patching
CO4/2	Green	0.00	0.19	0.19	Ditching
CO4/2	Green Road	0.00	0.19	0.19	Mowing
CO42/1	Stullenberger	0.00	1.59	1.59	Ditching
CO42/1	Stullenburger Road	0.00	1.59	1.59	Mowing
CO42/1	Stullenburger Rd	0.00	0.24	0.24	Patching
CO42/1	Stullen barger Rd	0.24	1.59	1.35	Stabilization
CO42/2	Shadylane	0.00	3.50	3.50	Ditching
CO42/2	Shady Lane	0.00	3.50	3.50	Mowing
CO42/2	Shady Lane Rd	0.00	0.73	0.73	Patching
CO42/3	Paughtown Road	0.00	1.92	1.92	Ditching
CO42/3	Paugh Town Road	0.00	1.92	1.92	Mowing
CO42/3	Paugh Town Rd	0.00	1.18	1.18	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO42/4	Sulphur to Nethkin	0.00	2.39	2.39	Ditching
CO42/4	Sulphur to Nethkin Road	0.00	2.39	2.39	Mowing
CO42/4	Sulphur to Nethkin Rd	0.00	0.26	0.26	Patching
CO42/5	Bane Cutoff	0.00	2.08	2.08	Ditching
CO42/5	Sulphur to Hartmansville Road	0.00	2.08	2.08	Mowing
CO42/5	Sulphur to Hartmansville Rd	0.00	2.08	2.08	Patching
CO42/6	Cemetey	0.00	0.51	0.51	Ditching
CO42/6	Cemetary Road (Elk Garden)	0.00	0.44	0.44	Mowing
CO42/6	Cemetary Rd in Elk Garden	0.00	0.44	0.44	Patching
CO46/1	Old WV 46	0.00	1.26	1.26	Ditching
CO46/1	Old WV 46 Road	0.00	1.26	1.26	Mowing
CO46/1	Old WV 46 Rd	0.00	1.04	1.04	Patching
CO46/1	Old WV 46 Rd	0.00	1.00	1.00	Stabilization
CO46/10	Cabin Run	0.00	1.49	1.49	Ditching
CO46/10	Cabin Run	0.00	1.49	1.49	Ditching
CO46/10	Cabin Run	0.00	1.49	1.49	Ditching
CO46/10	Cabin Run	0.00	1.49	1.49	Ditching
CO46/10	Staggs Road	0.00	1.49	1.49	Mowing
CO46/10	Staggs Rd	0.00	1.49	1.49	Patching
CO46/11	Fountain - Reapproach	0.00	0.35	0.35	Ditching
CO46/11	Fountain	0.00	0.35	0.35	Ditching
CO46/11	Fountain Road	0.00	0.35	0.35	Mowing
CO46/11	Fountain Rd	0.00	0.35	0.35	Patching
CO46/12	Charles Dermer	0.00	1.43	1.43	Ditching
CO46/12	Chas. Deremer Road	0.00	1.43	1.43	Mowing
CO46/12	Chas. Deremer Rd	0.00	1.43	1.43	Patching
CO46/13	Mill Run	0.00	1.76	1.76	Ditching
CO46/13	Mill Run Road	0.00	1.76	1.76	Mowing
CO46/13	Mill Run Rd	0.00	1.76	1.76	Stabilization
CO46/14	Ed Oates	0.00	1.81	1.81	Ditching
CO46/14	Ed Oates	0.00	1.81	1.81	Ditching
CO46/14	ED Oats Road	0.00	1.81	1.81	Mowing
CO46/14	Ed Oats Rd	0.00	1.81	1.81	Patching
CO46/15	Rinehart	0.00	1.31	1.31	Ditching
CO46/15	Rinehart	0.00	1.31	1.31	Ditching
CO46/15	Rinehart Run Road	0.00	1.31	1.31	Mowing
CO46/15	Rinhart Run Road	0.00	0.84	0.84	Patching
CO46/16	Meyers Run	0.00	0.62	0.62	Ditching
CO46/16	Run Road	0.00	0.62	0.62	Mowing
CO46/17	Old WV 46	0.00	0.66	0.66	Mowing
CO46/17	Old WV 46	0.00	0.60	0.60	Patching
CO46/18	Old WV 46 Spur	0.00	0.08	0.08	Mowing
CO46/18	Old WV 46 Spur	0.00	0.08	0.08	Patching
CO46/2	Barnum	0.00	2.51	2.51	Ditching
CO46/2	Barnum Road	0.00	2.51	2.51	Mowing
CO46/2	Montgomery Run Road	0.00	0.17	0.17	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO46/2	Barnum Rd	0.00	2.51	2.51	Patching
CO46/21	Old Rt 46 at Beryl	0.00	0.02	0.02	Mowing
CO46/23	Old Rt 46 Loop	0.00	0.15	0.15	Mowing
CO46/24	Reeves Road Extention	0.00	0.02	0.02	Mowing
CO46/25	Foreback	0.00	0.83	0.83	Ditching
CO46/25	Foreback	0.00	0.83	0.83	Ditching
CO46/25	Foreback Road	0.00	0.83	0.83	Mowing
CO46/25	Foreback Rd	0.00	0.83	0.83	Patching
CO46/3	Montgomery Run	0.00	0.19	0.19	Ditching
CO46/3	Montgomery Run Road	0.00	0.19	0.19	Mowing
CO46/4	Green Mt	0.00	4.93	4.93	Ditching
CO46/4	Green Mountain Road	0.00	4.93	4.93	Mowing
CO46/4	Green Mountain Rd	0.00	4.93	4.93	Patching
CO46/5	Jake Staggers	0.00	3.43	3.43	Ditching
CO46/5	Jake Staggers	0.00	3.43	3.43	Ditching
CO46/5	Jack Staggers Road	0.00	3.43	3.43	Mowing
CO46/5	Jake Staggers Rd	0.00	3.43	3.43	Patching
CO46/6	Reeves - Rawlings	0.00	0.96	0.96	Ditching
CO46/6	Reeves (Rawlings) Road	0.00	0.96	0.96	Mowing
CO46/6	Reeves (Rawlings) Rd	0.00	0.96	0.96	Patching
CO46/7	Horseshoe	0.00	4.57	4.57	Ditching
CO46/7	Horseshoe Road	0.00	4.57	4.57	Mowing
CO46/7	Horseshoe Rd	0.00	4.57	4.57	Patching
CO46/8	Cemetary Road	0.00	1.05	1.05	Mowing
CO46/8	Cemetary Rd	0.00	1.05	1.05	Patching
CO46/9	Susan Fleek	0.00	2.36	2.36	Ditching
CO46/9	Susan Fleek	0.00	2.36	2.36	Ditching
CO46/9	Susan Fleek Road	0.00	2.05	2.05	Mowing
CO46/9	Susan Fleek Rd	0.00	2.05	2.05	Patching
CO5/1	Pancake Road	0.00	0.49	0.49	Mowing
CO5/1	Pancake	0.00	0.49	0.49	Patching
CO5/2	Laurel Dale Post Office	0.00	0.84	0.84	Ditching
CO5/2	Laurel Dale PO	0.00	0.84	0.84	Mowing
CO5/2	Laural Dale PO	0.00	0.84	0.84	Patching
CO50/1	Burgess Hollow	0.00	2.86	2.86	Ditching
CO50/1	Burgess Hollow Road	0.00	1.43	1.43	Mowing
CO50/1	Burgess Hollow Road	1.43	2.86	1.43	Mowing
CO50/1	Burgess Hollow Rd	0.00	0.49	0.49	Patching
CO50/1	Burgess Hollow	0.00	2.86	2.86	Stabilization
CO50/10	Arnold Mine Road	0.00	0.16	0.16	Ditching
CO50/10	Arnold Mine Road	0.00	0.16	0.16	Mowing
CO50/10	Arnold Mine Rd	0.00	0.16	0.16	Patching
CO50/2	Hersey Hollow	0.00	1.13	1.13	Ditching
CO50/2	Hershey Hollow Road	0.00	1.13	1.13	Mowing
CO50/2	Hershey Hollow Rd	0.00	1.13	1.13	Patching
CO50/3	Parrell Hollow	0.00	3.26	3.26	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO50/3	Parrell Hollow	0.00	3.26	3.26	Ditching
CO50/3	Perrell Hollow Road	0.00	3.26	3.26	Mowing
CO50/3	Perell Hollow Rd	0.00	3.26	3.26	Patching
CO50/4	Shirley Lane	0.00	3.42	3.42	Ditching
CO50/4	Shirley Lane	0.00	3.42	3.42	Ditching
CO50/4	Shirleys Lane Road	0.00	3.42	3.42	Mowing
CO50/4	Shirleys Lane Rd	0.00	3.42	3.42	Patching
CO50/5	Pisgah	0.65	0.00	0.65	Ditching
CO50/5	Pisgar Road	0.00	0.65	0.65	Mowing
CO50/5	Pisgar Rd	0.00	0.65	0.65	Patching
CO50/6	Cam Stickley	0.00	1.45	1.45	Ditching
CO50/6	Cam Stickley	0.00	1.45	1.45	Ditching
CO50/6	Cam Stickley Road	0.00	1.45	1.45	Mowing
CO50/6	Cam Stickley Rd	0.00	1.45	1.45	Patching
CO50/7	Cameron Orchard	0.00	0.52	0.52	Ditching
CO50/7	Cameron Orchard Road	0.00	0.52	0.52	Mowing
CO50/7	Cameron Orchard Rd	0.00	0.52	0.52	Patching
CO50/8	Ebert Road	0.00	1.66	1.66	Ditching
CO50/8	Ebert Road	0.00	1.66	1.66	Ditching
CO50/8	Ebert Road	0.00	1.66	1.66	Mowing
CO50/8	Ebert Rd	0.00	1.66	1.66	Patching
CO50/9	Rogers Road	0.00	1.71	1.71	Ditching
CO50/9	Rogers Road	0.00	1.71	1.71	Ditching
CO50/9	Rodgers Road	0.00	1.71	1.71	Mowing
CO50/9	Rodgers Rd	0.00	1.71	1.71	Patching
CO6	Graysons Gap	0.00	1.12	1.12	Ditching
CO6	Grayson Gap	1.12	3.04	1.92	Ditching
CO6	Graysons Gap Road	0.00	3.04	3.04	Mowing
CO6	Graysons Gap Rd	0.00	3.04	3.04	Patching
CO6/1	Penneroil	0.00	0.85	0.85	Ditching
CO6/1	Penneroil	0.85	4.53	3.68	Ditching
CO6/1	Penneroil Road	0.00	4.53	4.53	Mowing
CO6/1	Penneroil Rd	0.00	4.53	4.53	Patching
CO6/2	Nancy Hanks	0.00	0.42	0.42	Ditching
CO6/2	Nancy Hanks Road	0.00	0.42	0.42	Mowing
CO6/2	Nancy Hanks Rd	0.00	0.42	0.42	Patching
CO7/1	Hooker Hollow	0.00	2.01	2.01	Ditching
CO7/1	Hooker Hollow	0.00	2.01	2.01	Ditching
CO7/1	Hooker Hollow Road	0.00	2.01	2.01	Mowing
CO7/1	Hooker Hollow Rd	0.00	2.01	2.01	Patching
CO8	Waxler	0.00	5.70	5.70	Ditching
CO8	Waxler	0.00	5.70	5.70	Ditching
CO8	Waxler Road	5.7	11.41	5.71	Ditching
CO8	Waxler Road	0.00	7.31	7.31	Mowing
CO8	Waxler Road	7.31	11.41	4.10	Mowing
CO8	Waxler Road	0.00	7.31	7.31	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO8	Waxler Rd	7.31	11.41	4.10	Patching
CO8/1	Gerstell Hollow Road	0.00	1.90	1.90	Mowing
CO8/1	Gerstell	0.00	1.90	1.90	Stabilization
CO8/2	Industrail Loop	0.00	0.26	0.26	Ditching
CO8/2	Industrial Loop	0.00	0.26	0.26	Ditching
CO8/2	Industrial Loop Road	0.00	0.26	0.26	Mowing
CO8/2	Industrial Loop Road	0.00	0.26	0.26	Patching
CO8/3	Old Rt 8/2	0.00	0.15	0.15	Ditching
CO8/3	Old Rt 8/2	0.00	0.15	0.15	Ditching
CO8/3	Old County Route 8/2	0.00	0.15	0.15	Mowing
CO8/3	Old County Rd 8/2	0.00	0.03	0.03	Patching
CO8/4	Glass Plant	0.00	0.10	0.10	Ditching
CO8/4	Glass Plant	0.00	0.10	0.10	Ditching
CO8/4	Glass Plant Road	0.00	0.10	0.10	Mowing
CO8/4	Glass Plant Access Rd	0.00	0.10	0.10	Patching
CO8/5	Harlen Ritter Drive	0.00	0.55	0.55	Ditching
CO8/5	Harlen Ritter Drive	0.00	0.55	0.55	Ditching
CO8/5	Harlen Ridder Drive	0.00	0.55	0.55	Mowing
CO8/5	Harland Ridder Drive	0.00	0.55	0.55	Patching
CO9	Knobley /Upper 9	1.95	4.08	2.13	Ditching
CO9	Knobley / Upper 9	1.95	4.08	2.13	Ditching
CO9	Knobley / Upper 9	4.08	3.87	0.21	Ditching
CO9	Knobley / Middle 9	7.95	13.34	5.39	Ditching
CO9	Knobley / Middle 9	7.95	13.34	5.39	Ditching
CO9	Knobley Road	13.34	24.25	10.91	Ditching
CO9	Knobley Road	0.00	19.98	19.98	Mowing
CO9	Knobley Road	19.98	24.25	4.27	Mowing
CO9	Knobley Rd	0.00	19.96	19.96	Patching
CO9	Knobley Rd	19.98	24.25	4.27	Patching
CO9	Knobley / Upper 9	0.00	1.95	1.95	Ditching
CO9	Knobley /Upper 9	1.95	0.00	1.95	Ditching
CO9/1	Tuckers Ridge	0.00	2.82	2.82	Ditching
CO9/1	Tuckers Ridge	0.00	2.82	2.82	Ditching
CO9/1	Tucker Ridge Road	0.00	2.82	2.82	Mowing
CO9/1	Tucker Ridge Rd	0.00	2.82	2.82	Patching
CO9/2	Double Cribbs	0.00	5.06	5.06	Ditching
CO9/2	Double Cribbs	0.00	5.06	5.06	Ditching
CO9/2	Double Cribbs	0.00	5.06	5.06	Mowing
CO9/2	Double Cribbs (Mike's Run)	0.00	2.43	2.43	Patching
CO9/3	Reeves Road	0.00	1.81	1.81	Ditching
CO9/3	Reeves Road	0.00	1.81	1.81	Mowing
CO9/3	Reeves Road	0.00	1.81	1.81	Patching
CO9/4	Dirty Foot	0.00	1.68	1.68	Ditching
CO9/4	Dirty Foot Road	0.00	1.68	1.68	Mowing
CO9/4	Dirty Foot Rd	0.00	1.68	1.68	Patching
CO9/6	Short Gap Road	0.00	0.09	0.09	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO9/6	Short Gap Rd	0.00	0.09	0.09	Patching
CO9/7	Bible Church Road	0.00	0.23	0.23	Mowing
CO9/7	Bible Church Rd	0.00	0.23	0.23	Patching
HA901	Sunrise Drive	0.00	1.15	1.15	Ditching
HA901	Sunrise Hights	0.00	1.15	1.15	Mowing
HA901	Sunrise Heights Rd	0.00	1.15	1.15	Patching
HA902	Spruce Street	0.00	0.30	0.30	Ditching
HA902	Spruce Street	0.00	0.30	0.30	Mowing
HA903	Tram Road	0.00	0.11	0.11	Ditching
HA903	Tram Road	0.00	0.11	0.11	Mowing
HA903	Ash Spring Run	0.00	0.70	0.70	Stabilization
HA904	Megans Lane	0.00	1.00	1.00	Ditching
HA904	Megans Lane	0.00	1.00	1.00	Ditching
HA904	Megans Lane	0.00	1.00	1.00	Mowing
HA904	Megans Lane	0.00	0.07	0.07	Patching
HA905	Linden Drive	0.00	0.25	0.25	Ditching
HA905	Lindon Drive	0.00	0.50	0.50	Mowing
HA905	Lindon Drive	0.00	0.25	0.25	Patching
HA906	Ash Spring Run Road	0.00	0.70	0.70	Mowing
HA907	Hidden View Estates	0.00	0.25	0.25	Mowing
HA907	Hidden View Estates	0.00	0.25	0.25	Patching
HA908	Lone Oak Lane	0.00	0.15	0.15	Mowing
HA908	Lone Oak Lane	0.00	0.15	0.15	Patching
HA909	The White Way Road	0.00	0.25	0.25	Mowing
HA909	White Way	0.00	0.25	0.25	Stabilization
HA910	Long View Drive	0.00	1.13	1.13	Ditching
HA910	Longveiw Drive	0.00	1.13	1.13	Ditching
HA910	Longview Drive	0.00	1.13	1.13	Mowing
HA910	Longview Drive	0.00	1.13	1.13	Stabilization
HA912	Cinclare	0.00	1.33	1.33	Ditching
HA912	Sinclair Road	0.00	1.33	1.33	Mowing
HA913	Dawn Drive	0.00	0.58	0.58	Ditching
HA913	Dawn Drive	0.00	0.58	0.58	Mowing
HA913	Dawn Drive	0.00	0.58	0.58	Patching
HA914	Diane Drive	0.00	0.17	0.17	Ditching
HA914	Diane Drive	0.00	0.17	0.17	Mowing
HA914	Diane Drive	0.00	0.17	0.17	Patching
HA915	Ronda Drive	0.00	0.22	0.22	Ditching
HA915	Ronda Drive	0.00	0.22	0.22	Mowing
HA915	Ronda Drive	0.00	0.22	0.22	Patching
HA916	Marle Drive	0.00	0.12	0.12	Ditching
HA916	Marie Drive	0.00	0.12	0.12	Mowing
HA916	Marie Drive	0.00	0.12	0.12	Patching
HA917	Patterson Creek Drive	0.00	0.31	0.31	Ditching
HA917	Pattersons Creek Drive	0.00	0.31	0.31	Mowing
HA918	Champwood	0.00	0.90	0.90	Ditching

Route	Local Name	BMP	EMP	Length	Activity
HA918	Champwood	0.00	0.90	0.90	Ditching
HA918	Champwood Lane	0.00	0.90	0.90	Mowing
HA919	Old Hickory	0.00	0.20	0.20	Ditching
HA919	Old Hickory Road	0.00	0.20	0.20	Mowing
HA920	Country Mile	0.00	0.88	0.88	Ditching
HA920	Country Mile	0.00	0.88	0.88	Ditching
HA920	Country Mile Road	0.00	0.88	0.88	Mowing
HA920	Country Mile Rd	0.00	0.88	0.88	Stabilization
HA921	Water Street	0.00	0.12	0.12	Ditching
HA921	Water Street (Fort Ashby Area)	0.00	0.12	0.12	Mowing
HA921	Water Street (Ft. Ashby)	0.00	0.12	0.12	Patching
HA930	Walbash	0.00	1.00	1.00	Ditching
HA930	Walbash Road	0.00	1.00	1.00	Mowing
HA931	See View Drive	0.00	0.41	0.41	Ditching
HA931	See View Drive	0.00	0.41	0.41	Ditching
HA931	See View Drive	0.00	0.41	0.41	Mowing
HA931	See View Dr	0.00	0.41	0.41	Stabilization
HA932	Black Alley	0.00	0.05	0.05	Mowing
HA932	Black Alley	0.00	0.05	0.05	Stabilization
HA933	Clearview Avenue	0.00	0.21	0.21	Ditching
HA933	Clearview Drive	0.00	0.21	0.21	Mowing
HA934	Ross Alley	0.00	0.10	0.10	Ditching
HA934	Ross Alley	0.00	0.10	0.10	Mowing
HA935	Mill Alley	0.00	0.11	0.11	Mowing
HA935	Mill Alley	0.00	0.11	0.11	Stabilization
HA937	Vinetta Lane	0.00	0.22	0.22	Ditching
HA937	Vinetta Lane	0.00	0.22	0.22	Mowing
HA937	Vinetta Ln	0.00	0.22	0.22	Stabilization
HA938	Mount Olive Church Road	0.00	0.10	0.10	Mowing
HA939	Sun Country	0.00	0.27	0.27	Ditching
HA939	Sun Country	0.00	0.27	0.27	Ditching
HA939	Sun Country Drive	0.00	0.27	0.27	Mowing
HA939	Sun Country Drive	0.00	0.27	0.27	Patching
HA940	Beal Road	0.00	0.13	0.13	Mowing
HA942	Hilltop Drive	0.00	0.11	0.11	Ditching
HA942	Hilltop Drive	0.00	0.11	0.11	Ditching
HA942	Hill Top Drive	0.00	0.11	0.11	Mowing
HA943	O'Neals Run Road	0.00	0.08	0.08	Ditching
HA943	Oniel Run	0.00	0.08	0.08	Ditching
HA943	Oniel Run Road	0.00	0.08	0.08	Mowing
HA943	Oneal Run Rd	0.00	0.08	0.08	Stabilization
HA944	Georgetown Farm Road	0.00	0.67	0.67	Ditching
HA944	Georgetown Farm Road	0.00	0.67	0.67	Ditching
HA944	Georgetown Farm Road	0.00	0.67	0.67	Mowing
HA944	George town Farm Rd	0.00	0.67	0.67	Stabilization
HA945	Greenwood Subdivision	0.00	0.89	0.89	Ditching

Route	Local Name	BMP	EMP	Length	Activity
HA945	Greenwood Road	0.00	0.86	0.86	Mowing
HA946	Turkeybird Lane	0.00	0.18	0.18	Ditching
HA946	Turkey Bird Lane	0.00	0.18	0.18	Mowing
HA947	Towhee Hollow	0.00	0.13	0.13	Ditching
HA947	Tawhee Hollow Road	0.00	0.13	0.13	Mowing
HA948	Hoot Owl Lane	0.00	0.04	0.04	Ditching
HA948	Hoot Owl Hollow Road	0.00	0.04	0.04	Mowing
HA949	Screech Owl Lane	0.00	0.34	0.34	Ditching
HA949	Screech Owl Lane	0.00	0.34	0.34	Mowing
HA950	Bluejay Hollow	0.00	0.37	0.37	Ditching
HA950	Blue Jay Hollow Road	0.00	0.37	0.37	Mowing
HA953	Maple Hollow	0.00	0.21	0.21	Ditching
HA953	Maple Hollow	0.00	0.21	0.21	Ditching
HA953	Maple Hollow Road	0.00	0.21	0.21	Mowing
HA953	Maple Hollow	0.00	0.21	0.21	Stabilization
HA954	Carolina Avenue	0.00	0.15	0.15	Mowing
HA954	Carolina Avenue	0.00	0.15	0.15	Patching
HA955	Clen Echo Road	0.00	1.73	1.73	Mowing
HA955	Glen Echo Rd	0.00	1.73	1.73	Stabilization
HA957	Florida Avenue	0.00	0.14	0.14	Mowing
HA957	Florida	0.00	0.14	0.14	Patching
HA958	Georgia Avenue	0.00	0.15	0.15	Mowing
HA958	Georgia Avenue	0.00	0.15	0.15	Patching
HA960	Cumberland Street	0.00	0.29	0.29	Ditching
HA960	Cumberland Street	0.00	0.29	0.29	Mowing
HA961	Tucker Street	0.00	0.03	0.03	Mowing
HA961	Tucker St	0.00	0.03	0.03	Stabilization
HA962	Morgan Street	0.00	0.29	0.29	Mowing
HA963	Wagoner Road	0.00	0.75	0.75	Mowing
HA963	Wagoner rd	0.00	0.75	0.75	Stabilization
HA964	Yellowbrick Road	0.00	0.36	0.36	Mowing
HA965	Detrick Road	0.00	0.46	0.46	Mowing
HA965	Detrick Rd	0.00	0.46	0.46	Stabilization
HA966	Charles Street	0.00	0.43	0.43	Mowing
HA967	Heavner Street	0.00	0.87	0.87	Ditching
HA967	Heavner Drive	0.00	0.87	0.87	Mowing
HA967	Heavner Dr	0.00	0.87	0.87	Patching
HA968	Ridge Road	0.00	0.29	0.29	Ditching
HA968	Ridge Road	0.00	0.29	0.29	Mowing
HA968	Ridge Rd Heavener	0.00	0.69	0.69	Stabilization
HA969	Forrest Drive	0.00	0.31	0.31	Ditching
HA969	Forest Drive	0.00	0.31	0.31	Mowing
HA969	Forest Dr	0.00	0.31	0.31	Patching
US220	Cut off	8.36	10.97	2.61	Ditching
US220	New Creek Highway	10.97	15.11	4.14	Ditching
US220	New Creek Highway	8.36	15.11	6.75	Mowing

Route	Local Name	BMP	EMP	Length	Activity
US220	US 220	0.00	6.75	6.75	Patching
US220	US 220	8.36	15.11	6.75	Patching
US50	Northwestern Turnpike	0.00	0.25	0.25	Ditching
US50	Northwestern Turnpike	0.25	1.80	1.55	Ditching
US50	Northwestern Turnpike	1.55	4.13	2.58	Ditching
US50	Northwestern Turnpike	4.13	8.00	3.87	Ditching
US50	Northwestern Turnpike	8.00	10.62	2.62	Ditching
US50	Northwestern Turnpike	10.62	18.24	7.62	Ditching
US50	Northwestern Turnpike	18.42	20.76	2.34	Ditching
US50	Northwestern Turnpike	18.42	20.76	2.34	Ditching
US50	Northwestern Turnpike	20.76	21.02	0.26	Ditching
US50	Northwestern Turnpike	20.76	21.02	0.26	Ditching
US50	Northwestern Turnpike	8.00	21.02	13.02	Mowing
US50	US 50	0.00	13.02	13.02	Patching
US50	Northwestern Turnpike	0.00	8.00	8.00	Patching
US50	Northwestern Turnpike	8.00	21.02	13.02	Patching
US50	Northwestern Turnpike	0.00	8.00	8.00	Mowing
WV28	Veterans Highway	0.00	2.97	2.97	Ditching
WV28	Frankfort Highway	7.54	13.55	6.01	Ditching
WV28	Frankfort Highway	0.00	13.55	13.55	Mowing
WV28	Veteran's Memorial Highway	0.00	2.97	2.97	Mowing
WV28	Frankfort Highway	0.00	13.55	13.55	Patching
WV28	Veteran's Memorial Highway	0.00	2.97	2.97	Patching
WV42	Elk Garden Highway	3.38	5.59	2.21	Ditching
WV42	Elk Garden Highway	5.59	10.79	5.20	Ditching
WV42	Elk Garden Highway	3.38	10.86	7.48	Mowing
WV42	Elk Garden Highway	3.38	10.86	7.48	Patching
WV46	Shaw Road	0.00	12.13	12.13	Ditching
WV46	Shaw Road	15.38	21.00	5.62	Ditching
WV46	Fort Ashby Highway	21.00	35.53	14.53	Ditching
WV46	Shaw Road	0.00	12.43	12.43	Mowing
WV46	Piedmont Road/Fort Ashby Road	14.44	29.52	15.08	Mowing
WV46	Fort Ashby Road	29.52	35.53	6.01	Mowing
WV46	Shaw Rd	0.00	12.43	12.43	Patching
WV46	WV 46	0.06	14.87	14.81	Patching
WV46	WV 46	14.44	29.52	15.08	Patching
WV46	Fort Ashby Road	29.52	35.53	6.01	Patching
WV93	Laurel Dale Road	0.00	3.68	3.68	Ditching
WV93	Laurel Dale Road	0.00	3.68	3.68	Mowing
WV93	Laurel Dale Road	0.00	2.19	2.19	Mowing
WV93	WV 93	0.00	3.68	3.68	Patching
WV93	WV 93	0.00	3.68	3.68	Patching
WV956	Rocket Center Road	0.00	4.18	4.18	Ditching
WV956	Rocket Center Road	0.00	4.18	4.18	Mowing
WV956	Rocket Center Road	0.00	4.18	4.18	Patching
WV972	WV 972	0.00	2.19	2.19	Patching

Route	Local Name	BMP	EMP	Length	Activity
WV972	WV 972	0.00	2.19	2.19	Patching

403.67 Mowing

454.12 Ditching

387.98 Patching