

Route	Local Name	BMP	EMP	Length	Activity
CO23	Stone Church Rd	0.00	6.16	6.16	Ditching
CO23	Stone Church Rd	0.00	6.16	6.16	Mowing
CO23	Stone Church Rd	0.00	6.16	6.16	Patching
CO23/1	Walnut Grove	0.00	0.42	0.42	Ditching
CO23/1	Walnut Grove	0.00	0.42	0.42	Mowing
CO23/1	Walnut Grove	0.00	0.42	0.42	Patching
CO23/5	Cedar Rocks Road	0.00	2.44	2.44	Ditching
CO23/5	Cedar Rocks Road	0.00	2.44	2.44	Mowing
CO23/5	Cedar Rocks Road	0.00	2.44	2.44	Patching
CO23/6	Maple Davis Road	0.00	0.76	0.76	Ditching
CO23/6	Maple Davis Road	0.00	0.76	0.76	Mowing
CO23/6	Maple Davis Road	0.00	0.76	0.76	Patching
CO23/7	Clifton Heights Road	0.00	1.07	1.07	Ditching
CO23/7	Clifton Heights Road	0.00	1.07	1.07	Mowing
CO23/7	Clifton Heights Road	0.00	1.07	1.07	Patching
CO39	Middle Creek	0.00	4.10	4.10	Ditching
CO39	Middle Creek	0.00	4.10	4.10	Mowing
CO39	Middle Creek	0.00	4.10	4.10	Patching
CO39/4	Stulphire Road	0.00	2.07	2.07	Ditching
CO39/4	Stulphire Road	0.00	2.07	2.07	Mowing
CO39/4	Stulphire Road	0.00	2.07	2.07	Patching
CO39/5	Parks	0.00	1.94	1.94	Ditching
CO39/5	Parks	0.00	1.94	1.94	Mowing
CO39/5	Parks	0.00	1.94	1.94	Patching
CO39/7	Bear Rock Road	0.00	1.07	1.07	Ditching
CO39/7	Bear Rock Road	0.00	1.07	1.07	Mowing
CO39/7	Bear Rock Road	0.00	1.07	1.07	Patching
CO40/4	Valley Grove Road	0.00	1.09	1.09	Ditching
CO40/4	Valley Grove Road	0.00	1.09	1.09	Mowing
CO40/4	Valley Grove Road	0.00	1.09	1.09	Patching
CO41	Dallas Pike	0.00	3.68	3.68	Ditching
CO41	Dallas Pike	0.00	3.68	3.68	Mowing
CO41	Dallas Pike	0.00	3.68	3.68	Patching
CO41/1	McCutcheon	0.00	2.32	2.32	Ditching
CO41/1	McCutcheon	0.00	2.32	2.32	Mowing
CO41/1	McCutcheon	0.00	2.32	2.32	Patching
CO41/3	West Alexander road	0.00	3.81	3.81	Ditching
CO41/3	West Alexander road	0.00	3.81	3.81	Mowing
CO41/3	West Alexander road	0.00	3.81	3.81	Patching
CO41/4	Sample	0.00	2.32	2.32	Ditching
CO41/4	Sample	0.00	2.32	2.32	Mowing
CO41/4	Sample	0.00	2.32	2.32	Patching
CO41/5	Cruzer	0.00	1.09	1.09	Ditching
CO41/5	Cruzer	0.00	1.09	1.09	Mowing
CO41/5	Cruzer	0.00	1.09	1.09	Patching
CO41/8	Idustrial Park	0.00	0.95	0.95	Ditching

Route	Local Name	BMP	EMP	Length	Activity
CO41/8	Idustrial Park	0.00	0.95	0.95	Mowing
CO41/8	Idustrial Park	0.00	0.95	0.95	Patching
CO41/9	Fort Henry	0.00	2.00	2.00	Ditching
CO41/9	Fort Henry	0.00	2.00	2.00	Mowing
CO41/9	Fort Henry	0.00	2.00	2.00	Patching
CO43	Dallas Pike	0.00	2.98	2.98	Ditching
CO43	Dallas Pike	0.00	2.98	2.98	Mowing
CO43	Dallas Pike	0.00	2.98	2.98	Patching
CO7/6	McCulloch road	0.00	0.56	0.56	Mowing
CO7/9	Longvue acres road	0.00	0.56	0.56	Mowing
CO8	Chapl Hill	0.00	4.81	4.81	Mowing
CO8	Chaple Hill	0.00	4.81	4.81	Patching
HA906	Chambers lane	0.00	0.43	0.43	Mowing
HA907	Highland av	0.00	0.25	0.25	Mowing
HA909	Hillcrest	0.00	0.27	0.27	Mowing
HA910	Merrymount	0.00	1.02	1.02	Mowing
HA911	County farm	0.00	1.00	1.00	Mowing
HA912	Steep hill	0.00	0.34	0.34	Mowing
WV2	WV2	0.00	9.28	9.28	Mowing
WV88	WV88	0.00	14.00	14.00	Mowing

72.79 Mowing
40.27 Ditching
45.08 Patching
0.00 Stabilization