

| Route | Local Name | BMP | EMP | Length | Activity |
|--------|--------------------------|------|------|--------|---------------|
| CO1 | North River Road | 0.00 | 8.79 | 8.79 | Ditching |
| CO1 | North River Road | 0.00 | 8.79 | 8.79 | Mowing |
| CO1 | North River Road | 0.00 | 8.79 | 8.79 | Patching |
| CO1/1 | Mt. Olive | 0.00 | 2.00 | 2.00 | Ditching |
| CO1/1 | Mt Olive | 0.00 | 6.00 | 6.00 | Mowing |
| CO1/1 | Mt Olive Road | 0.00 | 6.37 | 6.37 | Patching |
| CO1/2 | Bishop Road | 0.00 | 0.66 | 0.66 | Mowing |
| CO1/2 | clifford hollow | 0.00 | 0.66 | 0.66 | Stabilization |
| CO1/2 | Bishop Road | 0.00 | 0.66 | 0.66 | Ditching |
| CO1/3 | Skaggs Run/Lem Parks | 0.00 | 1.34 | 1.34 | Ditching |
| CO1/3 | Lem Parks & Upper Skaggs | 0.00 | 1.34 | 1.34 | Mowing |
| CO1/4 | Constable Hollow | 0.00 | 2.00 | 2.00 | Mowing |
| CO1/4 | constable hollow | 0.00 | 2.68 | 2.68 | Stabilization |
| CO1/4 | Constable Hollow | 0.00 | 2.68 | 2.68 | Mowing |
| CO1/5 | Skaggs Run | 0.00 | 3.14 | 3.14 | Ditching |
| CO1/5 | Skaggs Run | 0.00 | 3.14 | 3.14 | Mowing |
| CO1/5 | Skaggs Run | 0.00 | 3.14 | 3.14 | Stabilization |
| CO1/6 | Snarr Bridge | 0.00 | 0.76 | 0.76 | Mowing |
| CO1/7 | Hampshire Co Line | 0.00 | 0.13 | 0.13 | Mowing |
| CO10 | Welton Kessel | 0.00 | 8.50 | 8.50 | Ditching |
| CO10 | Rig Road | 0.00 | 8.52 | 8.52 | Mowing |
| CO10 | Rig Road | 0.00 | 4.96 | 4.96 | Mowing |
| CO10 | Rig Road | 0.00 | 8.52 | 8.52 | Mowing |
| CO10 | Rig Road | 0.00 | 5.00 | 5.00 | Patching |
| CO10 | Rig Road | 0.00 | 8.52 | 8.52 | Patching |
| CO10/1 | Frosty Hollow | 0.00 | 5.09 | 5.09 | Ditching |
| CO10/1 | Frosty Hollow Road | 0.00 | 5.09 | 5.09 | Mowing |
| CO10/1 | Frosty Hollow | 0.00 | 5.09 | 5.09 | Mowing |
| CO10/1 | Frosty Hollow | 2.61 | 5.09 | 2.48 | Patching |
| CO10/2 | River Road | 0.00 | 4.01 | 4.01 | Mowing |
| CO10/2 | River Road | 0.00 | 4.01 | 4.01 | Mowing |
| CO10/3 | Hutter Road | 0.00 | 7.15 | 7.15 | Ditching |
| CO10/3 | Hutter Road | 0.00 | 6.00 | 6.00 | Ditching |
| CO10/3 | Hutter Road | 6.00 | 7.15 | 1.15 | Ditching |
| CO10/3 | Hutter Road | 0.00 | 7.37 | 7.37 | Mowing |
| CO10/3 | Hutter Road | 0.00 | 7.37 | 7.37 | Mowing |
| CO10/3 | Hutter Road | 0.00 | 7.15 | 7.15 | Patching |
| CO10/3 | Hutter Road | 3.00 | 4.00 | 1.00 | Ditching |
| CO10/4 | Darlington School | 0.00 | 2.36 | 2.36 | Mowing |
| CO10/4 | Darlington School | 0.00 | 2.36 | 2.36 | Mowing |
| CO10/4 | Darlington School | 0.00 | 2.36 | 2.36 | Patching |
| CO10/5 | Walnut Bottom | 0.00 | 5.95 | 5.95 | Mowing |
| CO10/5 | Walnut Bottom | 0.00 | 5.95 | 5.95 | Mowing |
| CO10/5 | Walnut Bottom | 0.00 | 5.95 | 5.95 | Patching |
| CO10/5 | Walnut Bottom | 0.00 | 2.50 | 2.50 | Ditching |
| CO10/6 | Turkey Mtn | 0.00 | 1.00 | 1.00 | Ditching |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------------|-------------------|------------|------------|---------------|-----------------|
| CO10/6 | Turkey Mtn | 0.00 | 2.19 | 2.19 | Ditching |
| CO10/6 | Turkey Mountain | 0.00 | 2.19 | 2.19 | Mowing |
| CO10/6 | Turkey Mountain | 0.00 | 2.19 | 2.19 | Mowing |
| CO10/6 | Turkey Mountain | 0.00 | 2.19 | 2.19 | Patching |
| CO10/7 | Snyderville Road | 0.00 | 1.80 | 1.80 | Ditching |
| CO10/7 | Snyderville Road | 0.00 | 1.80 | 1.80 | Mowing |
| CO10/7 | Snyderville Road | 0.00 | 1.80 | 1.80 | Mowing |
| CO10/9 | Rig West | 0.00 | 0.92 | 0.92 | Ditching |
| CO10/9 | Rig West | 0.00 | 0.92 | 0.92 | Mowing |
| CO10/9 | Rig West | 0.00 | 0.92 | 0.92 | Mowing |
| CO11 | Parker Hollow | 0.00 | 7.33 | 7.33 | Ditching |
| CO11 | Parker Hollow | 0.00 | 0.21 | 0.21 | Mowing |
| CO11 | Parker Hollow | 0.00 | 7.33 | 7.33 | Mowing |
| CO11/2 | Brants Teets | 0.00 | 2.00 | 2.00 | Ditching |
| CO11/2 | Brants - Teets | 0.00 | 2.17 | 2.17 | Mowing |
| CO11/3 | Cawell Hollow | 0.00 | 0.54 | 0.54 | Ditching |
| CO11/3 | Caldwell Hollow | 0.00 | 6.73 | 6.73 | Mowing |
| CO11/3 | Caldwell Hollow | 0.00 | 5.20 | 5.20 | Mowing |
| CO11/3 | Caldwell Hollow | 3.00 | 6.73 | 3.73 | Patching |
| CO11/3 | Cawell Hollow | 1.00 | 4.73 | 3.73 | Stabilization |
| CO11/4 | Terra Alta School | 0.00 | 3.00 | 3.00 | Ditching |
| CO11/4 | Terra Alta School | 0.00 | 3.00 | 3.00 | Mowing |
| CO11/4 | Terra Alta School | 0.00 | 3.00 | 3.00 | Mowing |
| CO11/4 | Terra Alta School | 0.00 | 3.00 | 3.00 | Stabilization |
| CO12 | Howards Lick | 4.00 | 12.00 | 8.00 | Patching |
| CO12 | LRSP Howards Lick | 0.00 | 6.00 | 6.00 | Ditching |
| CO12 | Howards Lick LRSP | 3.72 | 11.44 | 7.72 | Mowing |
| CO12 | Howards Lick Road | 12.00 | 16.00 | 4.00 | Mowing |
| CO12 | Howards Lick | 0.00 | 16.00 | 16.00 | Mowing |
| CO12/1 | Helmick Road Road | 0.00 | 4.32 | 4.32 | Ditching |
| CO12/1 | Helmick Rock Road | 0.00 | 4.34 | 4.34 | Mowing |
| CO12/1 | Helmick Rock | 0.00 | 2.00 | 2.00 | Stabilization |
| CO12/2 | Jenkins Hollow | 0.00 | 2.58 | 2.58 | Mowing |
| CO12/2 | Jenkins Hollow | 0.00 | 2.58 | 2.58 | Mowing |
| CO12/3 | Shenandoah Mtn | 0.00 | 4.08 | 4.08 | Ditching |
| CO12/3 | Shenandoah Mtn | 0.00 | 4.08 | 4.08 | Mowing |
| CO12/3 | Shenandoah Mtn | 0.00 | 4.08 | 4.08 | Stabilization |
| CO13 | Fisher Road | 0.00 | 1.32 | 1.32 | Mowing |
| CO14 | Dove Hollow | 0.00 | 10.05 | 10.05 | Mowing |
| CO14 | Dove Hollow | 0.00 | 10.00 | 10.00 | Patching |
| CO14 | Dove Hollow | 0.00 | 10.05 | 10.05 | Ditching |
| CO14 | Dove Hollow | 0.00 | 10.05 | 10.05 | Mowing |
| CO14/1 | Whetzel Hollow | 0.00 | 6.75 | 6.75 | Ditching |
| CO14/1 | Whetzel Hollow | 0.00 | 6.75 | 6.75 | Ditching |
| CO14/1 | Kimsey Run | 0.00 | 6.75 | 6.75 | Mowing |
| CO14/1 | Whetzel Hollow | 0.00 | 6.75 | 6.75 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|----------|--------------------------|------|-------|--------|---------------|
| CO15 | Cunningham Lane | 0.00 | 0.95 | 0.95 | Ditching |
| CO15 | Cunningham Lane | 0.00 | 2.96 | 2.96 | Mowing |
| CO15 | Cunningham Lane | 0.00 | 2.96 | 2.96 | Mowing |
| CO15 | Cunningham Lane | 0.00 | 2.96 | 2.96 | Patching |
| CO16 | Mill Gap - Thorne Bottom | 0.00 | 10.91 | 10.91 | Ditching |
| CO16 | Mill Gap - thorne Bottom | 0.00 | 10.91 | 10.91 | Mowing |
| CO16 | Mill Gap - Thorn Bottom | 0.00 | 10.91 | 10.91 | Mowing |
| CO16 | Mill Gap- Thorne Bottom | 0.00 | 1.10 | 1.10 | Patching |
| CO16/1 | Settler's Valley Way | 0.00 | 0.42 | 0.42 | Ditching |
| CO16/1 | Settlers Valley Way | 0.00 | 0.42 | 0.42 | Stabilization |
| CO18 | Crab Run Road | 0.00 | 5.36 | 5.36 | Mowing |
| CO18 | Crab Run | 0.00 | 5.36 | 5.36 | Mowing |
| CO18 | Crab Run | 0.00 | 5.36 | 5.36 | Patching |
| CO18/1 | Cullers Run | 0.00 | 3.53 | 3.53 | Ditching |
| CO18/1 | Culler's Run | 0.00 | 3.53 | 3.53 | Mowing |
| CO18/1 | Cullers Run | 0.00 | 3.53 | 3.53 | Mowing |
| CO18/1 | Culler's Run | 0.00 | 3.53 | 3.53 | Patching |
| CO18/2 | Crab Run- VA Line | 0.00 | 1.23 | 1.23 | Ditching |
| CO18/2 | Crab Run- VA Line | 0.00 | 1.23 | 1.23 | Ditching |
| CO18/2 | Crab Run- VA Line | 0.00 | 0.92 | 0.92 | Mowing |
| CO2 | Old Fields Road | 0.00 | 6.00 | 6.00 | Ditching |
| CO2 | Old Fields Road | 0.00 | 9.74 | 9.74 | Mowing |
| CO2 | Old Fields Road | 0.00 | 9.74 | 9.74 | Mowing |
| CO2 | Old Fields Road | 0.00 | 9.74 | 9.74 | Patching |
| CO2 | Old 220 Old Fields Road | 6.00 | 8.00 | 2.00 | Ditching |
| CO2/1 | Flats Mtn View | 3.00 | 3.71 | 0.71 | Ditching |
| CO2/1 | Flats Mtn View | 0.00 | 4.66 | 4.66 | Mowing |
| CO2/1 | Flats Mt View | 0.00 | 4.66 | 4.66 | Mowing |
| CO2/1 | Flats- Mt View | 0.00 | 4.66 | 4.66 | Patching |
| CO2/2 | Shockey Road | 0.00 | 1.53 | 1.53 | Ditching |
| CO2/2 | Shockey Road | 0.00 | 1.53 | 1.53 | Mowing |
| CO2/2 | Shockey Road | 0.00 | 1.53 | 1.53 | Mowing |
| CO2/2 | Shockey Road | 0.00 | 1.53 | 1.53 | Patching |
| CO20 | Upper Cove Road | 0.00 | 5.00 | 5.00 | Mowing |
| CO20 | Upper Cove | 0.00 | 5.00 | 5.00 | Mowing |
| CO20 | Upper Cove | 0.00 | 3.00 | 3.00 | Patching |
| CO20/2 | Old Mill Road | 0.00 | 0.96 | 0.96 | Mowing |
| CO20/2 | Mill Road | 0.00 | 0.96 | 0.96 | Mowing |
| CO20/3 | Basore Road | 0.00 | 2.58 | 2.58 | Ditching |
| CO20/3 | Basore Road | 0.00 | 2.58 | 2.58 | Mowing |
| CO220/1 | Mt. View | 0.00 | 0.70 | 0.70 | Ditching |
| CO220/1 | Mountain View | 0.00 | 2.28 | 2.28 | Mowing |
| CO220/1 | Mtn View Road | 0.00 | 2.28 | 2.28 | Mowing |
| CO220/11 | American Woodmark Access | 0.00 | 0.11 | 0.11 | Mowing |
| CO220/12 | Town Run Road | 0.00 | 0.28 | 0.28 | Mowing |
| CO220/13 | Ogden Farm Road | 0.00 | 1.70 | 1.70 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------------|----------------------|------------|------------|---------------|-----------------|
| CO220/13 | Ogden Farms | 0.00 | 1.70 | 1.70 | Mowing |
| CO220/13 | Ogden Farms | 0.00 | 1.70 | 1.70 | Patching |
| CO220/14 | Southerly Drive | 0.00 | 0.42 | 0.42 | Mowing |
| CO220/15 | Howard Sions Road | 0.00 | 1.25 | 1.25 | Mowing |
| CO220/15 | Howard Sions Road | 0.00 | 1.25 | 1.25 | Mowing |
| CO220/18 | Tanglewood Drive | 0.00 | 0.54 | 0.54 | Mowing |
| CO220/19 | Tanglewood Court | 0.00 | 0.12 | 0.12 | Mowing |
| CO220/2 | Markwood Road | 0.00 | 2.48 | 2.48 | Mowing |
| CO220/2 | Markwood Road | 0.00 | 2.48 | 2.48 | Mowing |
| CO220/2 | JC Markwood Road | 0.00 | 2.48 | 2.48 | Mowing |
| CO220/2 | Markwood Road | 0.00 | 2.48 | 2.48 | Patching |
| CO220/20 | Greenwood Drive | 0.00 | 0.24 | 0.24 | Ditching |
| CO220/20 | Greenwood Drive | 0.00 | 0.24 | 0.24 | Mowing |
| CO220/21 | Dogwood Drive | 0.00 | 0.10 | 0.10 | Mowing |
| CO220/22 | Walnut Drive | 0.00 | 0.10 | 0.10 | Mowing |
| CO220/4 | Jenkins Hollow | 0.00 | 2.60 | 2.60 | Ditching |
| CO220/4 | Jenkins Run | 0.00 | 2.69 | 2.69 | Mowing |
| CO220/4 | Jenkins Run Road | 0.00 | 2.69 | 2.69 | Mowing |
| CO220/5 | Durgon Hollow | 0.00 | 1.92 | 1.92 | Ditching |
| CO220/5 | Durgon Run Road | 0.00 | 1.92 | 1.92 | Mowing |
| CO220/5 | Durgon Run Road | 0.00 | 1.92 | 1.92 | Mowing |
| CO220/5 | Durgon Road | 0.00 | 1.92 | 1.92 | Patching |
| CO220/6 | Cold Spring Road | 0.00 | 1.20 | 1.20 | Ditching |
| CO220/6 | Cold Spring Road | 0.00 | 1.68 | 1.68 | Mowing |
| CO220/6 | Cold Spring Hollow | 0.00 | 1.68 | 1.68 | Mowing |
| CO220/7 | Church Road | 0.00 | 0.56 | 0.56 | Ditching |
| CO220/7 | Church- Hamp Line | 0.00 | 0.56 | 0.56 | Mowing |
| CO220/7 | Chruch- Hamp CO Line | 0.00 | 0.56 | 0.56 | Mowing |
| CO220/8 | Fish Pond Road | 1.00 | 6.63 | 5.63 | Ditching |
| CO220/8 | Fish Pond | 0.00 | 6.63 | 6.63 | Mowing |
| CO220/8 | Fish Pond Road | 6.10 | 0.10 | 6.00 | Mowing |
| CO220/8 | Fish Pond | 2.30 | 4.20 | 1.90 | Stabilization |
| CO23/1 | Powder Spring | 0.00 | 2.40 | 2.40 | Ditching |
| CO23/1 | Powder Spring Hollow | 0.00 | 2.40 | 2.40 | Mowing |
| CO23/1 | Powder Spring | 0.00 | 2.40 | 2.40 | Mowing |
| CO23/1 | Powder Spring | 0.00 | 2.40 | 2.40 | Mowing |
| CO23/1 | Powder Spring | 0.00 | 2.40 | 2.40 | Patching |
| CO23/10 | Trout Run Road | 7.50 | 9.20 | 1.70 | Ditching |
| CO23/10 | Trout Run | 0.00 | 13.36 | 13.36 | Mowing |
| CO23/10 | Trout Run Road | 0.00 | 13.36 | 13.36 | Mowing |
| CO23/10 | Trout Run Road | 0.00 | 13.36 | 13.36 | Mowing |
| CO23/12 | Trout Run Cut off | 0.00 | 1.69 | 1.69 | Ditching |
| CO23/12 | Trout Run Cut off | 0.00 | 1.69 | 1.69 | Mowing |
| CO23/12 | Trout Run Cut off | 0.00 | 1.69 | 1.69 | Mowing |
| CO23/13 | Moores Run | 0.00 | 1.64 | 1.64 | Ditching |
| CO23/13 | Moores Run | 0.00 | 1.69 | 1.69 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|----------|--------------------------|------|------|--------|---------------|
| CO23/14 | Stacks Gap | 0.00 | 0.54 | 0.54 | Ditching |
| CO23/14 | Stack's Gap | 0.00 | 0.54 | 0.54 | Mowing |
| CO23/14 | Stack's Gap | 0.00 | 0.54 | 0.54 | Mowing |
| CO23/14 | Stacks Gap | 0.00 | 0.54 | 0.54 | Mowing |
| CO23/15 | Dover Hollow | 0.00 | 1.43 | 1.43 | Mowing |
| CO23/15 | Dover Hollow Road | 0.00 | 1.43 | 1.43 | Mowing |
| CO23/2 | Dover FT Run | 3.10 | 4.70 | 1.60 | Ditching |
| CO23/2 | Dover - Ft Run | 0.00 | 5.14 | 5.14 | Mowing |
| CO23/2 | Dover - Ft Run | 0.00 | 2.00 | 2.00 | Mowing |
| CO23/2 | Dover - Ft Run | 0.00 | 5.14 | 5.14 | Mowing |
| CO23/2 | Dover - FT Run | 0.00 | 5.14 | 5.14 | Patching |
| CO23/3 | Upper Skaggs & Lem Parks | 0.00 | 1.98 | 1.98 | Ditching |
| CO23/3 | Upper Skaggs & Lem Parks | 0.00 | 1.98 | 1.98 | Mowing |
| CO23/3 | | 0.00 | 1.34 | 1.34 | Stabilization |
| CO23/4 | Luxemburg | 0.00 | 2.09 | 2.09 | Ditching |
| CO23/4 | Luxemburg | 0.00 | 2.09 | 2.09 | Mowing |
| CO23/4 | Luxemburg | 0.00 | 2.09 | 2.09 | Stabilization |
| CO23/5 | Upper Pine Grove | 0.00 | 1.37 | 1.37 | Ditching |
| CO23/5 | Upper Pine Grove Road | 0.00 | 1.37 | 1.37 | Mowing |
| CO23/5 | Upper Pine Grove Road | 0.00 | 1.37 | 1.37 | Mowing |
| CO23/6 | Lower Pine Grove | 0.00 | 1.16 | 1.16 | Mowing |
| CO23/6 | Lower Pine Grove Road | 0.00 | 1.61 | 1.61 | Mowing |
| CO23/7 | Baughman Settlement | 0.00 | 3.00 | 3.00 | Ditching |
| CO23/7 | Baughman Settlement | 0.00 | 4.08 | 4.08 | Ditching |
| CO23/7 | Baughman settlement | 0.00 | 4.08 | 4.08 | Mowing |
| CO23/7 | Baughman Settlement | 0.00 | 4.08 | 4.08 | Mowing |
| CO23/7 | Baughman Settlement | 0.00 | 4.08 | 4.08 | Stabilization |
| CO23/8 | Pine Ridge Road | 0.00 | 4.00 | 4.00 | Mowing |
| CO23/8 | Pine Ridge Road | 0.00 | 4.23 | 4.23 | Mowing |
| CO23/8 | Pine Ridge | 0.00 | 4.23 | 4.23 | Mowing |
| CO23/8 | Pine Ridge Road | 0.00 | 4.00 | 4.00 | Patching |
| CO23/9 | Sauerkraut | 1.20 | 5.94 | 4.74 | Ditching |
| CO23/9 | Sauerkraut | 0.00 | 7.54 | 7.54 | Mowing |
| CO23/9 | Sauerkraut | 0.00 | 7.54 | 7.54 | Mowing |
| CO23/9 | Sauerkraut | 0.00 | 7.54 | 7.54 | Mowing |
| CO23/9 | Sauerkraut | 2.00 | 6.00 | 4.00 | Stabilization |
| CO259/1 | Grover Smith road | 0.00 | 3.31 | 3.31 | Ditching |
| CO259/1 | Grover Smith Road | 0.00 | 3.31 | 3.31 | Patching |
| CO259/1 | Grover Smith | 0.00 | 3.31 | 3.31 | Mowing |
| CO259/12 | Hunkerson Gap | 0.00 | 0.10 | 0.10 | Mowing |
| CO259/13 | Luther Heishman Road | 0.00 | 1.04 | 1.04 | Ditching |
| CO259/13 | Luter Heishman | 0.00 | 1.94 | 1.94 | Mowing |
| CO259/13 | Luther Heishman | 0.00 | 1.04 | 1.04 | Stabilization |
| CO259/2 | Shoemaker Hollow | 0.00 | 0.02 | 0.02 | Ditching |
| CO259/2 | Shoemaker Hollow | 0.00 | 1.52 | 1.52 | Mowing |
| CO259/2 | Shoemaker Hollow | 0.00 | 1.52 | 1.52 | Patching |

| Route | Local Name | BMP | EMP | Length | Activity |
|---------|----------------------|------|------|--------|---------------|
| CO259/3 | Dispanet Hollow | 0.00 | 3.40 | 3.40 | Mowing |
| CO259/3 | Dispanet Hollow | 0.00 | 3.40 | 3.40 | Mowing |
| CO259/4 | Strawderman Hollow | 0.00 | 0.10 | 0.10 | Ditching |
| CO259/4 | Strawderman Hollow | 0.00 | 3.44 | 3.44 | Mowing |
| CO259/4 | Strawderman Hollow | 0.00 | 3.44 | 3.44 | Mowing |
| CO259/4 | Strawderman Hollow | 0.00 | 3.44 | 3.44 | Patching |
| CO259/4 | Strawderman Hollow | 0.00 | 3.44 | 3.44 | Patching |
| CO259/6 | Mattie Snider | 0.00 | 1.31 | 1.31 | Ditching |
| CO259/6 | Mattie Snider | 0.00 | 1.31 | 1.31 | Mowing |
| CO259/6 | Mattie Snider | 0.00 | 1.31 | 1.31 | Stabilization |
| CO259/7 | Mongold Hollow | 0.00 | 1.67 | 1.67 | Mowing |
| CO259/7 | Mongold Hollow | 0.00 | 1.66 | 1.66 | Patching |
| CO259/7 | Mongold Hollow | 1.10 | 1.66 | 0.56 | Stabilization |
| CO259/8 | Big Ridge | 1.97 | 3.97 | 2.00 | Ditching |
| CO259/8 | Big Ridge | 0.00 | 2.00 | 2.00 | Mowing |
| CO259/8 | Big Ridge | 0.00 | 3.00 | 3.00 | Patching |
| CO259/8 | Big Ridge | 2.00 | 3.97 | 1.97 | Stabilization |
| CO259/9 | Funkhouser Road | 0.00 | 2.02 | 2.02 | Ditching |
| CO259/9 | Funkhouser Road | 0.00 | 2.02 | 2.02 | Mowing |
| CO259/9 | Funkhouser Road | 0.00 | 2.02 | 2.02 | Mowing |
| CO3/1 | Arkansaw | 0.00 | 6.23 | 6.23 | Ditching |
| CO3/1 | Arkansaw Road | 0.00 | 6.23 | 6.23 | Mowing |
| CO3/1 | Arkansaw Road | 0.00 | 6.23 | 6.23 | Mowing |
| CO3/1 | Arkansaw Road | 0.00 | 6.23 | 6.23 | Patching |
| CO3/1 | Arkansaw | 2.22 | 5.23 | 3.01 | Stabilization |
| CO3/1 | Arkansaw Road | 0.00 | 6.23 | 6.23 | Mowing |
| CO3/2 | Grover School | 0.00 | 0.50 | 0.50 | Ditching |
| CO3/2 | Grover School | 0.00 | 1.17 | 1.17 | Mowing |
| CO3/2 | Grover School Road | 0.00 | 1.17 | 1.17 | Mowing |
| CO3/2 | Grover School | 0.00 | 1.17 | 1.17 | Mowing |
| CO3/2 | Grover School | 0.00 | 1.17 | 1.17 | Patching |
| CO3/2 | Ft Run- Dover Hollow | 4.00 | 4.75 | 0.75 | Stabilization |
| CO3/3 | Heishman Road | 0.00 | 0.19 | 0.19 | Mowing |
| CO3/3 | Heishman Road | 0.00 | 0.19 | 0.19 | Mowing |
| CO3/3 | Heishman Road | 0.00 | 0.19 | 0.19 | Mowing |
| CO4/1 | Cunningham Lane "Y" | 0.00 | 0.44 | 0.44 | Ditching |
| CO4/1 | Cunningham Lane "Y" | 0.00 | 0.44 | 0.44 | Mowing |
| CO4/1 | Cunningham Lane "Y" | 0.00 | 0.44 | 0.44 | Mowing |
| CO5 | North Mountain | 0.00 | 3.45 | 3.45 | Mowing |
| CO5 | North Mountain Road | 0.00 | 3.59 | 3.59 | Mowing |
| CO5 | North Mountain | 0.00 | 3.59 | 3.59 | Mowing |
| CO5 | North Mountain Road | 0.00 | 3.45 | 3.45 | Patching |
| CO5/1 | Waites Run | 0.00 | 2.00 | 2.00 | Ditching |
| CO5/1 | Waites Run | 0.00 | 7.50 | 7.50 | Mowing |
| CO5/1 | Waites Run | 0.00 | 7.50 | 7.50 | Mowing |
| CO5/1 | Waites Run | 0.00 | 4.00 | 4.00 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------------|---------------------------------|------------|------------|---------------|-----------------|
| CO5/1 | Waites Run | 0.00 | 7.50 | 7.50 | Mowing |
| CO5/1 | Waites Run | 0.00 | 7.50 | 7.50 | Patching |
| CO5/1 | Waites Run | 4.50 | 7.50 | 3.00 | Stabilization |
| CO5/2 | Warden Circle | 0.00 | 0.82 | 0.82 | Mowing |
| CO5/4 | Old Strasburg | 0.00 | 0.58 | 0.58 | Mowing |
| CO5/4 | Old Strasburg | 0.00 | 0.58 | 0.58 | Mowing |
| CO53 | Old 29 Hampshire Line | 0.00 | 2.67 | 2.67 | Mowing |
| CO55/1 | Old Strasburg Road | 0.00 | 1.51 | 1.51 | Ditching |
| CO55/1 | Old Strasburg | 0.00 | 1.51 | 1.51 | Mowing |
| CO55/1 | Old Strasburg | 0.00 | 1.51 | 1.51 | Stabilization |
| CO55/1 | Old Strasburg Road | 0.00 | 1.51 | 1.51 | Mowing |
| CO55/10 | Dogwood Street | 0.00 | 0.15 | 0.15 | Mowing |
| CO55/11 | Industrial Access | 0.00 | 0.28 | 0.28 | Mowing |
| CO55/11 | Industrial Access | 0.00 | 0.28 | 0.28 | Mowing |
| CO55/11 | Industrial Access | 0.00 | 0.28 | 0.28 | Mowing |
| CO55/12 | East Hardy Middle School | 0.00 | 0.22 | 0.22 | Mowing |
| CO55/16 | Industrial Park | 0.00 | 0.28 | 0.28 | Mowing |
| CO55/16 | Industrial Park | 0.00 | 0.14 | 0.14 | Mowing |
| CO55/17 | Middle School Access | 0.00 | 0.23 | 0.23 | Mowing |
| CO55/17 | Middle School Access | 0.00 | 0.23 | 0.23 | Mowing |
| CO55/19 | Baker Industrial Park Road | 0.00 | 0.39 | 0.39 | Mowing |
| CO55/2 | Old Baker Road | 0.00 | 0.74 | 0.74 | Mowing |
| CO55/2 | Old Baker Road | 0.00 | 0.74 | 0.74 | Mowing |
| CO55/20 | OLD WV 55 | 0.00 | 8.00 | 8.00 | Ditching |
| CO55/20 | Old WV 55 | 0.00 | 24.00 | 24.00 | Ditching |
| CO55/20 | Old WV 55 | 0.00 | 17.28 | 17.28 | Mowing |
| CO55/20 | Old WV 55 Baker to Wardensville | 0.65 | 18.90 | 18.25 | Mowing |
| CO55/20 | Old WV 55 Baker to Criders | 6.40 | 17.26 | 10.86 | Mowing |
| CO55/22 | Eastern Drive | 0.00 | 0.20 | 0.20 | Mowing |
| CO55/22 | Eastern Drive | 0.00 | 0.20 | 0.20 | Mowing |
| CO55/26 | Freedom Way | 0.00 | 0.01 | 0.01 | Mowing |
| CO55/26 | Freedom Way | 0.00 | 0.50 | 0.50 | Mowing |
| CO55/3 | Hinkle Addition | 0.00 | 0.52 | 0.52 | Mowing |
| CO55/3 | Hinkle Addition | 0.00 | 0.52 | 0.52 | Mowing |
| CO55/7 | Caledonia | 0.00 | 1.20 | 1.20 | Mowing |
| CO55/7 | Caledonia | 0.00 | 1.20 | 1.20 | Mowing |
| CO55/7 | Caledonia | 0.00 | 1.20 | 1.20 | Mowing |
| CO55/8 | East Hardy High School | 0.00 | 0.09 | 0.09 | Mowing |
| CO55/9 | Laurel Street | 0.00 | 0.15 | 0.15 | Mowing |
| CO59 | Lower Cove | 5.00 | 7.61 | 2.61 | Ditching |
| CO59 | Lower Cove | 0.00 | 7.60 | 7.60 | Mowing |
| CO59 | Lower Cove Road | 0.00 | 7.61 | 7.61 | Mowing |
| CO59 | Lower Cove | 0.00 | 7.61 | 7.61 | Patching |
| CO59 | Lower Cove | 3.00 | 7.61 | 4.61 | Stabilization |
| CO59/1 | Middle Cove | 0.00 | 4.05 | 4.05 | Ditching |
| CO59/1 | Middle Cove | 0.00 | 4.05 | 4.05 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------|--------------------------|------|-------|--------|---------------|
| CO59/1 | Middle Cove | 0.00 | 4.05 | 4.05 | Mowing |
| CO59/1 | Middle Cove | 0.00 | 4.05 | 4.05 | Patching |
| CO59/2 | Mill Gap- Orkeny Springs | 0.00 | 2.28 | 2.28 | Ditching |
| CO59/2 | Mill Gap - Orkeny Spring | 0.00 | 2.28 | 2.28 | Stabilization |
| CO6 | Trough Road | 0.00 | 8.15 | 8.15 | Ditching |
| CO6 | Trough Road | 0.00 | 8.15 | 8.15 | Mowing |
| CO6 | Trough Road | 0.00 | 8.15 | 8.15 | Mowing |
| CO6 | Trough Road | 0.00 | 5.00 | 5.00 | Patching |
| CO6 | Trough Road | 4.00 | 8.15 | 4.15 | Patching |
| CO7 | South Fork | 6.00 | 7.00 | 1.00 | Ditching |
| CO7 | South Fork | 0.00 | 22.45 | 22.45 | Mowing |
| CO7 | South Fork Road | 0.00 | 22.45 | 22.45 | Mowing |
| CO7/1 | Dumpling Run | 0.00 | 4.26 | 4.26 | Ditching |
| CO7/1 | Dumpling Run | 0.00 | 4.26 | 4.26 | Mowing |
| CO7/1 | Dumpling Run | 0.00 | 4.26 | 4.26 | Stabilization |
| CO7/2 | Peru Gap | 0.00 | 5.60 | 5.60 | Ditching |
| CO7/2 | Peru Gap | 2.50 | 4.20 | 1.70 | Ditching |
| CO7/2 | Peru Gap | 0.00 | 5.60 | 5.60 | Mowing |
| CO7/2 | Peru Hollow | 0.30 | 5.60 | 5.30 | Stabilization |
| CO7/29 | Old Capon Road | 0.00 | 0.62 | 0.62 | Ditching |
| CO7/29 | Old Capon Road | 0.00 | 0.62 | 0.62 | Ditching |
| CO7/29 | Old Capon Road | 0.00 | 0.62 | 0.62 | Mowing |
| CO7/29 | Old Capon Road | 0.00 | 0.62 | 0.62 | Patching |
| CO7/29 | Old Capon Road | 0.00 | 0.62 | 0.62 | Patching |
| CO7/3 | Hinkle Mtn | 0.00 | 2.98 | 2.98 | Ditching |
| CO7/3 | Hinkle Mtn | 0.00 | 2.98 | 2.98 | Ditching |
| CO7/3 | Hinkle Mtn | 0.00 | 2.98 | 2.98 | Mowing |
| CO7/3 | Hinkle Mountain | 0.00 | 2.98 | 2.98 | Stabilization |
| CO7/30 | South Fork Estates III | 0.00 | 1.40 | 1.40 | Mowing |
| CO7/30 | South Fork Estates | 0.00 | 1.40 | 1.40 | Mowing |
| CO7/30 | South Fork Estates III | 0.00 | 1.40 | 1.40 | Patching |
| CO7/6 | Riverbend Lane | 0.00 | 0.67 | 0.67 | Ditching |
| CO7/6 | West Leg "Y" | 0.00 | 0.67 | 0.67 | Mowing |
| CO7/7 | Old Capon Road | 0.00 | 0.51 | 0.51 | Mowing |
| CO7/8 | Wolfe Mountain | 0.00 | 1.29 | 1.29 | Ditching |
| CO7/8 | Wolfe Mountain | 0.00 | 1.29 | 1.29 | Mowing |
| CO7/9 | Cedar Street | 0.00 | 0.11 | 0.11 | Mowing |
| CO8 | Needmore Rock Oak Road | 0.00 | 8.02 | 8.02 | Mowing |
| CO8 | Needmore Rock Oak | 0.00 | 8.00 | 8.00 | Mowing |
| CO8 | Needmore Rock Oak | 3.40 | 0.30 | 3.10 | Ditching |
| CO8 | Needmore Rock Oak Road | 0.00 | 8.02 | 8.02 | Mowing |
| CO8/1 | Paul Bean Road | 0.00 | 0.59 | 0.59 | Ditching |
| CO8/1 | Paul Bean Road | 0.00 | 0.59 | 0.59 | Mowing |
| CO8/1 | Paul Bean Road | 0.00 | 0.59 | 0.59 | Mowing |
| CO8/1 | Paul Bean | 0.00 | 0.59 | 0.59 | Stabilization |
| HA903 | High Lane Road | 0.00 | 0.50 | 0.50 | Ditching |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------------|-------------------------|------------|------------|---------------|-----------------|
| HA903 | High Lane | 0.00 | 0.50 | 0.50 | Mowing |
| HA904 | Lory Bess Lane | 0.00 | 0.72 | 0.72 | Mowing |
| HA904 | Lory Bess Lane | 0.00 | 0.72 | 0.72 | Mowing |
| HA908 | Hillside Drive | 0.00 | 0.44 | 0.44 | Ditching |
| HA908 | Hillside Drive | 0.00 | 0.44 | 0.44 | Mowing |
| HA909 | Rainbow Road | 0.00 | 0.31 | 0.31 | Mowing |
| HA910 | Leisure Acres | 0.00 | 1.03 | 1.03 | Ditching |
| HA910 | Leisure Acres | 0.00 | 1.03 | 1.03 | Mowing |
| HA910 | Leisure Acres | 0.00 | 1.03 | 1.03 | Mowing |
| HA913 | Silver River Acres | 0.00 | 0.14 | 0.14 | Ditching |
| HA913 | Silver River Acres | 0.00 | 0.14 | 0.14 | Mowing |
| HA914 | Sager Hollar Road | 0.00 | 0.29 | 0.29 | Ditching |
| HA915 | Whitetail Drive | 0.00 | 0.18 | 0.18 | Mowing |
| HA916 | Cove Mtn Road | 0.00 | 0.50 | 0.50 | Ditching |
| HA916 | Cove Mountain Road | 0.00 | 0.50 | 0.50 | Mowing |
| HA917 | Oak Drive | 0.00 | 0.14 | 0.14 | Ditching |
| HA917 | Oak Drive | 0.00 | 0.14 | 0.14 | Mowing |
| HA918 | Pine Drive | 0.00 | 0.10 | 0.10 | Mowing |
| HA919 | South Fork Estates Lane | 0.00 | 0.47 | 0.47 | Ditching |
| HA919 | South Fork Estates III | 0.00 | 0.47 | 0.47 | Mowing |
| HA920 | Dead End Drive | 0.00 | 0.12 | 0.12 | Ditching |
| HA920 | Dead End Drive | 0.00 | 0.12 | 0.12 | Mowing |
| HA921 | Shockey Blvd | 0.00 | 12.00 | 12.00 | Mowing |
| HA921 | Shockey Blvd | 0.00 | 0.12 | 0.12 | Ditching |
| HA922 | Backwoods Lane | 0.00 | 0.30 | 0.30 | Ditching |
| HA922 | Backwoods Lane | 0.00 | 0.30 | 0.30 | Mowing |
| HA925 | Shiloh Drive | 0.00 | 0.16 | 0.16 | Ditching |
| HA925 | Shiloh Drive | 0.00 | 0.16 | 0.16 | Mowing |
| HA926 | Riverview Lane | 0.00 | 0.38 | 0.38 | Ditching |
| HA926 | White Oak Lane | 0.00 | 0.38 | 0.38 | Mowing |
| HA927 | Jalapeno Drive | 0.00 | 0.05 | 0.05 | Mowing |
| HA928 | Oak Hill Road | 0.00 | 0.46 | 0.46 | Ditching |
| HA928 | Oak Hill Road | 0.00 | 0.46 | 0.46 | Ditching |
| HA928 | Oak Hill Drive | 0.00 | 0.46 | 0.46 | Mowing |
| HA928 | Oak Hill Road | 0.00 | 0.46 | 0.46 | Mowing |
| HA929 | Mountain Acres Drive | 0.00 | 0.37 | 0.37 | Ditching |
| HA929 | Mountain Acres Drive | 0.00 | 0.37 | 0.37 | Mowing |
| HA930 | Mountain Acres Loop | 0.00 | 0.90 | 0.90 | Ditching |
| HA930 | Mountain Acres Loop | 0.00 | 0.90 | 0.90 | Mowing |
| HA930 | Mountain Acres Loop | 0.00 | 0.90 | 0.90 | Ditching |
| HA932 | Butter Cup Road | 0.00 | 0.36 | 0.36 | Ditching |
| HA932 | Emswiler Drive | 0.00 | 0.36 | 0.36 | Mowing |
| HA933 | Midway Drive | 0.00 | 0.49 | 0.49 | Ditching |
| HA933 | Midway Drive | 0.00 | 0.49 | 0.49 | Mowing |
| HA934 | Hummingbird Hill | 0.00 | 0.46 | 0.46 | Ditching |
| HA934 | Hummingbird Hill | 0.00 | 0.46 | 0.46 | Mowing |

| Route | Local Name | BMP | EMP | Length | Activity |
|-------|--------------------|--------|--------|--------|----------|
| HA935 | Bowman Road | 0.00 | 0.28 | 0.28 | Ditching |
| HA935 | Bowman Road | 0.00 | 0.28 | 0.28 | Mowing |
| HA935 | Bowman Road | 0.00 | 0.28 | 0.28 | Mowing |
| HA936 | Scott's Lane | 0.00 | 0.10 | 0.10 | Ditching |
| HA936 | Scotts Lane | 0.00 | 0.10 | 0.10 | Mowing |
| HA936 | Scotts Lane | 0.00 | 0.10 | 0.10 | Mowing |
| HA937 | Sycamore Hill Road | 0.00 | 0.48 | 0.48 | Ditching |
| HA937 | Sycamore Hill | 0.00 | 0.48 | 0.48 | Mowing |
| HA937 | Sycamore Hill Road | 0.00 | 0.48 | 0.48 | Mowing |
| HA938 | Warden Hollow West | 0.00 | 1.09 | 1.09 | Mowing |
| HA939 | Beagle Drive | 0.00 | 0.41 | 0.41 | Mowing |
| HA940 | Cherokee Drive | 0.00 | 0.16 | 0.16 | Mowing |
| HA948 | Brierwood Lane | 0.00 | 0.19 | 0.19 | Ditching |
| HA948 | Brierwood Lane | 0.00 | 0.19 | 0.19 | Mowing |
| HA949 | John C. Crider | 0.00 | 0.54 | 0.54 | Ditching |
| HA949 | John C. Crider | 0.00 | 0.54 | 0.54 | Mowing |
| HA950 | Cardinal Drive | 0.00 | 0.31 | 0.31 | Mowing |
| HA950 | Cardinal Drive | 0.00 | 0.31 | 0.31 | Mowing |
| HA952 | Turkey Run | 0.00 | 0.71 | 0.71 | Ditching |
| HA952 | Turkey Run | 0.00 | 0.71 | 0.71 | Mowing |
| HA953 | Rabbit Run | 0.00 | 0.30 | 0.30 | Mowing |
| HA954 | Hollow Log Lane | 0.00 | 0.12 | 0.12 | Mowing |
| HA955 | Fox Run Road | 0.00 | 0.19 | 0.19 | Mowing |
| HA956 | Deer Run Road | 0.00 | 0.70 | 0.70 | Mowing |
| HA957 | Cougar Hollow | 0.00 | 0.20 | 0.20 | Mowing |
| HA958 | Hawksnest Drive | 0.00 | 0.35 | 0.35 | Ditching |
| HA958 | Hawksnest Drive | 0.00 | 0.35 | 0.35 | Mowing |
| PF814 | Warden Lake | 0.00 | 4.00 | 4.00 | Mowing |
| PF814 | Warden Lake | 0.00 | 3.75 | 3.75 | Mowing |
| PF814 | Warden Lake | 0.00 | 3.75 | 3.75 | Mowing |
| US220 | US 220 North | 10.70 | 11.70 | 1.00 | Ditching |
| US220 | 220 South | 0.00 | 10.00 | 10.00 | Mowing |
| US220 | US 220 North | 0.00 | 8.79 | 8.79 | Mowing |
| US220 | US 220 South | 0.00 | 10.00 | 10.00 | Mowing |
| US220 | US 220 S | 0.00 | 10.00 | 10.00 | Patching |
| US220 | US 220 N | 0.00 | 18.00 | 18.00 | Patching |
| US220 | US 220 S | 0.00 | 21.00 | 21.00 | Patching |
| US220 | US 220 N | 10.00 | 21.00 | 11.00 | Patching |
| US220 | US 220 South | 0.00 | 10.00 | 10.00 | Ditching |
| US220 | US 220 North | 10.00 | 21.00 | 11.00 | Mowing |
| US48 | Corridor H | 106.36 | 108.00 | 1.64 | Ditching |
| US48 | Corridor H | 108.00 | 110.00 | 2.00 | Ditching |
| US48 | Corridor H | 110.00 | 112.00 | 2.00 | Ditching |
| US48 | Corridor H | 112.00 | 114.00 | 2.00 | Ditching |
| US48 | Corridor H | 114.00 | 116.00 | 2.00 | Ditching |
| US48 | Corridor H | 116.00 | 118.00 | 2.00 | Ditching |

| Route | Local Name | BMP | EMP | Length | Activity |
|-------|----------------------------------|--------|--------|--------|----------|
| US48 | Corridor H | 118.00 | 120.00 | 2.00 | Ditching |
| US48 | Corridor H | 120.00 | 122.00 | 2.00 | Ditching |
| US48 | Corridor H | 122.00 | 124.00 | 2.00 | Ditching |
| US48 | Corridor H | 124.00 | 126.00 | 2.00 | Ditching |
| US48 | Corridor H | 126.00 | 128.00 | 2.00 | Ditching |
| US48 | Corridor H | 128.00 | 130.00 | 2.00 | Ditching |
| US48 | Corridor H | 130.00 | 132.00 | 2.00 | Ditching |
| US48 | Corridor H | 132.00 | 134.00 | 2.00 | Ditching |
| US48 | Corridor H | 134.00 | 135.42 | 1.42 | Ditching |
| US48 | Corridor H | 106.36 | 108.00 | 1.64 | Mowing |
| US48 | Corridor H | 108.00 | 110.00 | 2.00 | Mowing |
| US48 | Corridor H | 110.00 | 112.00 | 2.00 | Mowing |
| US48 | Corridor H | 112.00 | 114.00 | 2.00 | Mowing |
| US48 | Corridor H | 114.00 | 116.00 | 2.00 | Mowing |
| US48 | Corridor H | 116.00 | 118.00 | 2.00 | Mowing |
| US48 | Corridor H | 118.00 | 120.00 | 2.00 | Mowing |
| US48 | Corridor H | 120.00 | 122.00 | 2.00 | Mowing |
| US48 | Corridor H | 122.00 | 124.00 | 2.00 | Mowing |
| US48 | Corridor H | 124.00 | 126.00 | 2.00 | Mowing |
| US48 | Corridor H | 126.00 | 128.00 | 2.00 | Mowing |
| US48 | Corridor H | 128.00 | 130.00 | 2.00 | Mowing |
| US48 | Corridor H | 130.00 | 132.00 | 2.00 | Mowing |
| US48 | Corridor H | 132.00 | 134.00 | 2.00 | Mowing |
| US48 | Corridor H | 134.00 | 135.42 | 1.42 | Mowing |
| US48 | Corridor H | 106.36 | 108.00 | 1.64 | Patching |
| US48 | Corridor H | 108.00 | 110.00 | 2.00 | Patching |
| US48 | Corridor H | 110.00 | 112.00 | 2.00 | Patching |
| US48 | Corridor H | 112.00 | 114.00 | 2.00 | Patching |
| US48 | Corridor H | 114.00 | 116.00 | 2.00 | Patching |
| US48 | Corridor H | 116.00 | 118.00 | 2.00 | Patching |
| US48 | Corridor H | 118.00 | 120.00 | 2.00 | Patching |
| US48 | Corridor H | 120.00 | 122.00 | 2.00 | Patching |
| US48 | Corridor H | 122.00 | 124.00 | 2.00 | Patching |
| US48 | Corridor H | 124.00 | 126.00 | 2.00 | Patching |
| US48 | Corridor H | 126.00 | 128.00 | 2.00 | Patching |
| US48 | Corridor H | 128.00 | 130.00 | 2.00 | Patching |
| US48 | Corridor H | 130.00 | 132.00 | 2.00 | Patching |
| US48 | Corridor H | 132.00 | 134.00 | 2.00 | Patching |
| US48 | Corridor H | 134.00 | 135.42 | 1.42 | Patching |
| WV259 | WV 259 | 0.00 | 35.70 | 35.70 | Ditching |
| WV259 | WV 259 | 14.40 | 20.40 | 6.00 | Ditching |
| WV259 | WV 259 VA Line to Baker | 0.00 | 20.34 | 20.34 | Mowing |
| WV259 | WV 259 Wardensville to Hamp Line | 32.00 | 35.70 | 3.70 | Mowing |
| WV29 | Sperry's Run | 0.00 | 6.66 | 6.66 | Mowing |
| WV29 | Sperry's Run | 0.00 | 0.66 | 0.66 | Patching |
| WV29 | Sperry's Run Road | 0.00 | 6.66 | 6.66 | Ditching |

| Route | Local Name | BMP | EMP | Length | Activity |
|--------------|----------------------|------------|------------|---------------|-----------------|
| WV55 | Corridor H connector | 0.00 | 0.88 | 0.88 | Mowing |
| WV55 | Corridor H Connector | 0.00 | 0.88 | 0.88 | Mowing |

897.24 Mowing
369.86 Ditching
267.95 Patching