

Route	Local Name	BMP	EMP	Length	Activity
CO1	Lockbridge Road	0.00	8.17	8.17	Mowing
CO1	Lockbridge Road	0.00	8.17	8.17	Mowing
CO1	Lockbridge Road	0.00	4.79	4.79	Patching
CO1/2	Cozart Road	0.00	0.66	0.66	Mowing
CO1/5	Harvey Fox Road	0.00	1.50	1.50	Mowing
CO1/6	Dequasie Road	0.00	1.00	1.00	Mowing
CO10	Big Creek Road	0.00	2.57	2.57	Ditching
CO10	Big Creek Road	0.00	3.58	3.58	Mowing
CO10	Big Creek Road	0.00	3.58	3.58	Mowing
CO10	Big Creek Road	0.00	2.00	2.00	Patching
CO10	Big Creek Road	2.00	2.57	0.57	Patching
CO10/1	Left Fork Road	0.00	0.90	0.90	Ditching
CO10/1	Left Fork Road	0.00	0.90	0.90	Mowing
CO10/1	Left Fork Road	0.00	0.90	0.90	Mowing
CO10/1	Left Fork Road	0.00	0.90	0.90	Patching
CO11	Taylors Ridge Road	0.00	5.65	5.65	Ditching
CO11	Taylors Ridge Road	0.00	5.65	5.65	Mowing
CO11	Taylors Ridge Road	0.00	5.65	5.65	Mowing
CO11	Taylors Ridge	0.00	5.65	5.65	Patching
CO11/1	Boone Creek Road	0.00	1.82	1.82	Mowing
CO11/1	F04 BOONE CREEK	0.00	1.13	1.13	Stabilization
CO11/1	F04 BOONE CREEK	1.13	1.82	0.69	Stabilization
CO11/2	Mountain View Road	0.00	2.42	2.42	Mowing
CO11/2	Mountain View Road	0.00	1.76	1.76	Patching
CO11/2	F04 MOUNTAIN VIEW	1.76	2.42	0.66	Stabilization
CO12/1	Broomstraw Ridge Road	0.00	1.62	1.62	Ditching
CO12/1	Broomstraw Ridge Road	0.00	1.64	1.64	Mowing
CO12/1	Broomstraw Ridge Road	0.00	1.64	1.64	Mowing
CO12/1	Broomstraw Ridge Road	0.00	1.64	1.64	Patching
CO12/2	Madams Creek Road	0.00	4.68	4.68	Ditching
CO12/2	Martas Chapel Road	0.00	4.68	4.68	Mowing
CO12/2	Marthas Chaple Road	0.00	4.68	4.68	Patching
CO12/3	Davis Road	0.00	0.28	0.28	Ditching
CO12/3	Davis Road	0.00	0.28	0.28	Mowing
CO12/3	Doyle Road	0.00	0.28	0.28	Mowing
CO12/3	Davis Road	0.00	0.28	0.28	Patching
CO12/4	Bigony Drive	0.00	0.27	0.27	Mowing
CO12/4	Bigony Drive	0.00	0.27	0.27	Mowing
CO12/4	Bigony Drive	0.00	0.27	0.27	Patching
CO12/5	Marie Road	0.00	2.05	2.05	Ditching
CO12/5	Marie-Forest Hill Rd	0.00	2.05	2.05	Mowing
CO12/5	Marie-Forest Hill Road	0.00	2.05	2.05	Patching
CO12/6	Gill Road	0.00	0.30	0.30	Patching
CO12/7	Forest Hill School Rd	0.00	0.30	0.30	Mowing
CO12/7	Forest Hill School Road	0.00	0.24	0.24	Patching
CO13	WillowWood Road	0.00	4.36	4.36	Mowing
CO13	WillowWood Road	0.00	4.36	4.36	Mowing
CO13	Willowwood Road	0.00	4.36	4.36	Patching
CO13/1	Wiggins Crossing	0.00	0.82	0.82	Mowing
CO13/1	Wiggins Crossing	0.00	0.82	0.82	Mowing
CO13/1	Wiggins Crossing	0.00	0.82	0.82	Patching
CO13/2	Bun Hicks Road	0.00	1.10	1.10	Mowing
CO13/2	Bun Hicks Road	0.00	1.10	1.10	Mowing
CO13/2	Bun Hicks Road	0.00	1.10	1.10	Patching
CO13/3	Gun Club Road	0.00	0.70	0.70	Mowing
CO13/3	Gun Club Road	0.00	0.70	0.70	Mowing
CO13/3	Gun Club Road	0.00	0.70	0.70	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO14	Bellepoint Zion Mt. Road	0.00	8.27	8.27	Ditching
CO14	Zion Mt.	0.00	8.27	8.27	Mowing
CO14	Zion Mountain Road	0.00	8.27	8.27	Patching
CO14/1	Hartwell Road	0.00	2.42	2.42	Ditching
CO14/1	Hartwell Rd	0.00	2.42	2.42	Mowing
CO14/1	Hartwell Road	0.00	1.80	1.80	Patching
CO14/2	Low Gap Church Road	0.00	5.26	5.26	Ditching
CO14/2	Low Gap Church Rd	0.00	5.26	5.26	Mowing
CO14/3	Little Wolf Creek Road	0.00	2.60	2.60	Ditching
CO14/3	Little Wolf Creek Rd	0.00	2.60	2.60	Mowing
CO14/4	Canterberry School Rd	0.00	2.63	2.63	Mowing
CO14/4	Canterberry School Rd.	0.30	0.50	0.20	Patching
CO14/6	Bobby Meadows Road	0.00	0.85	0.85	Patching
CO15	Lowell Road	0.00	4.55	4.55	Ditching
CO15	Lowell Road	0.00	4.48	4.48	Mowing
CO15	Lowell Road	0.00	4.48	4.48	Patching
CO15/1	Kellers Creek Road	0.00	5.44	5.44	Ditching
CO15/1	Kellers Creek Road	0.00	2.97	2.97	Mowing
CO15/1	Kellers Creek Road	0.00	2.97	2.97	Mowing
CO15/1	Kellers Creek Rd.	0.00	1.40	1.40	Patching
CO15/1	Kellers Creek Road	0.00	1.28	1.28	Patching
CO15/1	Kellers Creek Road	2.97	5.44	2.47	Patching
CO15/2	Talcott-Lowell Road	0.00	1.49	1.49	Mowing
CO15/2	Talcott-Lowell Road	0.00	1.49	1.49	Mowing
CO15/2	Lowell Rd.	0.00	1.10	1.10	Patching
CO15/2	Talcott-Lowell Road	0.00	1.49	1.49	Patching
CO15/3	Riverview Road	0.00	0.89	0.89	Mowing
CO15/3	Riverview Road	0.00	0.89	0.89	Mowing
CO15/3	Riverview Road	0.00	0.89	0.89	Patching
CO15/3	Riverview Road	0.00	0.89	0.89	Patching
CO15/4	Central Avenue	0.00	0.20	0.20	Mowing
CO15/4	Central Avenue	0.00	0.20	0.20	Mowing
CO15/4	Central Avenue	0.00	0.20	0.20	Patching
CO16	Streeter Road	0.00	10.26	10.26	Ditching
CO16	Streeter Road	0.00	11.27	11.27	Mowing
CO16	Streeter Road	0.00	11.27	11.27	Mowing
CO16	Streeter Road	6.69	9.79	3.10	Patching
CO16	C05 BILL DAN LILLY ROAD (BETWEEN MP 0.00 & 0.88)	0.00	0.85	0.85	Stabilization
CO16	Streeter Road	3.23	6.59	3.36	Stabilization
CO16/1	Boland Road	0.00	5.76	5.76	Mowing
CO16/1	Boland Road	0.00	5.76	5.76	Mowing
CO16/2	Hatchers Bench Road	0.00	3.90	3.90	Mowing
CO16/2	C05 HATCHER BENCH	0.00	3.90	3.90	Stabilization
CO16/3	Hatchers Flat Road	0.00	0.64	0.64	Mowing
CO17	Barger Springs Road	0.00	4.72	4.72	Ditching
CO17	Barger Springs Road	0.00	6.51	6.51	Mowing
CO17	Barger Springs Road	0.00	6.51	6.51	Mowing
CO17	Barger Springs Road	0.00	6.51	6.51	Patching
CO17/1	War Ridge Road	0.00	1.11	1.11	Mowing
CO17/1	War Ridge Road	0.00	1.11	1.11	Mowing
CO17/1	War Ridge Road	0.00	1.11	1.11	Patching
CO17/2	Ben Vass Road	0.00	1.59	1.59	Mowing
CO17/2	Ben Vass Road	0.00	1.59	1.59	Mowing
CO17/2	Ben Vass Road	0.00	1.59	1.59	Patching
CO17/3	Shumate Road	0.00	1.10	1.10	Mowing
CO17/3	HE Shamblen Road	0.00	1.10	1.10	Stabilization
CO17/4	Talcott Back Road	0.00	0.37	0.37	Mowing
CO17/4	Talcott Back Road	0.00	0.37	0.37	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO17/5	Penn Ellison Road	0.00	0.80	0.80	Mowing
CO17/5	Penn Ellison Road	0.00	0.80	0.80	Mowing
CO17/6	Bill Purdue Road	0.00	0.55	0.55	Mowing
CO17/6	Bill Purdue Road	0.00	0.55	0.55	Mowing
CO17/7	Doc Fox Road	0.00	2.40	2.40	Mowing
CO17/7	Doc Fox Road	0.00	2.40	2.40	Mowing
CO17/7	Barger Springs Road	0.00	2.40	2.40	Patching
CO17/8	Pat Ball Road	0.00	0.80	0.80	Mowing
CO17/8	Pat Ball Road	0.00	0.80	0.80	Mowing
CO17/9	Holly Lane Road	0.00	0.36	0.36	Mowing
CO17/9	Holly Lane Rd.	0.00	0.36	0.36	Patching
CO18	Tallory Mountain	0.00	6.94	6.94	Mowing
CO18	Tallory Mountain	0.00	6.94	6.94	Mowing
CO18	Tallory Mountain Road	0.00	6.94	6.94	Patching
CO18/1	Edwards Road	0.00	1.28	1.28	Mowing
CO18/1	Edwards Road	0.00	1.28	1.28	Mowing
CO18/1	Edwards Road	0.00	1.28	1.28	Patching
CO18/2	Albert Hill Road	0.00	1.12	1.12	Mowing
CO18/2	Albert Hill Road	0.00	1.12	1.12	Mowing
CO18/2	Albert Hill Road	0.00	1.12	1.12	Patching
CO19	Ballengee-Wayside Road	0.00	1.56	1.56	Mowing
CO19	Ballengee-Wayside Road	0.00	1.56	1.56	Mowing
CO19	Ballengee-Wayside Road	0.00	1.56	1.56	Patching
CO19/1	Ballengee Road	0.00	2.84	2.84	Mowing
CO19/1	Ballengee Road	0.00	2.84	2.84	Mowing
CO19/1	Ballengee Road	0.00	2.84	2.84	Patching
CO19/2	Lawrence Ridge Road	0.00	0.99	0.99	Mowing
CO19/3	Stoney Creek Road	0.00	0.63	0.63	Mowing
CO19/3	Stoney Creek Road	0.00	0.63	0.63	Mowing
CO19/3	Stoney Creek Road	0.00	0.63	0.63	Patching
CO19/4	Plantation Road	0.00	0.30	0.30	Mowing
CO19/4	Plantation Road	0.00	0.30	0.30	Mowing
CO19/4	Plantation Road	0.00	0.30	0.30	Patching
CO2	Irish Mountain	0.00	2.18	2.18	Mowing
CO20/04	Vocational School Road	0.00	0.05	0.05	Mowing
CO20/05	Fox Addition Road	0.00	0.42	0.42	Mowing
CO20/06	Fox Addition Road	0.00	0.09	0.09	Mowing
CO20/1	Webbs Gate Road	0.00	1.29	1.29	Ditching
CO20/1	Webbs Gate Road	0.00	1.29	1.29	Mowing
CO20/1	Webbs Gate Road	0.00	1.29	1.29	Mowing
CO20/1	Webbs Gate Road	0.00	1.29	1.29	Patching
CO20/2	Bluestone Park Road	0.00	2.54	2.54	Mowing
CO20/2	Bluestone Park Road	0.00	2.54	2.54	Mowing
CO20/2	Bluestone Park Road	0.00	2.54	2.54	Patching
CO20/3	Tom Honaker Road	0.00	0.75	0.75	Ditching
CO20/3	D06 TOM HONAKER ROAD	0.20	0.75	0.55	Stabilization
CO21/1	Luther Hamm Rd	0.00	1.38	1.38	Mowing
CO21/1	Luther Ham Road	0.00	1.38	1.38	Patching
CO21/2	Indian Mills Road	0.00	1.97	1.97	Ditching
CO21/2	Indian Mills Rd	0.00	1.97	1.97	Mowing
CO21/2	Indian Mills Road	0.00	1.97	1.97	Patching
CO21/3	Cut Off Rd (Forest Hill)	0.00	0.74	0.74	Mowing
CO22	Ellison Road	0.00	3.18	3.18	Ditching
CO22	Ellison Ridge Road	0.04	0.08	0.04	Patching
CO23	Mouth of Indian Creek	0.00	1.86	1.86	Mowing
CO23	Shanklins Ferry Road	0.00	3.18	3.18	Patching
CO23/2	Barton Ridge	0.00	4.50	4.50	Mowing
CO23/4	Cedar Branch Rd	0.00	1.81	1.81	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO23/4	Cedar Branch Road	0.00	0.81	0.81	Patching
CO23/5	Manderville-Naponset Rd	0.00	2.00	2.00	Mowing
CO23/5	Manderville Naponset Road	0.00	2.00	2.00	Patching
CO23/6	Shanklins Ferry Rd	0.00	2.42	2.42	Mowing
CO23/7	Manderville Church	0.00	1.43	1.43	Mowing
CO23/7	Shumate Road	0.00	1.43	1.43	Patching
CO24	Patterson Mtn. Road	0.00	1.10	1.10	Mowing
CO24	Patterson Mtn. Road	0.00	1.10	1.10	Mowing
CO24	Patterson Mountain Road	0.00	1.10	1.10	Patching
CO25	Mt. View Road	0.00	10.71	10.71	Ditching
CO25	Mount View Road	0.00	10.71	10.71	Mowing
CO25	Mount View Road	0.00	10.71	10.71	Mowing
CO25	Ellison(Mount View0	0.00	11.85	11.85	Patching
CO25/1	Massy Road	0.00	0.65	0.65	Mowing
CO25/10	Basham Branch Rd	0.00	1.98	1.98	Ditching
CO25/10	Basham Branch Road	0.00	1.98	1.98	Mowing
CO25/2	White Oak Road	0.00	2.60	2.60	Mowing
CO25/2	B04 WHITE OAK ROAD	0.00	2.60	2.60	Stabilization
CO25/3	Streeter - White Oak School Road	0.00	2.43	2.43	Mowing
CO25/3	Streeter - White Oak School Road	0.00	2.43	2.43	Mowing
CO25/3	Streeter White Oak School Rd.	0.00	2.43	2.43	Patching
CO25/4	Joe Cole Road	0.00	2.81	2.81	Mowing
CO25/5	Johnson Road	0.00	1.51	1.51	Mowing
CO25/5	Johnson Road	0.00	1.51	1.51	Mowing
CO25/5	Johnson Road	0.00	0.57	0.57	Patching
CO25/6	North Fork Road	0.00	2.96	2.96	Mowing
CO25/7	Moye/Lilly Road	0.00	2.31	2.31	Ditching
CO25/7	Moye- Lilly Road	0.00	2.31	2.31	Mowing
CO25/7	Moye- Lilly Road	0.00	2.31	2.31	Mowing
CO25/7	Moye-Lilly Rd.	0.00	1.22	1.22	Patching
CO25/8	Ext. of Moye/Lilly Rd	0.00	0.45	0.45	Ditching
CO25/8	Woodlawn Road	0.00	0.45	0.45	Mowing
CO26	Indian Ridge Road	0.00	2.31	2.31	Ditching
CO26	Indian Ridge Road	0.00	5.41	5.41	Mowing
CO26	Indian Ridge Road	0.00	5.41	5.41	Mowing
CO26	Indian Ridge Road	0.00	5.41	5.41	Patching
CO26/1	Salt Wells Road	0.00	12.67	12.67	Mowing
CO26/2	Lick Creek	0.00	2.54	2.54	Mowing
CO26/2	Butler Scales(Lick Creek)	0.00	2.54	2.54	Mowing
CO26/2	Lick Creek Road	0.00	2.54	2.54	Patching
CO26/3	Butler Scales Road	0.00	0.80	0.80	Ditching
CO26/3	Butler Scales Road	0.00	0.80	0.80	Mowing
CO26/4	Rocky Mount road	0.00	0.60	0.60	Mowing
CO26/4	Hopkins Road9Rocky Mount)	0.00	0.60	0.60	Mowing
CO26/4	Hopkins Road	0.00	0.60	0.60	Patching
CO26/5	Honeysuckle Road	0.00	0.79	0.79	Mowing
CO26/5	Honeysuckle Road	0.00	0.79	0.79	Stabilization
CO26/6	Fred Keaton Road	0.00	0.20	0.20	Mowing
CO26/7	L&L Road	0.00	0.13	0.13	Mowing
CO26/8	Begil Farm Road	0.00	1.20	1.20	Mowing
CO27	Ellison Ridge Road	0.53	6.14	5.61	Ditching
CO27	Ellison Ridge Road	0.00	7.48	7.48	Mowing
CO27	Ellison Ridge Road	0.00	7.48	7.48	Mowing
CO27	Ellison Ridge Road	0.00	6.01	6.01	Patching
CO27/1	Suck Creek Road	0.00	4.08	4.08	Ditching
CO27/1	Suck Road Road	0.00	4.08	4.08	Mowing
CO27/1	B06 SUCK CREEK	0.00	4.08	4.08	Stabilization
CO27/2	Hatcher Road	0.00	3.22	3.22	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO27/2	Hatcher Road	0.00	3.22	3.22	Mowing
CO27/3	Little Bluestone Road	0.00	1.43	1.43	Mowing
CO27/4	Cecil Pack Road	0.00	0.20	0.20	Mowing
CO27/4	Cecil Pack Road	0.00	0.20	0.20	Mowing
CO27/5	Lilly Lane	0.00	0.41	0.41	Mowing
CO27/6	Sand Spring Road	0.00	0.26	0.26	Mowing
CO27/6	Sand Spring Road	0.00	0.26	0.26	Mowing
CO28	Lick Creek(Tophet Road)	0.00	1.62	1.62	Mowing
CO28	Lick Creek(Tophet Road)	0.00	1.62	1.62	Mowing
CO28	Hilltop Road	0.00	1.62	1.62	Patching
CO28/2	Dry Fork Run Road	0.00	3.56	3.56	Mowing
CO28/2	D07 DRY FORK RUN	0.80	2.70	1.90	Stabilization
CO28/2	D07 DRY FORK RUN	2.70	3.54	0.84	Stabilization
CO28/3	Island Creel Road	0.00	1.71	1.71	Mowing
CO28/5	Loverin Road	0.00	0.11	0.11	Mowing
CO29	4-H Camp Road	0.00	2.14	2.14	Ditching
CO29	4-H Camp Road	0.00	2.14	2.14	Mowing
CO29	4-H Camp Road	0.00	2.14	2.14	Mowing
CO29	4-H Camp Road	0.00	2.14	2.14	Patching
CO3/1	Will Dodd Road	0.00	2.00	2.00	Ditching
CO3/1	Will Dodd Road	0.00	5.62	5.62	Mowing
CO3/1	Will Dodd Road	0.00	5.62	5.62	Mowing
CO3/1	Will Dodd Road	0.00	0.34	0.34	Patching
CO3/1	Will Dodd Road	4.55	5.62	1.07	Patching
CO3/10	Eagle Branch Road	0.00	2.25	2.25	Mowing
CO3/10	Eagle Branch Road	0.00	2.25	2.25	Mowing
CO3/11	Big Branch Road	0.00	3.65	3.65	Mowing
CO3/11	Big Branch Road	0.00	3.65	3.65	Mowing
CO3/11	Big Branch Road	0.00	2.18	2.18	Patching
CO3/12	Pie Hollow Road	0.00	0.42	0.42	Mowing
CO3/12	Pie Hollow Road	0.00	0.42	0.42	Mowing
CO3/12	Pie Hollow Road	0.00	0.72	0.72	Patching
CO3/14	Bruce Allen Road	0.00	2.20	2.20	Mowing
CO3/14	Bruce Allen Road	0.00	1.00	1.00	Patching
CO3/14	F04 BRUCE ALLEN ROAD	0.00	2.20	2.20	Stabilization
CO3/15	Huston Road	0.00	0.88	0.88	Mowing
CO3/15	Lowell Road	0.00	4.48	4.48	Mowing
CO3/15	Huston Road	0.00	0.88	0.88	Mowing
CO3/15	Huston Road	0.00	0.25	0.25	Patching
CO3/16	Donahoe	0.00	0.41	0.41	Mowing
CO3/16	Donahoe	0.00	0.41	0.41	Mowing
CO3/17	Bennett Cemetary Road	0.00	0.51	0.51	Mowing
CO3/17	Bennett Cemetary Road	0.00	0.51	0.51	Mowing
CO3/17	Bennett Cemetary Road	0.00	0.41	0.41	Patching
CO3/17	C03 BENNETT CEMETERY ROAD	0.00	0.52	0.52	Stabilization
CO3/18	Clayton Road(Fisher Hill)	0.00	0.59	0.59	Mowing
CO3/18	West Clayton Road	0.00	0.59	0.59	Mowing
CO3/18	Clayton Road	0.00	0.59	0.59	Patching
CO3/19	Marvin Deeds Road	0.00	0.82	0.82	Mowing
CO3/19	Marvin Deeds Road	0.00	0.82	0.82	Mowing
CO3/19	Marvin Deeds Road	0.00	0.82	0.82	Patching
CO3/2	Beagal Club Road	0.00	1.00	1.00	Ditching
CO3/2	Beagal Club Road	0.00	3.90	3.90	Mowing
CO3/2	Beagal Club Road	0.00	3.90	3.90	Mowing
CO3/2	Beagal Club Road	0.00	0.70	0.70	Patching
CO3/20	Keeneys Knob Road	0.00	0.78	0.78	Mowing
CO3/20	Keeneys Knob Road	0.00	0.78	0.78	Mowing
CO3/21	Madams Creek Road	0.00	6.41	6.41	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO3/21	Madams Creek Road	0.00	6.41	6.41	Mowing
CO3/21	Broomstraw Ridge Road	0.00	6.41	6.41	Patching
CO3/22	Glen Ray Road	0.00	0.74	0.74	Mowing
CO3/22	Glen Ray Road	0.00	0.74	0.74	Mowing
CO3/22	Glenn Ray Road	0.00	0.74	0.74	Patching
CO3/23	Keeneys Bench	0.00	3.57	3.57	Mowing
CO3/23	Keeneys Bench	0.00	3.57	3.57	Mowing
CO3/3	Albert Mann Road	0.00	1.46	1.46	Ditching
CO3/3	Robins roost Road	0.00	1.46	1.46	Mowing
CO3/3	Robins roost Road	0.00	1.46	1.46	Mowing
CO3/3	Robins Roost Road	0.00	1.46	1.46	Patching
CO3/36	Tom Mack Road	0.00	0.40	0.40	Mowing
CO3/37	Altare Road	0.00	0.15	0.15	Mowing
CO3/37	Altare Road	0.00	0.15	0.15	Mowing
CO3/38	Riverside Rest Road	0.00	0.50	0.50	Mowing
CO3/38	Riverside Rest Road	0.00	0.50	0.50	Mowing
CO3/38	Riverside Rest Road	0.00	0.20	0.20	Patching
CO3/39	Giles Fayette Kanawa Turnpike	0.00	1.06	1.06	Mowing
CO3/4	Sand Knob Road	0.00	3.00	3.00	Ditching
CO3/4	Sand Knobb Road	0.00	3.49	3.49	Mowing
CO3/4	Sand Knobb Road	0.00	3.49	3.49	Mowing
CO3/4	Sand Knob Road	0.00	3.06	3.06	Patching
CO3/40	Eigth Street(Glenn Ray)	0.00	0.15	0.15	Mowing
CO3/40	Eigth Street(Glenn Ray)	0.00	0.15	0.15	Mowing
CO3/40	Eighth Street	0.00	0.15	0.15	Patching
CO3/41	Teddy Wills Road	0.00	0.78	0.78	Mowing
CO3/41	Teddy Wills Road	0.00	0.78	0.78	Patching
CO3/43	Bruce Street(Pine Hill)	0.00	0.58	0.58	Mowing
CO3/43	Lookout Avenue	0.00	0.58	0.58	Mowing
CO3/43	Lookout Avenue	0.00	0.58	0.58	Patching
CO3/44	Kessler Lane	0.00	0.30	0.30	Patching
CO3/45	Jack Lilly Road	0.00	0.75	0.75	Ditching
CO3/45	Jack Lilly Road	0.00	0.75	0.75	Mowing
CO3/45	C05 JACK LILLY ROAD	0.00	0.75	0.75	Stabilization
CO3/46	Graham House Road	0.00	0.43	0.43	Mowing
CO3/46	Graham House Road	0.00	0.43	0.43	Mowing
CO3/46	Grham House Road	0.00	0.43	0.43	Patching
CO3/47	John Talbot Road	0.00	0.34	0.34	Mowing
CO3/47	John Talbot Road	0.00	0.34	0.34	Mowing
CO3/47	John Talbert Road	0.00	0.34	0.34	Patching
CO3/48	Eagle Branch Road(Old Delta 9)	0.00	1.50	1.50	Mowing
CO3/49	JW Whanger Road	0.00	0.33	0.33	Mowing
CO3/49	JW Whanger Road	0.00	0.33	0.33	Mowing
CO3/49	J.W. Whanger Road	0.00	0.33	0.33	Patching
CO3/5	West Woodrumtown Road	0.00	2.25	2.25	Ditching
CO3/5	East Woodrumtown Road	0.00	3.02	3.02	Patching
CO3/50	Wade Harvey Road	0.00	0.50	0.50	Mowing
CO3/51	Bolliing Road	0.00	0.50	0.50	Mowing
CO3/52	Roy Keaton Road	0.00	0.50	0.50	Mowing
CO3/53	Doug Craft Road	0.00	0.35	0.35	Mowing
CO3/53	Doug Craft Road	0.00	0.35	0.35	Mowing
CO3/53	Doug Craft Road	0.00	0.35	0.35	Patching
CO3/54	Donald Avenue	0.00	0.08	0.08	Mowing
CO3/54	Donald Avenue	0.00	0.08	0.08	Mowing
CO3/54	Donald Avenue	0.10	0.18	0.08	Patching
CO3/55	Main Street(Talcott)	0.00	0.12	0.12	Mowing
CO3/55	Penny Lane	0.00	0.12	0.12	Mowing
CO3/56	"MOCK FARM ROAD"	0.00	1.04	1.04	Stabilization

Route	Local Name	BMP	EMP	Length	Activity
CO3/57	Falling Branch Road	0.00	0.45	0.45	Mowing
CO3/58	Colonial Manner Drive	0.00	0.78	0.78	Mowing
CO3/58	Colonial Manner Drive	0.00	0.78	0.78	Mowing
CO3/58	Colonial Manner Drive	0.00	0.78	0.78	Patching
CO3/59	Colonial Manner Lane	0.00	0.40	0.40	Mowing
CO3/59	Colonial Manner Lane	0.00	0.40	0.40	Mowing
CO3/6	East Woodrumtown Rd.	0.00	0.71	0.71	Ditching
CO3/6	East Woodrum Town Road	0.00	0.71	0.71	Stabilization
CO3/60	Sammy Ball Road	0.00	0.43	0.43	Mowing
CO3/61	Autumn Estate Road	0.00	0.56	0.56	Mowing
CO3/61	Autumn Estate Road	0.00	0.56	0.56	Mowing
CO3/63	Oak View Lane	0.00	0.17	0.17	Mowing
CO3/63	Oak View Lane	0.00	0.17	0.17	Mowing
CO3/63	Oak View Lane	0.00	0.17	0.17	Patching
CO3/65	Mock Farm Road	0.00	1.04	1.04	Mowing
CO3/65	Sky View Drive	0.00	0.29	0.29	Mowing
CO3/65	Sky View Drive	0.00	0.29	0.29	Mowing
CO3/7	John-Cook Road	1.47	1.73	0.26	Patching
CO3/8	Camp Lightfoot Road	0.00	3.61	3.61	Ditching
CO3/8	Camp Lightfoot Road	0.00	3.61	3.61	Patching
CO3/9	Valley Heights Road	0.00	1.99	1.99	Mowing
CO3/9	Valley Heights Road	0.00	1.99	1.99	Mowing
CO3/9	Valley Heights Road	0.00	0.87	0.87	Patching
CO3/9	Valley Heights Road	0.87	1.03	0.16	Patching
CO33	Seminole Road	0.00	10.19	10.19	Ditching
CO33	Seminole Rd	0.00	10.19	10.19	Mowing
CO33	Seminole Road (305)	0.00	10.19	10.19	Mowing
CO33/1	Presbyterian Camp Road	0.00	2.43	2.43	Ditching
CO33/1	Presbyterian Camp Rd	0.00	2.43	2.43	Mowing
CO33/1	Seminole Road	0.00	2.43	2.43	Patching
CO33/2	Stinking Lick Road	0.00	2.89	2.89	Patching
CO4	Green Sulphur Springs Road	0.00	4.27	4.27	Mowing
CO4	Green Sulphur Springs Road	0.00	4.27	4.27	Mowing
CO4	Green Sulphur Springs Rd	0.00	3.06	3.06	Patching
CO4/1	E02 BENNETT ROAD	0.00	2.23	2.23	Stabilization
CO4/1	E02 BENNETT ROAD	2.23	2.42	0.19	Stabilization
CO4/2	Red Springs Road	0.00	2.67	2.67	Mowing
CO4/2	F02 RED SPRINGS	0.00	2.67	2.67	Stabilization
CO4/5	Sycamore Lane Road	0.00	1.13	1.13	Mowing
CO4/5	E02 SYCAMORE LANE	0.00	0.53	0.53	Stabilization
CO4/5	E02 SYCAMORE LANE	0.53	0.60	0.07	Stabilization
CO4/5	E02 SYCAMORE LANE	0.60	1.13	0.53	Stabilization
CO44/05	Brooks Mountain Road	0.00	3.95	3.95	Mowing
CO44/1	Coon Creek Road	0.00	0.72	0.72	Mowing
CO44/1	Coon Creek Road	0.00	0.72	0.72	Mowing
CO44/1	Coon Creek Road	0.00	0.57	0.57	Patching
CO44/1	Coon Ck. Rd.	0.26	0.57	0.31	Patching
CO44/10	River Ridge Road	0.00	7.19	7.19	Mowing
CO44/10	River Ridge Road	0.00	7.19	7.19	Mowing
CO44/10	River Ridge Road	0.00	0.12	0.12	Patching
CO44/10	River Rige Rd.	0.12	1.43	1.31	Patching
CO44/10	River Ridge Road	0.12	1.43	1.31	Patching
CO44/11	Shockley Hill	0.00	4.20	4.20	Mowing
CO44/11	Gravelly Point Road(Shockley Hill)	0.00	4.20	4.20	Mowing
CO44/11	Gravelly Point Road	0.00	2.59	2.59	Patching
CO44/12	Broadway Road	0.00	2.73	2.73	Mowing
CO44/12	Gravelly Point Road(Broadway)	0.00	2.73	2.73	Mowing
CO44/12	Broadway Road		2.73	2.73	Patching

Route	Local Name	BMP	EMP	Length	Activity
CO44/13	Knobs Road	0.00	2.27	2.27	Mowing
CO44/13	Knobs Road	0.00	2.27	2.27	Mowing
CO44/13	Knob Ridge Road	0.00	0.75	0.75	Patching
CO44/14	Pipestem Knob Road	0.00	1.84	1.84	Mowing
CO44/14	Pipestem Knob Road	0.00	1.84	1.84	Mowing
CO44/14	Pipestem knob Road	0.00	0.52	0.52	Patching
CO44/14	Pipestem knob Road	0.52	1.84	1.32	Patching
CO44/15	Patterson Creek Road	0.00	0.41	0.41	Mowing
CO44/15	Patterson Creek Road	0.00	0.41	0.41	Patching
CO44/16	Lane School Road	0.00	0.50	0.50	Mowing
CO44/16	Lane School Road	0.00	0.50	0.50	Mowing
CO44/16	Lane School Road	0.00	0.50	0.50	Patching
CO44/17	Mullens Road	0.00	0.15	0.15	Mowing
CO44/17	Mullens Road	0.00	0.15	0.15	Mowing
CO44/19	Lester Neely Road	0.00	1.22	1.22	Mowing
CO44/19	Lester Neely Road	0.00	1.22	1.22	Mowing
CO44/19	Lester Nelly Road	0.00	1.22	1.22	Patching
CO44/20	Surveyor Branch Road	0.00	1.71	1.71	Mowing
CO44/20	Surveyor Branch Road	0.00	1.71	1.71	Mowing
CO44/20	Survveryor Branch	0.00	1.71	1.71	Patching
CO44/21	Patterson Mountain Road	0.00	0.96	0.96	Patching
CO44/23	Brooks Church Road(Left Fork)	0.00	0.40	0.40	Mowing
CO44/23	D03 BROOKS CHURCH ROAD - LEFT FORK	0.00	0.40	0.40	Stabilization
CO44/24	Brooks Church Road(Right Fork)	0.00	0.40	0.40	Mowing
CO44/24	D03 BROOKS CHURCH ROAD - RIGHT FORK	0.00	0.40	0.40	Stabilization
CO44/25	Williams Mountain Road	0.00	2.44	2.44	Stabilization
CO44/26	Fox Cemetary Road	0.00	0.31	0.31	Mowing
CO44/27	Cave Ridge Road	0.00	1.50	1.50	Mowing
CO44/27	Cave Ridge Road	0.00	1.50	1.50	Mowing
CO44/29	Brooks Mountain Road	0.00	0.31	0.31	Mowing
CO44/3	Duncan Branch Road	0.00	6.34	6.34	Mowing
CO44/3	E02 DUNCAN BRANCH	1.83	5.94	4.11	Stabilization
CO44/30	Mill Road	0.00	1.51	1.51	Mowing
CO44/30	"MILL ROAD"/"BROOK'S MT."	0.00	1.51	1.51	Stabilization
CO44/4	Chestnut Mountain Road	0.00	5.70	5.70	Mowing
CO44/4	Chestnut Mountain Road	0.00	5.70	5.70	Mowing
CO44/4	Chestnut Mountain Road	3.76	5.70	1.94	Patching
CO44/5	Brooks Mt. Road	0.00	3.95	3.95	Ditching
CO44/5	D03 BROOKS MOUNTAIN	0.00	2.47	2.47	Stabilization
CO44/5	D03 BROOKS MOUNTAIN	2.47	3.83	1.36	Stabilization
CO44/5	D03 BROOKS MOUNTAIN	3.83	3.95	0.12	Stabilization
CO44/6	Tug Creek Mountain Road.	0.00	6.98	6.98	Mowing
CO44/6	Tug Creek Mountain Road.	0.00	6.98	6.98	Mowing
CO44/6	Tug Creek Mountain Road	0.84	2.19	1.35	Patching
CO44/6	Tug Creek Mountain Road	2.19	6.98	4.79	Patching
CO44/7	Leatherwood Road	0.00	4.73	4.73	Mowing
CO44/7	Leatherwood Road	0.00	4.73	4.73	Mowing
CO44/7	Leatherwood Road	0.90	2.29	1.39	Patching
CO44/8	Frank Brown Road	0.00	1.00	1.00	Mowing
CO44/8	Frank Brown Road	0.00	1.00	1.00	Patching
CO5	Elton Lwan Road	0.00	2.95	2.95	Mowing
CO5	Elton Lwan Road	0.00	2.95	2.95	Mowing
CO5	Elton -Lawn Road	0.00	2.95	2.95	Patching
CO5	Elton-lawn Road	0.00	2.93	2.93	Patching
CO5/1	Williams Mt. Road	0.00	1.19	1.19	Mowing
CO5/2	Fisher Creek Road	0.00	0.08	0.08	Mowing
CO6	Hungars Creek Road	0.00	5.77	5.77	Mowing
CO6	Hungars Creek Road	0.00	5.77	5.77	Mowing



Route	Local Name	BMP	EMP	Length	Activity
CO6	Hungers Creek Road	0.00	5.77	5.77	Patching
CO6/1	Bunn Fink Road	0.00	1.34	1.34	Mowing
CO6/1	Bunn Fink Road	0.00	1.34	1.34	Mowing
CO6/2	Boom Hollow Road	0.00	0.41	0.41	Mowing
CO6/2	F04 BOOM HOLLOW ROAD	0.00	0.41	0.41	Stabilization
CO7	Ramp Road	8.29	22.64	14.35	Ditching
CO7	Clayton Judson Road	0.00	26.25	26.25	Mowing
CO7	Clayton Judson Road	0.00	26.25	26.25	Mowing
CO7	Clayton Rd.	1.70	1.70	-	Patching
CO7/1	Beurytown(Claypool)	0.00	5.76	5.76	Mowing
CO7/10	Spice Lick Road	0.00	1.41	1.41	Ditching
CO7/10	Spice Lick Road	0.00	1.41	1.41	Mowing
CO7/11	George Ballengee Road	0.00	0.70	0.70	Mowing
CO7/11	George Ballengee Road	0.00	0.70	0.70	Mowing
CO7/12	Kierby Mountain Road	0.00	0.41	0.41	Mowing
CO7/12	Kirby Mountain Road	0.00	0.41	0.41	Patching
CO7/13	Tom Blake Road	0.00	1.85	1.85	Ditching
CO7/13	Tom Blake Road	0.00	2.09	2.09	Mowing
CO7/13	F03 TOM BLAKE	0.00	2.09	2.09	Stabilization
CO7/14	Santafee Road	0.00	1.81	1.81	Ditching
CO7/14	Santa Fe Road	0.00	1.81	1.81	Mowing
CO7/14	Santa Fe Road	0.00	1.81	1.81	Mowing
CO7/14	Santa Fe Road	0.00	0.90	0.90	Patching
CO7/14	Griffith Creek Road	0.30	1.81	1.51	Stabilization
CO7/15	Kirby Mt. Road	0.00	2.13	2.13	Ditching
CO7/15	Kirby Mounatain Road	0.00	2.13	2.13	Mowing
CO7/15	Kirby Mt. Rd.	0.00	2.13	2.13	Patching
CO7/16	King Cemetary Road	0.00	1.66	1.66	Mowing
CO7/16	King Cemetary Road	0.46	1.66	1.20	Stabilization
CO7/17	Kenney Knob Fire Tower Road	0.00	5.71	5.71	Mowing
CO7/18	Morgan-Meadows Road	0.00	0.73	0.73	Mowing
CO7/19	Honaker Road(Sandstone)	0.00	0.47	0.47	Mowing
CO7/2	Hump Mountain	0.00	5.94	5.94	Mowing
CO7/2	Hump Mountain	0.00	5.94	5.94	Mowing
CO7/2	Hump Mountain Road	1.70	5.94	4.24	Patching
CO7/2	D02 HUMP MOUNTAIN	0.00	1.70	1.70	Stabilization
CO7/20	Ward Bench Road	0.00	2.00	2.00	Ditching
CO7/20	Ward Bench Road	0.00	2.00	2.00	Mowing
CO7/3	Swell Mt. Road	0.00	3.80	3.80	Ditching
CO7/3	Swell Mt. Road	0.00	3.80	3.80	Mowing
CO7/3	Swell Mt. Road	0.00	0.67	0.67	Patching
CO7/3	Swell Mt. Rd.	0.00	0.96	0.96	Stabilization
CO7/4	Wingfield Mt. Road	0.00	4.21	4.21	Mowing
CO7/5	Sheppard Mt. Road	0.00	2.40	2.40	Ditching
CO7/5	Keeney Mountain Road	0.00	2.40	2.40	Mowing
CO7/5	Keeney Mountain Road	0.00	2.40	2.40	Mowing
CO7/6	Kessler Creek Road	0.00	2.50	2.50	Ditching
CO7/6	Keeney Mountain Road	0.00	1.91	1.91	Mowing
CO7/6	Keeney Mountain Road	0.00	1.91	1.91	Mowing
CO7/6	Keeney Mountain Road	0.00	1.91	1.91	Patching
CO7/7	Sourwood Mt. Rd.	0.00	1.81	1.81	Ditching
CO7/7	Sourwood Mountain Road	0.00	2.11	2.11	Mowing
CO7/8	Keeney Mt. Road	0.00	7.42	7.42	Ditching
CO7/8	Keeney Mountain Road	0.00	7.42	7.42	Mowing
CO7/8	Keeney Mountain Road	0.00	7.42	7.42	Mowing
CO7/9	Plumley Mt. Road	0.00	3.16	3.16	Ditching
CO7/9	Plumley Mountain Road	0.00	3.16	3.16	Mowing
CO8	Powley Creek Road	0.00	5.72	5.72	Mowing

Route	Local Name	BMP	EMP	Length	Activity
CO8	Powley Creek Road	0.00	5.72	5.72	Mowing
CO8	Powley Creek Road	0.00	0.60	0.60	Patching
CO8	Powley Creek Road	0.60	1.90	1.30	Patching
CO9	Elk Knob Road	0.00	7.93	7.93	Ditching
CO9	Elk Knob Road	0.00	7.93	7.93	Mowing
CO9	Elk Knob Road	0.00	7.93	7.93	Patching
CO9/2	Esquire Cemetary Road	0.00	1.27	1.27	Mowing
CO9/2	Esquire Cemetary Road	0.81	1.27	0.46	Patching
CO9/3	Tug Creek Connection Rd.	0.00	1.02	1.02	Ditching
CO9/3	Tug Creek Connection Road	0.00	1.02	1.02	Mowing
CO9/3	Tug Creek Connection Road	0.00	1.02	1.02	Patching
HA903	Howards Branch	0.00	0.32	0.32	Patching
HA906	Wills Drive	0.00	0.18	0.18	Patching
HA907	Summers Street(Glenn Ray)	0.00	0.23	0.23	Mowing
HA907	Summers Street(Glenn Ray)	0.00	0.23	0.23	Mowing
HA908	Hardesty Drive	0.00	0.12	0.12	Mowing
HA908	Hardesty Drive	0.00	0.12	0.12	Mowing
HA909	Weikle Drive	0.00	0.35	0.35	Mowing
HA909	Weikle Drive	0.00	0.35	0.35	Mowing
HA910	Autumn Street	0.00	0.80	0.80	Mowing
HA910	Autumn Street	0.00	0.80	0.80	Mowing
HA911	Winter Street	0.00	0.80	0.80	Mowing
HA911	Winter Street	0.00	0.80	0.80	Mowing
HA913	Holly Ridge Road	0.00	0.34	0.34	Mowing
HA915	F04 LONNIE MAN ROAD	0.00	0.22	0.22	Stabilization
HA916	Valley View Street	0.00	0.13	0.13	Mowing
HA916	Valley View Street	0.00	0.13	0.13	Mowing
HA918	Monroe Avenue	0.00	0.80	0.80	Mowing
HA918	Monroe Avenue	0.00	0.80	0.80	Mowing
HA919	Cantley Road	0.00	0.23	0.23	Mowing
HA919	F05 CANTLEY ROAD	0.00	0.23	0.23	Stabilization
HA920	Graceland Lane	0.00	0.19	0.19	Mowing
HA920	Graceland Lane	0.00	0.19	0.19	Mowing
HA924	Kirks Road	0.00	0.15	0.15	Mowing
PF801	PIPESTEM ACCESS ROAD	0.00	3.55	3.55	Mowing
PF801	PIPESTEM ACCESS ROAD	0.00	3.55	3.55	Mowing
PF801	PIPESTEM ACCESS ROAD	0.00	3.55	3.55	Patching
PF802	PIPESTEM CAMPING AREA	0.00	0.35	0.35	Mowing
PF802	PIPESTEM CAMPING AREA	0.00	0.35	0.35	Mowing
PF802/00	PIPESTEM CAMPING AREA	0.00	0.35	0.35	Patching
PF803	PIPESTEM VISITORS CENTER	0.00	0.35	0.35	Mowing
PF803	PIPESTEM VISITORS CENTER	0.00	0.35	0.35	Mowing
PF803/00	PIPESTEM VISITORS CENTER	0.00	0.35	0.35	Patching
PF804	PIPESTEM CABINS 1-5 & 9	0.00	0.15	0.15	Mowing
PF804	PIPESTEM CABINS 1-5 & 9	0.00	0.15	0.15	Mowing
PF804/00	PIPESTEM CABINS 1-5 & 9	0.00	0.15	0.15	Patching
PF805	PIPESTEM CABINS 1-5 & 9	0.00	0.16	0.16	Mowing
PF805	PIPESTEM CABINS 1-5 & 9	0.00	0.16	0.16	Mowing
PF805/00	PIPESTEM CABINS 10-13	0.00	0.06	0.06	Patching
PF806	PIPESTEM CABINS 14-19	0.00	0.35	0.35	Mowing
PF806	PIPESTEM CABINS 14-19	0.00	0.35	0.35	Mowing
PF806/00	PIPESTEM CABINS 14-19	0.00	0.35	0.35	Patching
PF807	PIPESTEM CABINS 20-24	0.00	0.11	0.11	Mowing
PF807	PIPESTEM CABINS 20-24	0.00	0.11	0.11	Mowing
PF807/00	PIPESTEM CABINS 20-24	0.00	0.11	0.11	Patching
PF808	PIPESTEM CABINS 6-8	0.00	0.05	0.05	Mowing
PF808	PIPESTEM CABINS 6-8	0.00	0.05	0.05	Mowing
PF808/00	PIPESTEM CABINS 6-8	0.00	0.05	0.05	Patching

Route	Local Name	BMP	EMP	Length	Activity
PF809	PIPESTEM CAMPING AREA LOOP	0.00	0.23	0.23	Mowing
PF809	PIPESTEM CAMPING AREA LOOP	0.00	0.23	0.23	Mowing
PF809/00	PIPESTEM CAMPING AREA LOOP	0.00	0.23	0.23	Patching
PF810	PIPESTEM CAMPING AREA	0.00	0.08	0.08	Mowing
PF810	PIPESTEM CAMPING AREA	0.00	0.08	0.08	Mowing
PF810/00	PIPESTEM CAMPING AREA	0.00	0.08	0.08	Patching
PF811	PIPESTEM ARCHERY CLUB	0.00	0.08	0.08	Mowing
PF811	PIPESTEM ARCHERY CLUB	0.00	0.08	0.08	Mowing
PF811/00	PIPESTEM ARCHERY CLUB	0.00	0.08	0.08	Patching
PF812	PIPESTEM ARCHERY CLUB	0.00	0.16	0.16	Mowing
PF812	PIPESTEM ARCHERY CLUB	0.00	0.16	0.16	Mowing
PF812/00	PIPESTEM PAR 3 GOLF COURSE	0.00	0.16	0.16	Patching
PF813	PIPESTEM CAMPING AREA LOOP	0.00	0.11	0.11	Mowing
PF813	PIPESTEM CAMPING AREA LOOP	0.00	0.11	0.11	Mowing
PF813/00	PIPESTEM CAMPING AREA LOOP	0.00	0.11	0.11	Patching
PF814	Long Branch Lake Road	0.00	0.30	0.30	Mowing
PF814	Long Branch Lake Road	0.00	0.30	0.30	Mowing
PF814/00	PIPESTEM LONG BRANCH LAKE ROAD	0.00	0.30	0.30	Patching
PF824/00	BLUESTONE CABIN ACCESS	0.00	0.92	0.92	Patching
PF824/00	BLUESTONE SERVICE AREA	0.00	0.10	0.10	Patching
PF825/00	BLUESTONE BOAT DOCK #1	0.00	0.16	0.16	Patching
PF826	BLUESTONE SWIMMING POOL	0.00	0.16	0.16	Mowing
PF826	BLUESTONE SWIMMING POOL	0.00	0.16	0.16	Mowing
PF826/00	BLUESTONE SWIMMING POOL	0.00	1.48	1.48	Patching
PF827/00	BLUESTONE CAMPING AREA	0.00	0.51	0.51	Patching
PF828/00	BLUESTONE CAMPING AREA	0.00	0.10	0.10	Patching
PF829/00	BLUESTONE CABINS 6-8	0.00	0.26	0.26	Patching
PF830/00	BLUESTONE CABINS 11-15	0.00	0.18	0.18	Patching
PF831/00	BLUESTONE CABINS 22-24	0.00	0.08	0.08	Patching
PF832/00	BLUESTONE CABINS 9-10	0.00	0.10	0.10	Patching
PF833/00	BLUESTONE CABINS 1-5	0.00	0.26	0.26	Patching
PF834	BLUESTONE BOAT DOCK #2	0.00	0.61	0.61	Mowing
PF834	BLUESTONE BOAT DOCK #2	0.00	0.61	0.61	Mowing
PF834/00	BLUESTONE BOAT DOCK #2	0.00	0.61	0.61	Patching
PF835/00	ASSISTANT PARK SUPER. RESID. ACCESS ROAD (BLUESTONE STATE PARK)			-	Patching
PF845	BLUESTONE CRUMPS BOTTOM	0.00	4.83	4.83	Mowing
PF845	BLUESTONE CRUMPS BOTTOM	0.00	4.83	4.83	Mowing
PF845	"TOMS RUN ROAD"	0.00	0.49	0.49	Stabilization
PF845	"TOMS RUN ROAD"	0.49	4.83	4.34	Stabilization
PF845/00	BLUESTONE CRUMPS BOTTOM	0.00	4.83	4.83	Patching
PF846/00	BLUESTONE CRUMPS BOTTOM	0.00	0.81	0.81	Patching
PF847	BLUESTONE INDIAN CREEK	0.00	3.93	3.93	Mowing
PF847/00	BLUESTONE INDIAN CREEK	0.00	4.29	4.29	Patching
PF848	BLUESTONE INDIAN CREEK	0.00	0.28	0.28	Mowing
PF848	BLUESTONE INDIAN CREEK	0.00	0.28	0.28	Mowing
PF848	BLUESTONE INDIAN CREEK	0.00	0.28	0.28	Mowing
PF848/00	BLUESTONE INDIAN CREEK	0.00	0.28	0.28	Patching
PF849	BLUESTONE GAME PLOT	0.00	0.75	0.75	Mowing
PF849	BLUESTONE GAME PLOT	0.00	0.40	0.40	Mowing
PF849/00	BLUESTONE GAME PLOT	0.00	0.75	0.75	Patching
PF850/00	BLUESTONE GAME PLOT	0.00	0.50	0.50	Patching
PF851	BLUESTONE SHANKLINS FERRY	0.00	3.03	3.03	Mowing
PF851/00	BLUESTONE SHANKLINS FERRY	0.00	3.03	3.03	Patching
PF852/00	BLUESTONE CONFERENCE CENTER	0.00	0.80	0.80	Patching
PF853	Old Mill Campground	0.00	0.50	0.50	Mowing
PF853	Old Mill Campground	0.00	0.50	0.50	Mowing
PF853/00	BLUESTONE - OLD MILL CAMPGROUND	0.00	0.50	0.50	Patching
PF854	Pits Road	0.00	0.50	0.50	Mowing

Route	Local Name	BMP	EMP	Length	Activity
PF854	Pits Road	0.00	0.50	0.50	Mowing
PF854/00	BLUESTONE - PITS ROAD	0.00	0.50	0.50	Patching
WV107	Avis Road	0.00	1.74	1.74	Patching
WV107	Avis Road	0.00	1.08	1.08	Patching
WV12	Forest Hill Road	0.00	9.39	9.39	Ditching
WV12	Forest Hill Road	0.00	9.39	9.39	Mowing
WV12	Forest Hill Road	0.00	9.39	9.39	Patching
WV12	Talcott-Lowell Rd.	14.86	23.83	8.97	Patching
WV122	Greenville Road	0.00	1.68	1.68	Mowing
WV122	Gap-Mills Road	0.00	1.68	1.68	Patching
WV20	Pipestem Road	0.00	6.00	6.00	Ditching
WV20	Pipestem Road	6.00	12.55	6.55	Ditching
WV20	Sandstone Road	13.61	20.00	6.39	Ditching
WV20	Sandstone Road	20.00	27.50	7.50	Ditching
WV20	Sandstone Road	27.50	35.79	8.29	Ditching
WV20	Pipestem-Meadow Bridge	0.00	35.79	35.79	Mowing
WV20	Pipestem Road	9.30	12.55	3.25	Mowing
WV20	Sandstone Mountain Road	0.00	7.00	7.00	Patching
WV20	Pipestem Road	0.00	7.00	7.00	Patching
WV20	Pipestem Rd	0.00	14.35	14.35	Patching
WV20	Sandstone Mountain Road	7.00	14.00	7.00	Patching
WV20	Sandstone Mountain Road	14.00	21.00	7.00	Patching
WV20	Sandstone Mountain Road	21.00	28.00	7.00	Patching
WV20	Sandstone Mountain Road	28.00	35.79	7.79	Patching
WV3	White Oak Beech Run	0.00	8.31	8.31	Ditching
WV3	Talcott-Lowell Road	0.00	29.30	29.30	Mowing
WV3	Hinton Road	11.63	14.48	2.85	Patching

885.41 Mowing  
236.22 Ditching  
348.19 Patching