

**APPROVED LIST****APPROVED REPAIR MATERIALS FOR PORTLAND CEMENT CONCRETE****MEETING REQUIRMENTS OF SECTION 715.4.1 AND 715.4.2 OF THE STANDARD SPECIFICATIONS**

<b>Contact: Michael Perrow</b>	<b>Phone:304-414-6644</b>	<b>Email: Michael.D.Perrow@WV.GOV</b>
--------------------------------	---------------------------	---------------------------------------

EFFECTIVE: 05/04/2022

Section 715.4.1

Note : All products must be evaluated by NTPEP for current WVDOH approval.

<i>BRAND NAME</i>	<i>DATE APPROVED</i>	<i>MANUFACTURER</i>	<i>CLASSIFICATION BY COMPRESSIVE STRENGTH ONLY</i>	<i>APPROVAL NUMBER</i>	<i>Horizontal or Vertical Application</i>
Planitop 18 ES	2/16/2017	MAPEI Corporation MCX2.01.715	R-1, R-2, R-3	1460206A	Horizontal
Planitop 18 ES (Extended) with Pea Gravel	2/16/2017	MAPEI Corporation MCX2.01.715	R-1, R-2, R-3	1460207A	Horizontal
Planitop X	2/16/2017	MAPEI Corporation MCX2.01.715	R-1, R-2, R-3	1460208A	Vertical
Planitop 18 TG	10/1/2019	MAPEI Corporation MCX2.01.715	R-1, R-2, R-3	1901057A	Horizontal
Planitop 18 TG (Extended) with Pea Gravel	10/1/2019	MAPEI Corporation MCX2.01.715	R-1,R-2,R-3	1901366A	Horizontal
Planitop XS	11/18/2019	MAPEI Corporation MCX2.01.715	R-1, R-2	1901665A	Vertical
VersaSpeed 100	6/22/2017	Euclid Chemical Co.  ECC1.01.707	R-1, R-2	1460224A	Horizontal & Vertical
EucoRepair V100	6/14/2021	Euclid Chemical Co.  ECC1.01.707	R-1, R-2	2002707A	Horizontal & Vertical
EucoRepair SCC Fast	6/14/2021	Euclid Chemical Co.  ECC1.01.707	R-1, R-2	2002706A	Horizontal & Vertical
Commercial Grade FastSet Concrete Mix	3/2/2017	QUIKRETE QCX1.01.715	R-1, R-2, R-3	1460213A	Horizontal
Commercial Grade FastSet DOT Mix	3/2/2017	QUIKRETE QCX1.01.715	R-1, R-2, R-3	1460214A	Horizontal
Rapid Road Repair	3/7/2017	QUIKRETE QCX1.01.715	R-1, R-2	1460215A	Horizontal

Commercial Grade Fast Set Repair Mortar	7/13/2020	QUIKRETE QCX1.01.715	R-1, R-2	2002679A	Vertical
QUIKRETE Rapid Road Repair - CA	1/31/2022	QUIKRETE QCX1.01.715	R-1, R-2, R-3	2102250A	Horizontal
QUIKRETE Rapid Road Repair - CA Extended	1/31/2022	QUIKRETE QCX1.01.715	R-1, R-2, R-3	2102249A	Horizontal
QUIKRETE Commercial Grade FastSet DOT Mix Extended	1/31/2022	QUIKRETE QCX1.01.715	R-1, R-2, R-3	2102251A	Horizontal
Duracrete II VOFT	3/10/2017	Kaufman Products, Inc. KPC2.01.715	R-1, R-2	1460218A	Vertical
HiCap FT	3/10/2017	Kaufman Products, Inc. KPC2.01.715	R-1, R-2	1460219A	Vertical
Phoscrete HC	6/14/2018	Phoscrete Corporation PCX1.01.715	R-1, R-2, R-3	1462991A	Horizontal
SikaQuick VOH	6/21/2017	Sika Corporation SCC2.01.707	R-1, R-2	1460221A	Vertical
SikaQuick 1000	6/21/2017	Sika Corporation SCC2.01.707	R-1, R-2	1460222A	Horizontal
Sikacrete 421 CI Rapid	5/5/2021	Sika Corporation SCC2.01.707	R-1, R-2	2002705A	Horizontal
EcoFix	10/18/2017	United States Gypsum Co. (USG) USG1.01.715	R-1, R-2, R-3	1461343A	Horizontal
EcoFix (Extended) with Pea Gravel	10/18/2017	United States Gypsum Co. (USG) USG1.01.715	R-1, R-2	1461344A	Horizontal
EcoFix Xtend	10/18/2017	United States Gypsum Co. (USG) USG1.01.715	R-1, R-2	1461345A	Horizontal
EcoFix AG5000	10/18/2017	United States Gypsum Co. (USG) USG1.01.715	R-1, R-2, R-3	1461346A	Horizontal
EcoFix AG5000 (Extended) with Pea	10/18/2017	United States Gypsum Co. (USG) USG1.01.715	R-1, R-2	1461347A	Horizontal
Fastrac 246	7/5/2017	Western Marterial & Design WMD1.01.715	R-1, R-2, R-3	1461038A	Horizontal
Fastrac 300	4/29/2020	Western Marterial & Design WMD1.01.715	R-1, R-2, R-3	2001929A	Horizontal

<b>Rapid Set DOT Repair Mix</b>	<b>10/16/2019</b>	<b>CTS Cement Manufacturing Corporation CTS1.02.701</b>	<b>R-1, R-2, R-3</b>	<b>1901228A</b>	Horizontal
<b>Rapid Set DOT Repair Mix (Extended) with Pea Gravel</b>	<b>10/16/2019</b>	<b>CTS Cement Manufacturing Corporation CTS1.02.701</b>	<b>R-1, R-2, R-3</b>	<b>1901229A</b>	Horizontal
<b>Rapid Set DOT Concrete Mix</b>	<b>9/13/2021</b>	<b>CTS Cement Manufacturing Corporation CTS1.02.701</b>	<b>R-1, R-2, R-3</b>	<b>2102243A</b>	Horizontal
<b>Rapid Set VO Repair Mix</b>	<b>10/16/2019</b>	<b>CTS Cement Manufacturing Corporation CTS1.02.701</b>	<b>R-1, R-2, R-3</b>	<b>1901231A</b>	Vertical
<b>US SPEC Transpatch Concrete</b>	<b>4/14/2020</b>	<b>US Mix Co. USM1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2001457A</b>	Horizontal
<b>US SPEC SC Concrete</b>	<b>7/19/2021</b>	<b>US Mix Co. USM1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2002709A</b>	Horizontal
<b>US SPEC Quickset</b>	<b>9/9/2021</b>	<b>US Mix Co. USM1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2002727A</b>	Vertical
<b>ProSpec Premium Patch 200</b>	<b>5/21/2020</b>	<b>H.B. Fuller, Construction Products Inc HBF1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2001980A</b>	Horizontal
<b>10-60 Rapid Mortar</b>	<b>9/20/2021</b>	<b>Master Builders Solutions Admixtures US, LLC BAS1.02.715</b>	<b>R-1, R-2, R-3</b>	<b>2102243A</b>	Horizontal
<b>SilproRepair VOH</b>	<b>2/23/2022</b>	<b>SILPRO LLC SIL1.01.601</b>	<b>R-1, R-2</b>	<b>2102252A</b>	Vertical
<b>SilproRapid</b>	<b>2/23/2022</b>	<b>SILPRO LLC SIL1.01.601</b>	<b>R-1, R-2, R-3</b>	<b>2102253A</b>	Horizontal
<b>RepCon 928</b>	<b>5/4/2022</b>	<b>SpecChem, LLC SPC1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2200494</b>	Horizontal
<b>RepCon VO</b>	<b>5/4/2022</b>	<b>SpecChem, LLC SPC1.01.715</b>	<b>R-1, R-2, R-3</b>	<b>2200495</b>	Vertical