

## WVDOH APL - Silicone Joint Sealant

Effective Date: April 27, 2026

Contact: Calvin Ratchford

Phone: 304-414- 6649

Email: Calvin.W.Ratchford@wv.gov

Site Manager (SM) Material Code: 708.004.001      Type I - A

AWP Material Code: 708.004.001.1      Type I - A

<b>Type I - A Low Modulus Non-Slag Silicone</b>				
<b>Manufacturer (Source Code)</b>	<b>Product Location</b>	<b>Product Name</b>	<b>WVDOH Approval Number</b>	<b>Date of Approval</b>
Crafco Inc. (CCX3.03.708)	Chandler, Arizona	Roadsaver Non-Slag Silicone Sealant 34902	1465336A	09/01/2015
Pecora Corporation	Harleysville, Pennsylvania	301 NS	2601397	03/23/2026
Sika Corporation (SCX2.01.708)	Lyndhurst, New Jersey	Sikasil 728 NS	1465338A	07/30/2019

Site Manager (SM) Material Code: 708.004.002      Type II - A

AWP Material Code: 708.004.001.2      Type II - A

<b>Type II - A Very Low Modulus Self Leveling</b>				
<b>Manufacturer (Source Code)</b>	<b>Product Location</b>	<b>Product Name</b>	<b>WVDOH Approval Number</b>	<b>Date of Approval</b>
Crafco Inc. (CCX3.03.708)	Chandler, Arizona	Roadsaver Self-Leveling Silicone Sealant 34903	1465337A	09/01/2015
Pecora Corporation	Harleysville, Pennsylvania	300 SL	2601396	03/23/2026
Sika Corporation (SCX2.01.708)	Lyndhurst, New Jersey	Sikasil 728 SL	1465339A	07/30/2019

The products listed in this APL have met the requirements set forth in WVDOH Standard Specifications Roads and Bridges - Section 708.4 - Silicone Joint Sealant